

To: Rickelle Williams, City Manager

From: Talal Abi-Karam, Interim Director – Public Works

Date: March 5, 2025

Re: Change Order No. #1 for Design-Build RFP 99 Project # P12384

Job Description: NE 25th Ave 24-Inch Force Main Replacement, and NE 38th St 42-Inch Force Main and

NE 19th Ave 24-Inch Force Main Replacement.

Contractor: David Mancini and Sons, Inc.

Amount: Total amount of Change Order # 1 for \$997,595.04 - No additional days.

Funding: 10-496-7999-536-60-6599-P12384

The purpose of this Change Order is:

Change Order is being requested for necessary improvements within the Repump B station located inside the Coral Ridge Country Club. The additional work consists of installing a new 36" diameter above ground bypass system that will replace an existing deteriorated bypass that has non-functioning components. The bypass is a critical infrastructure for the operation of the Repump B station. The bypass provides relief to the station during peak flows and serves as a "booster" to its discharge during normal operating conditions. This Change Order includes the necessary materials, labor, equipment and coordination to perform the work without disruption to the pumping system.

EXISTING CONTRACT ITEMS ARE UTILIZED – TOTAL CREDIT: (\$0.00)



NEW CONTRACT ITEMS ARE UTILIZED - TOTAL ADDITIVE COST: \$997,595.04

Item No.12-P12384 Description: Repump B New Bypass Connection ADD: \$997,595.04

NET AMOUNT OF THIS CHANGE ORDER

\$997,595.04

ADDITIONAL CONTRACT TIME BEING REQUESTED-

(0) CALENDAR DAYS

THE TOTAL AMOUNT OF THIS CHANGE ORDER

\$997,595.04



IN WITNESS OF THE FOREGOING, the Parties have set their hands and seals the day and year first written above.

| CITY |
|--|
| CITY OF FORT LAUDERDALE, a Florida municipa corporation. |
| By:RICKELLE WILLIAMS City Manager |
| Date: |
| ATTEST: |
| By: DAVID R. SOLOMAN City Clerk |
| Approved as to Legal Form and Correctness: D'Wayne M. Spence, Interim City Attorney |

RHONDA MONTOYA HASAN Senior Assistant City Attorney



CONTRACTOR

| Signature Print Name JOSE 1105 Signature NOSE 1105 | DAVID MANCINI & SONS, INC., a Florida profit corporation By: FABIO ANGARITA Vice President |
|--|---|
| Print Name | |
| | ATTEST: |
| 1000 | |
| (CORPORATE SEAL) | |
| ADJ4 10 | Print Name: Wand Wander Of |
| | Title: VCO President |
| STATE OF Horiba: COUNTY OF Droword | |
| | before me by means of physical presence or □ online, 2025, by Fabio Angarita, as Vice President, for David ion. |
| LEYDIS COLOMINA POWER MY COMMISSION # HH 502789 EXPIRES: July 10, 2028 | (Signature of Notary Public - State of Florida) (Print, Type, or Stamp Commissioned Name of Notary Public) |
| | |
| Personally Known OR Produced Identif | ication |
| Type of Identification Produced: | |

REV.10.COL Revision Date: 10/06/2021 Approved by: Alan Dodd

Equal Opportunity Employer

PUBLIC WORKS DEPARTMENT

100 N ANDREWS AVENUE, FORT LAUDERDALE, FLORIDA 33301 TELEPHONE (954) 828-5772, FAX (954) 828-5074 WWW.FORTLAUDERDALE.GOV

Page 4 of 5

Printed On Recycled Paper.





CHANGE ORDER SUMMARY SHEET

ORIGINAL CONTRACT AMOUNT \$38,597,800.00 **COST OF CHANGE ORDERS TO DATE** \$0.00 **COST OF THIS CHANGE ORDER** \$997,595.04 TOTAL: \$39,595,395.04 **ORIGINAL CONTRACT TIME** 660 calendar days (P12384) TIME ADDED TO DATE calendar days TIME ADDED TO THIS CHANGE ORDER calendar days TOTAL: 660 calendar days

SCHEDULE OF CHANGE ORDERS TO DATE

AMOUNT OF
COST OR
DATE DESCRIPTION CREDIT

NONE TO DATE

C.O.#



2601 Wiles Rd Pompano Beach Florida 33073 PH: (954) 977-3556 FAX: (954) 944-2040

CONTRACT: P12384

PROJECT: Coral Ridge Force Main Replacement CONTRACTOR: David Mancini & Sons, Inc. (DMSI)

DATE: 3/4/2025

DESCRIPTION: Additional cost related to Repump B connection with 36-Inch above ground bypass.

SUMMARY OF DIRECT COSTS

| 1 | TOTAL LABOR | \$ 154,887.77 |
|---|--|------------------|
| 2 | TOTAL EQUIPMENT | \$ 83,279.20 |
| 3 | TOTAL MATERIAL | \$ 445,948.55 |
| 4 | TOTAL SUBCONTRACTORS | \$ 178,341.51 |
| | SUBTOTAL | \$ 862,457.03 |
| 5 | CONTRACTOR'S MARKUP 8.00% | \$ 68,996.56 |
| 7 | GENERAL CONDITIONS [Items (3+4+5)/Construction Cost] 5.35% | \$ 46,141.45 |
| 8 | TAXES | \$ 26,806.91 |
| | Total Direct Cost | \$ 977,595.04 |

SUMMARY OF TIME IMPACT (REQUEST FOR ADDITIONAL TIME)

DMSI reserves the right to claim for additional contract time if the critical path is affected after approval.

Submitted by:

Alejandra Suarez 03/19/2025

Alejandra Suarez

Assistant Project Manager

Assistant Project Manager David Mancini and Sons, Inc

City of Fort Lauderdale

Approved by:



LABOR COSTS

| SUMMARY - LABOR COSTS | | |
|-----------------------|-------------|------------------|
| SUPERVISION | | \$ 21,600.00 |
| CREW | | \$ 66,630.00 |
| LABOR BURDEN (75.55%) | | \$ 66,657.77 |
| | TOTAL LABOR | \$ 154,887.77 |

| LABOR BURDEN MULTIPLIER (LBM) | 58.20% |
|--|--------|
| Social Security Contributions & Excise and Payroll | 6.20% |
| Medicate Rate | 1.45% |
| Unemployment | 5.49% |
| Workmens Compensation | 7.16% |
| Health Benefits | 14.20% |
| Retirement Benefits | 23.70% |
| VACATION MULTIPLIER (VM) | 13.00% |
| Sick Leave (1 week out of 52) | |
| Vacation (2 weeks out of 52) | |
| Holiday Pay (1 week out of 52) | |
| Insurance Schedule | 4.35% |
| General Liability Insurance | 4.35% |

| Г | Total Labor Burden Rate | 75.55% |
|---|--------------------------|---------|
| | Total Easter Burden Hate | 75.5570 |

| SUPERVISION | Н | lourly Rate (Salary) | Hourly Overtime Rate | Hours (Salary) | Hours Overtime | Total Cost |
|-------------------|----|----------------------|----------------------|----------------|-----------------------|-----------------|
| Project Manager | ¢ | \$ 60.00 | | 30.00 | | \$ 1,800.00 |
| Superintendent | \$ | \$ 55.00 | | 75.00 | | \$ 4,125.00 |
| Crew Foreman | \$ | \$ 47.50 | | 180.00 | | \$ 8,550.00 |
| Crew Foreman | \$ | \$ 47.50 | | 150.00 | | \$ 7,125.00 |
| TOTAL SUPERVISION | | | | | | \$ 21,600.00 |

| MAINLINE CREW - DMSI | Hourly Rate | Но | urly Overtime Rate | Hours | Hours Overtime | Total Cost |
|----------------------|--------------------|----|--------------------|--------|----------------|-------------------|
| Excavator Operator | \$ 30.00 | \$ | 45.00 | 150.00 | 30.00 | \$ 5,850.00 |
| Loader Operator | \$ 27.00 | \$ | 40.50 | 150.00 | 30.00 | \$ 5,265.00 |
| Pipe Layer | \$ 28.00 | \$ | 42.00 | 150.00 | 30.00 | \$ 5,460.00 |
| Skilled Laborer | \$ 24.00 | \$ | 36.00 | 150.00 | 30.00 | \$ 4,680.00 |
| Skilled Laborer | \$ 24.00 | \$ | 36.00 | 150.00 | 30.00 | \$ 4,680.00 |
| Laborer | \$ 20.00 | \$ | 30.00 | 150.00 | 30.00 | \$ 3,900.00 |
| Laborer | \$ 20.00 | \$ | 30.00 | 150.00 | 30.00 | \$ 3,900.00 |
| TOTAL CREW | | | | | | \$ 33,735.00 |

| ASSEMBLY CREW - DMSI | | Hourly Rate | Hourly Overtime Rate | Hours | Hours Overtime | Total Cost |
|----------------------|----|--------------------|----------------------|--------|----------------|-----------------|
| Excavator Operator | \$ | 30.00 | \$ 45.00 | 120.00 | 30.00 | \$ 4,950.00 |
| Loader Operator | \$ | 27.00 | \$ 40.50 | 120.00 | 30.00 | \$ 4,455.00 |
| Pipe Layer | \$ | 28.00 | \$ 42.00 | 120.00 | 30.00 | \$ 4,620.00 |
| Skilled Laborer | \$ | 24.00 | \$ 36.00 | 120.00 | 30.00 | \$ 3,960.00 |
| Skilled Laborer | \$ | 24.00 | \$ 36.00 | 120.00 | 30.00 | \$ 3,960.00 |
| Laborer | \$ | 20.00 | \$ 30.00 | 120.00 | 30.00 | \$ 3,300.00 |
| Laborer | \$ | 20.00 | \$ 30.00 | 120.00 | 30.00 | \$ 3,300.00 |
| TOTAL CREW | • | | | | | \$ 28,545.00 |

| 30.00 27.00 24.00 | \$ 45.00 \$ 40.50 \$ 36.00 | 30.00 30.00 30.00 | | \$ \$ | |
|-------------------------|----------------------------------|-------------------------|----------------------|----------------------|-------------------|
| | | | | \$ ¢ | 810.00 |
| 24.00 | \$ 36.00 | 30.00 | | ¢ | 720.00 |
| | | | | ڔ | 720.00 |
| 24.00 | \$ 36.00 | 30.00 | | \$ | 720.00 |
| 20.00 | \$ 30.00 | 30.00 | | \$ | 600.00 |
| 20.00 | \$ 30.00 | 30.00 | | \$ | 600.00 |
| | | | | \$ | 4,350.00 |
| | 20.00 | 20.00 \$ 30.00 | 20.00 \$ 30.00 30.00 | 20.00 \$ 30.00 30.00 | 20.00 \$ 30.00 \$ |

EQUIPMENT, MATERIAL & SUBCONTRACTOR COSTS



| EQUIPMENT COSTS - RENTAL RATE BLUE BOOK | | | | | |
|--|----|--------------|---------------|----|------------|
| Skid- Steer | ٧ | Working Rate | Working Hours | • | Total Cost |
| CAT 272D | \$ | 84.69 | 180.00 | \$ | 15,244.20 |
| Loaders | | | | | |
| CAT 938M | \$ | 65.42 | 180.00 | \$ | 11,775.60 |
| Excavators | | | | | |
| CAT 308 | \$ | 68.14 | 150.00 | \$ | 10,221.00 |
| CAT 325 | \$ | 133.24 | 180.00 | \$ | 23,983.20 |
| Trucks | | | | | |
| Pick-Up Truck - Chevy Silverado 2500 - Foreman | \$ | 23.39 | 60.00 | \$ | 1,403.40 |
| Pick-Up Truck - Chevy Silverado 2500 - Foreman | \$ | 23.39 | 60.00 | \$ | 1,403.40 |
| Asphalt Pavers | | | | | |
| CAT AP-600D | \$ | 129.56 | 20.00 | \$ | 2,591.20 |
| Miscellaneous Equipment | | | | | |
| Trash Pump | \$ | 9.83 | 150.00 | \$ | 1,474.50 |
| Steel Plates - 8'x20' (6 On Site \$60 per plate PER DAY) | \$ | 360.00 | 15.00 | \$ | 5,400.00 |
| Air Compressor Sullair 375 | \$ | 59.80 | 150.00 | \$ | 8,970.00 |
| Roller | \$ | 27.09 | 30.00 | \$ | 812.70 |
| TOTAL EQUIPMENT | | | | \$ | 83.279.20 |

| MATERIAL COSTS | | | | | | |
|----------------------------|-----|------|----|------------|----|------------|
| Material Description | QTY | Unit | | Unit Cost | 1 | otal Cost |
| 36" FLGXPE DIP 6' | 1 | EA | \$ | 9,988.24 | \$ | 9,988.24 |
| 36" FLGXPE DIP 4' | 1 | EA | \$ | 7,641.18 | \$ | 7,641.18 |
| 36" FLGXFLG DIP 2' | 2 | EA | \$ | 8,089.41 | \$ | 16,178.82 |
| 36" MEGA FLANGE REST ADPT | 1 | EA | \$ | 3,708.38 | \$ | 3,708.38 |
| 36" FLG 90 BEND | 2 | EA | \$ | 14,002.40 | \$ | 28,004.80 |
| 36" FLG ACC KIT NEOPRENE | 10 | EA | \$ | 1,158.83 | \$ | 11,588.30 |
| 36" FLG PLUG VALVE W/GEAR | 1 | EA | \$ | 49,916.85 | \$ | 49,916.85 |
| 36" FLG CHECK VALVE | 1 | EA | \$ | 48,348.31 | \$ | 48,348.31 |
| 2" BALL CORP | 1 | EA | \$ | 315.00 | \$ | 315.00 |
| 2" X 4" SS NIPPLE | 1 | EA | \$ | 14.00 | \$ | 14.00 |
| 36"X2" DBL STRP SS | 1 | EA | \$ | 720.00 | \$ | 720.00 |
| 2" SEWAGE AIR RELEASE VLV | 1 | EA | \$ | 1,040.00 | \$ | 1,040.00 |
| 42" MJ LONG SLEEVE | 1 | EA | \$ | 8,338.99 | \$ | 8,338.99 |
| 42" MEGALUG DIP W/ACC | 10 | EA | \$ | 2,417.08 | \$ | 24,170.80 |
| 42" MJ 45 BEND | 1 | EA | \$ | 11,719.18 | \$ | 11,719.18 |
| 42" X 36" MJ TEE | 1 | EA | \$ | 19,636.05 | \$ | 19,636.05 |
| 36" MEGALUG DIP W/ACC | 5 | EA | \$ | 1,693.30 | \$ | 8,466.50 |
| 36" MJ 90 BEND | 1 | EA | \$ | 9,596.14 | \$ | 9,596.14 |
| 36" MJ PLUG VALVE | 1 | EA | \$ | 50,939.33 | \$ | 50,939.33 |
| 42" MJ PLUG VALVE | 1 | EA | \$ | 103,264.00 | \$ | 103,264.00 |
| 72" ARV MANHOLE / TOP SLAB | 1 | EA | \$ | 2,648.00 | \$ | 2,648.00 |
| 690-AH-M PL R/C | 1 | EA | \$ | 4,225.00 | \$ | 4,225.00 |
| 36" BLND FLG | 1 | EA | \$ | 15,546.85 | \$ | 15,546.85 |
| 36 SS FLG ACC SET | 1 | EA | \$ | 1,158.83 | \$ | 1,158.83 |
| Asphalt | 65 | TON | \$ | 135.00 | \$ | 8,775.00 |
| SUBTOTAL | | | | | \$ | 445,948.55 |
| SURTAX | | | \$ | 50.00 | \$ | 50.00 |
| TAXES | | | | | \$ | 26,806.91 |
| TOTAL MATERIAL | | | _ | | \$ | 472,755.46 |

| SUBCONTRACTORS COSTS | | | | |
|-------------------------------------|-----|------|-----------------|------------------|
| Description | QTY | Unit | Unit Cost | Total Cost |
| CMA | 1 | LS | \$ 62,400.00 | \$ 62,400.00 |
| A&M Brothers Concrete | 1 | LS | \$ 7,600.00 | \$ 7,600.00 |
| SUPERMIX Flowable Fill 18 CY | 1 | LS | \$ 3,228.40 | \$ 3,228.40 |
| SUPERMIX 4 CY Concrete for Linestop | 1 | LS | \$ 1,053.90 | \$ 1,053.90 |
| Rangeline | 1 | LS | \$ 50,307.00 | \$ 50,307.00 |
| Rangeline (IF NEEDED) | 1 | LS | \$ 50,096.00 | \$ 50,096.00 |
| MWI PUMPS (IF NEEDED) | 1 | LS | \$ 3,656.21 | \$ 3,656.21 |
| TOTAL SUBCONTRACTOR | | | | \$ 178,341.51 |



P12383 & P12384 – CORAL RIDGE FORCE MAIN REPLACEMENT PROJECT

LABOR BURDEN BREAKDOWN

- A. 6.20 % SOCIAL SECURITY RATE
- B. 1.45 % MEDICARE RATE
- C. 5.49 % UNEMPLOYMENT
- D. 7.16 % WORKERS COMP
- E. 4.35 % GENERAL LIAB
- F. 14.20 % HEALTH INS
- G. 23.70 % RETIREMENT
- H. 13.00 % VAC/HOLIDAY

Burden Rate: 75.55%

DMSI offers our employees the following paid-off time:

- (2) Weeks Paid Vacation
- (3) Weeks Holiday paid, including time between Christmas and New Year
- (1) Week for Sick Time

Based on this, a DMSI employee works 46 weeks a year and gets paid for 52. Therefore, the yearly burden for General Liability, Health Insurance, Retirement, and vacation Holiday Time must be INCREASED based on the calculation below to cover the six non-revenue weeks (for DMSI), whereas DMSI compensates the employee.

Items A-C Above are standard rates through the federal government and the State of Florida.

Item D – Is DMSI's Workman's Comp rate for Sewer when this project was bid and the Contract executed.

Item E – Is DMSI's G/L rate (1.89%) plus 2.46% to cover the non-revenue paid weeks (See Below) (\$21.87x40x6=\$5,248.80x1.89%=\$992.02/\$21.87x40x46 or an additional 2.46%)

Item F – Insurance burden is calculated using the average hourly employee rate multiplied by 40/hrs. per week for 46 weeks worked, dividing this by the average cost of yearly insurance premiums for hourly employees. (Average hourly rate \$21.87x 40 hours x 46 weeks/year divided by the average cost of SGL coverage 476.18/mo. x 12)

Item G - (RETIREMENT 11% + Bonus, which is merely part of the employee's yearly compensation package, of 10% plus the average hourly rate $$21.87 \times 40 \times 6$$ weeks non-working = \$5,248.80, we pay 21% of this income as retirement benefit so we need to add \$1,102.25 to 46 weeks of working to cover these costs or an additional 2.7%)



ITEM H - (6weeks/46weeks of working to cover costs of vacation and holiday)

By signing below, I certify that the information provided is true and correct to the best of my knowledge.

Sincerely,

Fabio Angarita
Vice president


David Mancini and Sons, Inc


Note:


Our financial statement is proprietary and confidential, so we do not wish it to be made public. Our records are available for your appropriate staff to review at our Pompano Beach, FL office.


Please advise us 48 hours in advance.


If you have any questions about our financial information, please call our Financial Controller, Kimberley Weldon, at (954) 977-3556.














All prices shown in US Dollars (\$)

February 6, 2024 Rental Rate Blue Book®

Caterpillar 308E2 CR (disc. 2020)

Crawler Mounted Hydraulic Excavators

Size Class: **6.5 - 8.4 mt** Weight:



Configuration for 308E2 CR (disc. 2020)

Horsepower Power Mode 65.0 hp Operating Weight 18519 lbs

Diesel

Blue Book Rates

** FHWA Rate is equal to the monthly ownership cost divided by 176 plus the hourly estimated operating cost.

| | Ownership Costs | | | Estimated Operating Costs | FHWA Rate** | |
|--|-----------------|----------------|--------------|------------------------------|-------------|-------------|
| | Monthly | Weekly | Daily | Hourly | Hourly | Hourly |
| Published Rates | USD \$6,930.00 | USD \$1,940.00 | USD \$485.00 | USD \$73.00 | USD \$28.76 | USD \$68.14 |
| Adjustments | | | | | | |
| Region (100%) | - | - | - | - | | |
| Model Year (2020: 100%) | - | - | - | - 10 | | |
| Adjusted Hourly Ownership Cost (100%) | - | - | - | | | |
| Hourly Operating Cost (100%) | | | | | - | |
| Total: | USD \$6,930.00 | USD \$1,940.00 | USD \$485.00 | USD \$73.00 | USD \$28.76 | USD \$68.14 |

Non-Active Use Rates Hourly Standby Rate USD \$21.66 Idling Rate USD \$46.22

Rate Element Allocation

| Element | Percentage | Value |
|-----------------------------|------------|-------------------|
| Depreciation (ownership) | 30% | USD \$2,079.00/mo |
| Overhaul (ownership) | 45% | USD \$3,118.50/mo |
| CFC (ownership) | 15% | USD \$1,039.50/mo |
| Indirect (ownership) | 10% | USD \$693.00/mo |
| Fuel (operating) @ USD 4.15 | 23.78% | USD \$6.84/hr |

Revised Date: 1st quarter 2024

These are the most accurate rates for the selected Revision Date(s). However, due to more frequent online updates, these rates may not match Rental Rate Blue Book® Print. Visit the Cost Recovery Product Guide on our Help page for more information.




All prices shown in US Dollars (\$)

Rental Rate Blue Book® February 6, 2024

Caterpillar 325

Crawler Mounted Hydraulic Excavators

Size Class: 21.5 - 24.4 mt Weight:



Configuration for 325

Bucket Capacity 1.2 cu yd Horsepower 174 hp
Operating Weight 49604 lbs Power Mode Diesel

Blue Book Rates

** FHWA Rate is equal to the monthly ownership cost divided by 176 plus the hourly estimated operating cost.

| | | Ownership | Costs | | Estimated Operating Costs | FHWA Rate** |
|--|-----------------|----------------|----------------|--------------|------------------------------|--------------|
| | Monthly | Weekly | Daily | Hourly | Hourly | Hourly |
| Published Rates | USD \$14,760.00 | USD \$4,135.00 | USD \$1,035.00 | USD \$155.00 | USD \$49.38 | USD \$133.24 |
| Adjustments | | | | | | |
| Region (100%) | - | - | - | - | | |
| Model Year (2024: 100%) | - | - | - | - 40 | | |
| Adjusted Hourly Ownership Cost (100%) | - | - | - | | | |
| Hourly Operating Cost (100%) | | | | | - | |
| Total: | USD \$14,760.00 | USD \$4,135.00 | USD \$1,035.00 | USD \$155.00 | USD \$49.38 | USD \$133.24 |

Non-Active Use RatesHourlyStandby RateUSD \$46.13Idling RateUSD \$97.70

Rate Element Allocation

| Element | Percentage | Value |
|-----------------------------|------------|-------------------|
| Depreciation (ownership) | 30% | USD \$4,428.00/mo |
| Overhaul (ownership) | 45% | USD \$6,642.00/mo |
| CFC (ownership) | 15% | USD \$2,214.00/mo |
| Indirect (ownership) | 10% | USD \$1,476.00/mo |
| Fuel (operating) @ USD 4.15 | 28.03% | USD \$13.84/hr |

Revised Date: 1st quarter 2024

These are the most accurate rates for the selected Revision Date(s). However, due to more frequent online updates, these rates may not match Rental Rate Blue Book® Print. Visit the Cost Recovery Product Guide on our Help page for more information.



All prices shown in US Dollars (\$)

Rental Rate Blue Book® February 6, 2024

Caterpillar 938M

4-Wd Articulated Wheel Loaders

Size Class: 175 - 199 hp Weight: N/A



Configuration for 938M

Horsepower 168.0 hp Operator Protection ROPS/FOPS

Power Mode Diesel

Blue Book Rates

** FHWA Rate is equal to the monthly ownership cost divided by 176 plus the hourly estimated operating cost.

| Ownership Costs | | | Estimated Operating Costs | FHWA Rate** | | |
|---------------------------------------|----------------|----------------|------------------------------|-------------|-------------|-------------|
| | Monthly | Weekly | Daily | Hourly | Hourly | Hourly |
| Published Rates | USD \$6,410.00 | USD \$1,795.00 | USD \$450.00 | USD \$68.00 | USD \$29.00 | USD \$65.42 |
| Adjustments | | | | | | |
| Region (100%) | - | - | - | - | N.Y | |
| Model Year (2024: 100%) | - | - | - | - | _ | |
| Adjusted Hourly Ownership Cost (100%) | - | - | - | X-O | | |
| Hourly Operating Cost (100%) | | | | | - | |
| Total: | USD \$6,410.00 | USD \$1,795.00 | USD \$450.00 | USD \$68.00 | USD \$29.00 | USD \$65.42 |

Non-Active Use Rates
Standby Rate
USD \$24.77
Idling Rate
USD \$49.38

Rate Element Allocation

| Element | Percentage | Value |
|-----------------------------|------------|-------------------|
| Depreciation (ownership) | 39% | USD \$2,499.90/mo |
| Overhaul (ownership) | 32% | USD \$2,051.20/mo |
| CFC (ownership) | 18% | USD \$1,153.80/mo |
| Indirect (ownership) | 11% | USD \$705.10/mo |
| Fuel (operating) @ USD 4.15 | 44.69% | USD \$12.96/hr |

Revised Date: 1st quarter 2024

These are the most accurate rates for the selected Revision Date(s). However, due to more frequent online updates, these rates may not match Rental Rate Blue Book® Print. Visit the Cost Recovery Product Guide on our Help page for more information.



All prices shown in US Dollars (\$)

Rental Rate Blue Book® February 6, 2024

GMC\CHEVY 2500

On-Highway Light Duty Trucks

Size Class: 300 hp & Over Weight: N/A



Crew

Diesel

Configuration for 2500

 Axle Configuration
 4.0 x 2.0
 Cab Type

 Horsepower
 310.0 hp
 Power Mode

 Ton Rating
 3.0 / 4.0

Blue Book Rates

** FHWA Rate is equal to the monthly ownership cost divided by 176 plus the hourly estimated operating cost.

| | | Ownership (| Costs | | Estimated Operating Costs | FHWA Rate** |
|--|--------------|--------------|-------------|----------------------------------|------------------------------|-------------|
| | Monthly | Weekly | Daily | Hourly | Hourly | Hourly |
| Published Rates | USD \$710.00 | USD \$200.00 | USD \$50.00 | USD \$8.00 | USD \$19.36 | USD \$23.39 |
| Adjustments | | | | | _ | |
| Region (100%) | - | - | - | ₩. . () [×] | | |
| Model Year (2024: 100%) | - | - | - | - | | |
| Adjusted Hourly Ownership Cost (100%) | - | - | - | | | |
| Hourly Operating Cost (100%) | | | | | - | |
| Total: | USD \$710.00 | USD \$200.00 | USD \$50.00 | USD \$8.00 | USD \$19.36 | USD \$23.39 |

Non-Active Use Rates
Standby Rate
USD \$2.66
Idling Rate
USD \$19.45

Rate Element Allocation

| Element | Percentage | Value |
|-----------------------------|------------|-----------------|
| Lienient | reicemage | value |
| Depreciation (ownership) | 35% | USD \$248.50/mo |
| Overhaul (ownership) | 34% | USD \$241.40/mo |
| CFC (ownership) | 13% | USD \$92.30/mo |
| Indirect (ownership) | 18% | USD \$127.80/mo |
| Fuel (operating) @ USD 4.15 | 79.65% | USD \$15.42/hr |

Revised Date: 1st quarter 2024

These are the most accurate rates for the selected Revision Date(s). However, due to more frequent online updates, these rates may not match Rental Rate Blue Book® Print. Visit the Cost Recovery Product Guide on our Help page for more information.



All prices shown in US Dollars (\$)

Rental Rate Blue Book® February 6, 2024

Sullair 375HDPQCA

Portable Rotary Screw Air Compressors

Size Class: 250 - 599 cu ft/min Weight: 4150 lbs



Configuration for 375HDPQCA

Air Delivery Rating 375.0 cu ft/min Horsepower 130.0 Power Mode Diesel

Blue Book Rates

** FHWA Rate is equal to the monthly ownership cost divided by 176 plus the hourly estimated operating cost.

| | Ownership Costs | | | Estimated Operating Costs | FHWA Rate** | |
|---------------------------------------|-----------------|----------------|--------------|------------------------------|-------------|-------------|
| | Monthly | Weekly | Daily | Hourly | Hourly | Hourly |
| Published Rates | USD \$4,235.00 | USD \$1,185.00 | USD \$295.00 | USD \$44.00 | USD \$35.74 | USD \$59.80 |
| Adjustments | | | | | | |
| Region (100%) | - | - | - | | · · | |
| Model Year (2024: 100%) | - | - | - | √ - () ` | | |
| Adjusted Hourly Ownership Cost (100%) | - | - | - | | | |
| Hourly Operating Cost (100%) | | | | | - | |
| Total: | USD \$4,235.00 | USD \$1,185.00 | USD \$295.00 | USD \$44.00 | USD \$35.74 | USD \$59.80 |

Non-Active Use RatesHourlyStandby RateUSD \$7.94Idling RateUSD \$43.46

Rate Element Allocation

| Element | Percentage | Value |
|-----------------------------|------------|-------------------|
| Depreciation (ownership) | 15% | USD \$635.25/mo |
| Overhaul (ownership) | 67% | USD \$2,837.45/mo |
| CFC (ownership) | 10% | USD \$423.50/mo |
| Indirect (ownership) | 8% | USD \$338.80/mo |
| Fuel (operating) @ USD 4.15 | 54.28% | USD \$19.40/hr |

Revised Date: 1st quarter 2024

These are the most accurate rates for the selected Revision Date(s). However, due to more frequent online updates, these rates may not match Rental Rate Blue Book® Print. Visit the Cost Recovery Product Guide on our Help page for more information.



All prices shown in US dollars (\$)

Rental Rate Blue Book® February 26, 2025

Caterpillar AP-600D (disc. 2017)

Wheel Mounted Asphalt Pavers

Size Class: 35,000 lbs & Over Weight: 37251 lbs



Configuration for AP-600D (disc. 2017)

Horsepower 165.0 hp Power Mode Diesel Screed Model AS3251C Wheel Drive 2.0

Blue Book Rates

** FHWA Rate is equal to the monthly ownership cost divided by 176 plus the hourly estimated operating cost.

| | Ownership Costs | | | Estimated Operating Costs | FHWA Rate** | |
|---------------------------------------|-----------------|----------------|--------------|------------------------------|-------------|--------------|
| | Monthly | Weekly | Daily | Hourly | Hourly | Hourly |
| Published Rates | USD \$13,590.00 | USD \$3,805.00 | USD \$950.00 | USD \$145.00 | USD \$52.34 | USD \$129.56 |
| Adjustments | | | | | | |
| Region (100%) | - | - | - | - | | |
| Model Year (2017: 100%) | - | - | - | - 40 | | |
| Adjusted Hourly Ownership Cost (100%) | - | - | - | | | |
| Hourly Operating Cost (100%) | | | | | - | |
| Total: | USD \$13,590.00 | USD \$3,805.00 | USD \$950.00 | USD \$145.00 | USD \$52.34 | USD \$129.56 |

Non-Active Use Rates
Standby Rate
USD \$34.17

Idling Rate USD \$101.17

Rate Element Allocation

| Element | Percentage | Value |
|-----------------------------|------------|-------------------|
| Depreciation (ownership) | 28.26% | USD \$3,840.02/mo |
| Overhaul (ownership) | 55.75% | USD \$7,575.79/mo |
| CFC (ownership) | 9.39% | USD \$1,276.63/mo |
| Indirect (ownership) | 6.6% | USD \$897.56/mo |
| Fuel (operating) @ USD 3.54 | 45.76% | USD \$23.95/hr |

Revised Date: 1st quarter 2025

These are the most accurate rates for the selected Revision Date(s). However, due to more frequent online updates, these rates may not match Rental Rate Blue Book® Print. Visit the Cost Recovery Product Guide on our Help page for more information.



All prices shown in US dollars (\$)

Rental Rate Blue Book® February 25, 2025

Caterpillar CB-24 (disc. 2013)

Tandem Vibratory Compactors

Size Class: 1.5 - 3.4 mt Weight: 5952 lbs



Configuration for CB-24 (disc. 2013)

Drum Width 47.0 in Horsepower 31.8 hp

Power Mode Diesel

Blue Book Rates

** FHWA Rate is equal to the monthly ownership cost divided by 176 plus the hourly estimated operating cost.

| Ownership Costs | | | | | Estimated Operating Costs | FHWA Rate** |
|--|----------------|--------------|--------------|-------------|------------------------------|-------------|
| | Monthly | Weekly | Daily | Hourly | Hourly | Hourly |
| Published Rates | USD \$2,805.00 | USD \$785.00 | USD \$195.00 | USD \$29.00 | USD \$11.15 | USD \$27.09 |
| Adjustments | | | | | | |
| Region (100%) | - | - | - | - \ | ♦ | |
| Model Year (2013: 100%) | - | - | - | - | | |
| Adjusted Hourly Ownership Cost (100%) | - | - | - | ×(C) | | |
| Hourly Operating Cost (100%) | | | | | - | |
| Total: | USD \$2,805.00 | USD \$785.00 | USD \$195.00 | USD \$29.00 | USD \$11.15 | USD \$27.09 |

Non-Active Use Rates Hourly

Standby Rate
USD \$8.29
Idling Rate
USD \$18.59

Rate Element Allocation

| Element | Percentage | Value |
|-----------------------------|------------|-------------------|
| Depreciation (ownership) | 29.28% | USD \$821.19/mo |
| Overhaul (ownership) | 47.97% | USD \$1,345.54/mo |
| CFC (ownership) | 11.56% | USD \$324.26/mo |
| Indirect (ownership) | 11.19% | USD \$314.01/mo |
| Fuel (operating) @ USD 3.54 | 23.77% | USD \$2.65/hr |

Revised Date: 1st quarter 2025

These are the most accurate rates for the selected Revision Date(s). However, due to more frequent online updates, these rates may not match Rental Rate Blue Book® Print. Visit the Cost Recovery Product Guide on our Help page for more information.

All American Precast

1300 NW 4 Street Homestead, FL 33030 US +13054182795 ARV MANHOLE TOP SLAB WITH RIM AND COVER FOR ACCESS TO LINESTOP SADDLE ON DRIVEWAY

ADMIN@ALLAMERICANPRECAST.COM

www.allamericanprecast.com



Estimate

ADDRESS

DAVID MANCINI & SONS INC

2601 Wiles Road

Pompano Beach, FL 33073

SHIP TO

CITY OF FT LAUDERDALE

PROJECT # 12384

NE 38th ST 42-INCH FM MAIN REPLACEMENT

FORT LAUDERDALE FL

ESTIMATE # 12206D1 **DATE** 08/07/2024

P.O. NUMBER FLGOLF-06

SALES REP

JOB NAME

Al

PROJ 12384 NE 38th ST

| QTY | RATE | AMOUNT |
|-----|-----------------------------|---|
| 7 | 6,378.00 | 44,646.00T |
| 1 | 2,500.00 | 2,500.00 |
| 2 | 2,153.00 | 4,306.00T |
| 3 | 2,648.00 | 7,944.00T |
| 12 | 150.00 | 1,800.00 |
| 5 | 4,225.00 | 21,125.00 |
| 1 | 0.00 | 0.00 |
| 1 | 0.00 | 0.00 |
| | 7 1 2 3 12 5 | 7 6,378.00 1 2,500.00 2 2,153.00 3 2,648.00 12 150.00 5 4,225.00 1 0.00 |

1.Proposals are valid for up to 30 calendar days, pricing may be subject to change after 30 days. All American Precast manufacturing, Corp reserves the right to withdraw proposal. Engineering fees if required must be requested.



Date 01/14/25

Customer David Mancini & Sons

2601 Wiles Rd Deerfield Beach, 33073

Coral Ridge Bypass
TBD

 Contact
 Ryan Kaltz

 Phone
 954-826-8639

 Email
 Rkaltz@Dmsi.co

Term 4 week

PO: Pending

| Qty | Item | Day | Week | 4 Week | 4 week |
|-----|-----------------------------|---------|---------|----------|------------|
| 100 | 24" Steel Pipe Per Ft | \$1.67 | \$5.00 | \$15.00 | \$1,500.00 |
| 3 | 24" Flange Elbow 90 | \$27.78 | \$83.33 | \$250.00 | \$750.00 |
| 1 | Misc. Nuts, Bolts, Silicone | \$19.44 | \$58.33 | \$175.00 | \$175.00 |

TOTAL RENTAL \$2,425.00

| Services | Item | Price | Total |
|----------|----------|----------|----------|
| 2 | Delivery | \$250.00 | \$500.00 |
| 2 | Pick up | \$250.00 | \$500.00 |

Services Total \$1,000.00

 Subtotal
 \$3,425.00

 Env. Fee
 \$24.25

 Estimated Tax
 \$206.96

 Estimated Total*
 \$3,656.21

*This is an estimate. Actual site conditions can vary which may effect the final pricing.

Customer Responsibilities:

Point of discharge.

Project

Fueling, unless otherwise noted by contractor.

Power source, materials and labor for electric units.

Heavy equipment for loading , unloading, set up and tear down of equipment $\left(U.O.N\right)$

Discharge Permit and fees.

Monitoring of Dewatering Equipment

Ballast Rock for turbidity control and stability if needed.

Cleaning of sediment tank/s



FEL-POMPANO BEACH WW #125 1950 NW 18TH STREET POMPANO BEACH, FL 33069-1394

Phone: 954-973-8100 Fax: 954-917-3134 Deliver To:

From: Matt Briggle

matt.briggle@ferguson.com

Comments:

22:05:49 OCT 02 2024 Page 1 of 2

FEL-POMPANO BEACH, FL WW #125
Price Quotation

Phone: 954-973-8100 Fax: 954-917-3134

 Bid No:
 B574476
 Cust Phone:
 954-977-3556

 Bid Date:
 10/02/24
 Terms:
 NET 10TH PROX

Quoted By: MB

Customer: DAVID MANCINI & SONS INC Ship To: DAVID MANCINI & SONS INC

2601 WILES ROAD 2601 WILES ROAD

CORAL RIDGE FM REPLACEMENT
POMPANO BEACH, FL 33073

CORAL RIDGE FM REPLACEMENT
POMPANO BEACH, FL 33073

Cust PO#: Job Name: CORAL RIDGE FM REPLACEMEN

| Item | Description | Quantity | Net Price | UM | Total |
|--------------|--------------------------------|----------|------------|----|------------|
| MJLSP4LA42 | 42 MJ C153 P-401 LONG SLV L/A | 1 | 8338.990 | EA | 8338.99 |
| IJ4P4LA42 | 42 MJ C153 P-401 45 BEND L/A | 1 | 11719.180 | EΑ | 11719.18 |
| 118MJ36 | 36 MJ N/LUBE PLUG VLV L/A | 1 | 50939.330 | EΑ | 50939.33 |
| -MJPLUGVLV42 | 42 MJ PLUG VALVE - SEE SPEC | 2 | 103264.000 | EΑ | 206528.00 |
| -MJTLA4236 | 42X36 MJ TEE C153 CL | 1 | 19636.050 | EΑ | 19636.05 |
| 19P4LA36 | 36 MJ C153 P-401 90 BEND L/A | 1 | 9596.140 | EΑ | 9596.14 |
| PP436P | 36X4'0 FLGXPE P-401 BT DI SPL | 2 | 7641.180 | EΑ | 15282.36 |
| PP436K | 36X2'0 FLGXFLG P-401 BT DI SPL | 2 | 8089.410 | EΑ | 16178.82 |
| PP436U | 36X6'0 FLGXPE P-401 BT DI SPL | 1 | 9988.240 | EΑ | 9988.24 |
| 13600 | 36 MEGAFLANGE FLG ADPT | 2 | 3708.380 | EΑ | 7416.76 |
| P436 | 36 DI 125# FLG P-401 90 BEND | 2 | 14002.400 | EΑ | 28004.80 |
| /F36PV | 36 FLG PLUG VLV | 1 | 49916.850 | EΑ | 49916.85 |
| VFCV36 | 36 FLG CHK VLV | 1 | 48348.310 | EΑ | 48348.31 |
| .DE42 | 42 DI MJ WDG RTNR GLAND *ONEL | 10 | 2417.080 | EΑ | 24170.80 |
| DE36 | 36 DI MJ WDG REST GLND *ONELO | 5 | 1693.300 | EΑ | 8466.50 |
| SSFAP36 | 36 SS FLG ACC SET | 10 | 1158.830 | EA | 11588.30 |
| | | | | | |
| | ARV | | | | |
| C2023830IP7 | 36X2 IP DBL STRP SS EPOX SDL | 1 | 720.000 | EΑ | 720.00 |
| 317007NL | LF 2 MIP X FIP BALL CORP | 1 | 315.000 | EΑ | 315.00 |
| K | 2 SEWAGE AIR RELEASE VLV | 1 | 1040.000 | EΑ | 1040.00 |
| 6NKP | 2X4 SS S40 316L WLD NIP | 1 | 14.000 | EA | 14.00 |
| | | N | ot Total: | | ¢529209 43 |

 Net Total:
 \$528208.43

 Tax:
 \$31742.51

 Freight:
 \$0.00

 Total:
 \$559950.94



500 West Cypress Creek Road, Suite 600 Fort Lauderdale, FL 33309

Office: +1 (954) 730-0707



December 12th, 2024

Fabio Angarita David Mancini & Sons, Inc 2601 Wiles Road Pompano Beach, FL 33073

Subject: City of Fort Lauderdale

P12384 Coral Ridge Force Main - Phase 4 RCO #2 - 36-inch Bypass at Repump B

Dear Mr. Angarita,

During the design of the force main in Phase 4 of the City of Fort Lauderdale Force Main Project (P12384), the City of Fort Lauderdale has requested that DMSI replace the existing 36-inch above-ground bypass at Repump B. The work required to install a new bypass necessitates additional design and inspection services from CMA that were not included in the original Design Citeria Package (DCP).

As requested by the City of Fort Lauderdale, CMA will include in our Phase 4 submittal plans a detailed design encompassing all necessary piping, valves, connection points, and pipe supports to meet City standards. This design will also incorporate the above-ground bypass under the same permit. Additionally, CMA will provide restoration design plans for all areas impacted during the construction of the bypass. To support the construction process, CMA will provide an inspector onsite during the installation of the 36-inch above-ground bypass. This request also includes the redesign of the connection location to the existing 42-inch influent line at the Master Repump station as discussed in the field with City staff.

Please note that CMA will not perform any modeling or flow calculations as part of this work. The design plans will incorporate the existing system and be replaced in kind.

This additional scope of work has resulted in unanticipated costs for CMA related to the design and construction inspection of the bypass and new connection locations to the existing force main system. The estimated total cost for these additional services is \$62,400.

Please feel free to contact me if you have any additional questions at +1 (561) 744-8282 or via email at vlocigno@chenmoore.com.

Respectfully submitted,

Vincent Locigno

Chen Moore and Associates Vincent Locigno, PE Project Engineer



Rangeline will provide the following Material:

| Quantity | Description | Unit Price | Total |
|----------|--|------------|------------|
| 1 | Night Work Option for the 42" Double Line stop Service | \$9,545.00 | \$9,545.00 |
| 1 | Night Work Option for the 42" Double Re-Stop Service | \$5,574.00 | \$5,574.00 |

Rangeline Group will perform the following Double Line Stop:

| Quantity | Size | Pipetype | Product | Double Line Stop With Bypass | Total | Line Stop Equipment Overnight charges after 7PM on 5th Day "When Equipment is on the Pipe" |
|----------|------|----------|------------|------------------------------------|-------------|--|
| 1 | 42" | DI | Force Main | \$84,520.00 | \$84,520.00 | \$1,500.00 Per Day, Per Line Stop |

Rangeline Group will perform the following Double Re-Stop:

| Quantity | Size | Pipetype | Product | Double Re- Stop With Bypass | Total | Line Stop Equipment Overnight charges after 7PM on 5th Day "When Equipment is on the Pipe" |
|----------|------|----------|------------|-----------------------------------|-------------|--|
| 1 | 42" | DI | Force Main | \$44,522.00 | \$44,522.00 | \$1,500.00 Per Day, Per Line Stop |

PLEASE NOTE: Rangeline will make every attempt to remove the completion plug and re-insert the line stopper through the existing fitting. If the completion plug cannot be removed, the existing line stop fitting will have to be abandoned and a new line stop fitting and location will be needed in order to shut the system down.

Note: Rangeline cannot guarantee a 100% shutdown due to debris, mineral deposits, solids and/or sediments in the pipe.

Prices are based on the following below:

- Rangeline will provide epoxy coated linestop fittings with stainless steel hardware for the double linestop services, and use existing and serviceable linestop fittings for the double re-stop services.
- If the project is cancelled after NON-AIS(standard) materials are ordered, there will be a restocking fee.
- Rangeline will provide (2) 24" 150# flanged outlets for customer to connect Bypass Piping to the 42" double line stop or double re-stop sets. Customer must provide and install all Bypass Piping and related materials.
- When equipment is placed on the pipeline system, whether the Re-Stop is in the main or not, per day charges will apply.
- Please allow (7 14 days) notice for scheduling after receipt of materials to ensure availability. Projects that require shorter lead times may incur additional charges.
- Contractor must encase each line stop fitting in concrete.
- If the type of pipe changes from what we have quoted above, prices and scheduling may vary. Contractor or Municipality is responsible for verifying the type of pipe and it's O.D.
- Rangeline may require a pre-construction meeting or site visit prior to scheduling any services.
- Normal daytime hours (7:00AM- 7:00 PM EST) Monday through Friday. Technician(s) will have a \$375.00 per hour after hours charge, portal-to-portal. Additional Expenses will be charged at our cost plus 20%.
- Rangeline will allow (3) Mobilizations/De-Mobilizations to the jobsite per double line stop and (2) Mobilizations/De-Mobilizations to the jobsite per double re-stop. Additional trips will be \$750.00 per trip. Mobilization charges are applied when the technician leaves the shop or jobsite to start or after completion of the project.

Rangeline Tapping Services
7256 Westport Place Ste A West Palm Beach, FL 33413



A & M Brothers Concrete Corp.

95 NE 12 Street Homestead Fl, 33030 Phone: (786) 296 5979

a.m.concrete@hotmail.com

CONTRACTOR: DAVID MANCINI & SONS INC

Attn: Alejandra Suarez Email: ASuarez@dmsi.co PHONE: (786)-284-2268 COUNTY: BROWARD

PROJECT NAME: CORAL RIDGE ABOVE GROUND PIPE SUPPORT

PROPOSAL / CONTRACT
PROPOSAL VALID FOR 90 CALENDAR DAYS
CALENDAR DAYS
Date: FEBRUARY 04, 2025

| Item | Description | Unit | Unit price | Quantity | To | otal Amount |
|----------|--|---------|--------------------|------------|-----|--|
| 1 | 5' X 18" ABOVE GROUND PIPE SUPPORT WITH #5 REBAR 12" ON CENTER TOP AND BOTTOM EACH WAY | EACH | \$ 3,800.00 | 2 | \$ | 7,600.00 |
| | Note: Final Invoice base on Field measurements | | TOTAL | | \$ | 7,600.00 |
| PI | RICE INCLUDES LABOR, MATERIALS, EQUIPMENT A | ND 3,00 | 0 REG OR 2,5 | 00 DOT PSI | CON | The second secon |
| Field O | ffice, Inspections, Concrete Cylinder Test are NOT Included | | ance of Traffic NC | | | |
| Fill Mat | terials, Grading and Base Preparation are NOT Included | | out/As Built NOT | | | |
| | ock Base and Subgrade are NOT Included. | | Pump are NOT In | | | |

PAYMENT TO A & M Brothers Concrete Corp. is due within 30 days of receipt of this invoice. Any payment not received timely, shall be subject to interest at the rate of 1.5 % per month. In the event of legal action is required to enforce this invoice, A & M Brothers Concrete shall be entitled to recover its attorneys' fees and costs.

ACCEPTANCE OF PROPOSAL/CONTRACT:

DAVID MANCINI & SONS

Name / Title

Signature

| The above prices, specifications and conditions are s | satisfactory and are hereby accepted. You are authorized to do the work as |
|---|--|
| specified. Payment will be made as outlined above. | |
| | |
| Date | |

CONFIDENTIAL







| Customer Name | David Mancini & Sons - Alejandra Suarez Phone: 954-977-3556 | | '-3556 | | |
|---|---|--|--------------------|--|--|
| Address | 2601 Wiles Road, Pompano Beach, FL 33073 | | Fax: | | |
| Project Name | Coral Ridge FM Replacement - Proj 23-FL.GOLF | Cell: 305-775-5 | Cell: 305-775-5340 | | |
| Address | NE 50th Court & 15th Ave, Ft Lauderdale, 33334 | asuarez@dmsi.o | asuarez@dmsi.co | | |
| Mix Code | Description | U.O.M. | Price | | |
| | * As Requested * | | | | |
| 06-FF-95 | FDOT FLOWABLE FILL EXCAVATABLE 100 PSI | Cubic Yard | \$173.00 | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | 1 | | | |
| | | | | | |
| | | 1 | | | |
| | | 1 | | | |
| | | 1 | | | |
| | | 1 | | | |
| | | | | | |
| | | ┪ ├──── | | | |
| | | ┪ ├────┤ | | | |
| | | ┪ ├────┤ | | | |
| | | | | | |
| | | | | | |
| | OFDWOE CHARGES | ∤ | | | |
| | SERVICE CHARGES | | *05.00 | | |
| 0 | Environmental Load Charge | Load | \$25.00 | | |
| Currently | FUEL SURCHARGE - ADJUSTED WEEKLY 1/16/2025 | Load | \$32.20 | | |
| 6:00am-12:30pm | Saturday Delivery Charge | Cubic Yard | TBD | | |
| 6:00 pm-6:00 am | Plant Opening 4-HR Minimum Monday - Friday | FLAT | TBD | | |
| SHORT257 | Minimum Load Charge - Less than 7 CY | Load | \$250.00 | | |
| | Return Concrete Handling & Disposal Fee | Cubic Yard | \$35.00 | | |
| | Order Cancellation Fee | FLAT | \$1,500.00 | | |
| 1/6/2025 | Effective Date Expiration Date 3/31/2025 | | | | |
| Escalation | TBD 7/1/2025 | | | | |
| • | nust be accepted by written purchase order 30 calendar days from qu | • | · | | |
| Supermix at all times reserves the right to increase the quoted prices without notice that reflect an increase in raw material costs, | | | | | |
| changes in market conditions, or surcharges incurred by Supermix, and to cancel or defer any quote in the event Supermix | | | | | |
| becomes delayed or prevented by shortages or allocations of raw materials. Supermix shall not be liable to Buyer, any of its | | | | | |
| counterparties, or any third parties for damages as a result of any such price change, delay, or cancellation. | | | | | |
| Supermix | Peter Kaczorowski Office: 954.480.9333 Cell: 95 | 54.214.4937 | | | |
| Representative | | pete@supermix.co | <u>m</u> | | |
| Accepted by | · · · · · · · · · · · · · · · · · · · | Date: | | | |

CAM #25-0539 Exhibit 4 Page 29 of 205

CONFIDENTIAL







| Customer Name | David Mancini & Sons | Phone: 954-977-3556 | | |
|--|--|----------------------------|--------------------|--|
| Address | 2601 Wiles Road, Pompano Beach, FL 33073 | Fax: | | |
| Project Name | | Cell: 954-668-7 | Cell: 954-668-7770 | |
| Address | | | | |
| Mix Code | Description | U.O.M. | Price | |
| | * As Submitted - 11/6/2024 * | | | |
| 33905 | 3000 PEAROCK PUMPMIX | Cubic Yard | \$187.00 | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | SERVICE CHARGES | | | |
| | Environmental Load Charge | Load | \$25.00 | |
| Currently | FUEL SURCHARGE - ADJUSTED WEEKLY 11/6/2024 | Load | \$30.90 | |
| 6:00am-12:30pm | Saturday Delivery Charge | Cubic Yard | TBD | |
| 6:00 pm-6:00 am | Plant Opening 4-HR Minimum Monday - Friday | FLAT | TBD | |
| SHORT257 | Minimum Load Charge - Less than 7 CY | Load | \$250.00 | |
| If Needed | Placing Pump Primer & Blowback Grout Mix | Cubic Yard | \$250.00 | |
| | Return Concrete Handling & Disposal Fee | Cubic Yard | \$35.00 | |
| | Order Cancellation Fee | FLAT | \$1,500.00 | |
| 11/6/2024 | Effective Date | Expiration Date | 6/30/2025 | |
| Escalation | NOT TO EXCEED \$10.00 CY 7/1/2025 - 12/30/2025 | | | |
| This quotation m | nust be accepted by written purchase order 30 calendar days from qu | ote date or it will expire | ; however, | |
| Supermix at all time | s reserves the right to increase the quoted prices without notice that | reflect an increase in r | aw material costs, | |
| changes in marke | t conditions, or surcharges incurred by Supermix, and to cancel or d | efer any quote in the ev | ent Supermix | |
| becomes delayed or prevented by shortages or allocations of raw materials. Supermix shall not be liable to Buyer, any of its | | | | |
| counterparties, or any third parties for damages as a result of any such price change, delay, or cancellation. | | | | |
| • | | | | |
| Supermix | | 4.214.4937 | | |
| Representative | Account Manager Fax: 954.480.2893 Email: | pete@supermix.co | <u>om</u> | |
| Accepted by | | Date: | | |

City of Fort Lauderdale

NE 38th Street 42-Inch FM and NE 19th Avenue 24-Inch FM Replacement

Submittal Name: SHOP DRAWINGS - CHECK VALVE



| 1. Date of Submission | 12/6/2024 | |
|--|---|--|
| 2. Project Number | P12384 | |
| 3. Project Name | NE 38th Street 42-Inch FM and NE 19th Avenue 24-Inch FM Replacement | |
| 4. Contractor Identification | 23-FL.GOLF-001 | |
| a. Contractor | David Mancini and Sons, Inc | |
| b. Supplier | | |
| c. Manufacturer | N/A | |
| d. Manufacturer or supplier representative | N/A | |
| 5. Identification of the Product | EXB-12.0-P12384-02-1 | |
| 6. Reference to Contract Drawing | D02 | |
| 7. Reference to Specification Section Number, page and paragraphs. | Technical Specifications 2.03 | |
| 8. Indication of Contractor's approval. | Approved by DMSI | |
| 9. Contractor's Certification Statement. (Refer to paragraph 1.03.F.2) | "By this submittal, I hereby represent that I have determined and verified all field measurements, field construction criteria, materials, dimensions, catalog numbers and similar data and I have checked and coordinated each item with other applicable approved shop drawings and all Contract requirements." | |
| 10. Identification of deviations from the Contract, if any. | | |
| 11. Reference to previous submittal (for resubmittals). | | |





AWWA C508 Swing Check Valves

<u>Index</u>

| Brochure | 1 |
|--|---|
| Design Standards | 3 |
| Pressure vs Temp Ratings | 4 |
| Technical Drawings | |
| 2"-48" Swing Check Valve AWWA C508 | |
| Standard Material of Construction Rubber Seated | 6 |
| Flanged w/ Outside Lever & Weight CVI Dimensions | 7 |
| 36" Check Valve Drawing with Materials | 8 |







2"-48" CVI BONDED SEAT SWING CHECK

BONDED SEAT SWING CHECK VALVE


VSI offers the simplified bonded seat type check valve for pump and lift stations where a standard duty valve is acceptable and external accessories are not required. It still exemplifies VSI's commitment to providing a quality product.

- Body seats are permanently bonded nonreplaceable, reducing possible leakage paths.
- Disc seats are replaceable by way of replacing the entire disc.
- The shaft extends only to one side, reducing seal friction and possible leakage paths.




SIMPLE INTERNALS

VSI Bonded Seat Swing Check Valves are built with simplicity in mind for use in general duty applications. They feature minimal internal hardware and robust coatings for long service life in many less demanding applications.



REPLACEABLE DISC

VSI Swing Check Valves incorporate a replaceable bonded seat, which can be removed without taking the valve out from the line. Simply remove the sealed cover, and change out the entire disc.



CAM #25-0539

Exhibit 4 VSI Waterworks Page 34 of 205 105 Alpha Drive, Alpharetta, GA 30004 T: 770.740.0800 F: 770.740.8777 E: sales@vsiwaterworks.com



DESIGN STANDARDS

| Size Range | 6"-48" Flanged End |
|-----------------|---------------------------|
| Construction | AWWA C508 |
| | ASME B16.34 |
| | API 600 |
| Coatings | AWWA C550* |
| Connections | ANSI B16.1 Class 125* |
| | ANSI B16.1 Class 250 |
| | ANSI B16.5 Class 150 |
| | ANSI B16.5 Class 300 |
| Lay Length | AWWA C508 Appendix A Full |
| | ISO 5752 |
| Classifications | 150 PSIG |
| | 175 PSIG |
| | 200 PSIG* |
| | 250 PSIG* |

American Water Works Association



BY Vincent Lodigno, PE DATE 12/9/24


RESISTANCE GUIDE

| Designation | Common Names | Composition | Min/Max Temperature Range | General Properties | Resistant to: | Attached by: |
|-------------|---------------|---|------------------------------|--|---|--|
| EPDM | EPDM, EPM | Ethylene-propyl- ene-diene Monomer | - 40F/250F | Excellent ozone, chemical, and aging resistance. Poor resistance to petroleum-based fluids | Animal and vegetable oils, ozone, strong and oxidizing chemicals. | Mineral oils and solvents, aromatic hydrocarbons |
| NBR | NBR, Buna-N | Nitrile-butadiene | -30F/225F | Excellent resistance to petroleum-based fluids. Good physical properties | Many hydrocarbons, fats, oils, greases, hydraulic fluids, chemicals | Ozone, ketones, esters, aldehydes, chlorinated and nitro hydrocarbons |
| FPM | FPM, Viton® | Hexaflouroproply- ene-vinylidene fluoride | -10F/400F | Excellent oil and air resistances both at low and high temperatures. Very good chemical resistance | All aliphatic, aromatic, and halogenated hydrocarbons, acids, animal and vegetable oils | Ketones, low-molec- ular weight esters and nitro containing compounds |
| PTFE | PTFE, Teflon® | Polytetrafluoro-eth- ylene | -100F/450F | Excellent abrasion resistance and chemically inert | Acids, harsh inorganic and organic chemicals, oils, oxidizing agents, and solvents | Molten alkali metals and fluorine at high temperatures |

*Standard Option



PRESSURE/TEMPERATURE RATINGS




In determining field pressure ratings for Series CVI Check Valves that are constructed of Ductile Iron the above chart should be used. Pressure cast on valve represents maximum seating pressure; maximum hydrostatic pressure is temperature dependent, and may be higher than nominal pressure rating.



CAM #25-0539 Exhibit 4 Page 36 of 205 to AWWA C508



MATERIALS OF CONSTRUCTION METAL SEATED VALVES




| | | / | | | |
|------|--------------------|---------------------------------|--|--|--|
| ITEM | DESCRIPTION | MATERIAL OF TIONS | | | |
| 1 | BODY | DUCTILE IRON ASTM A536 65-45-12 | | | |
| | | STAINLESS 304 ASTM A276 | | | |
| 2 | BODY SEAT RING | STAINLESS 316 ASTM A276 | | | |
| | KING | BRONZE ASTM B62 | | | |
| | DICOCEAT | STAMLESS 304 ASTM A276 | | | |
| 3 | DISC SEAT RING | STAINLESS 316 ASTM A276 | | | |
| | / | BRONZE ASTM B62 | | | |
| 4 | DISC | DUCTILE IRON ASTM A536 65-45-12 | | | |
| 5 | WASHER! | STEEL ASTM A36 | | | |
| | WETTED | STAINLESS ASTM F593 GROUP 1 | | | |
| 6 | WETTED HARDWARE | STAINLESS ASTM F593 GROUP 2 | | | |
| | | STEEL ASTM A325 TYPE 1 | | | |
| 7 | ARM | DUCTILE IRON ASTM A536 65-45-12 | | | |
| 8 | SEAL | EPDM | | | |
| /° | JLAL | BUNA-N (NBR) | | | |
| 9 | COVER | SAME AS BODY (1) | | | |
| | EXTERIOR | STAINLESS ASTM F593 GROUP 1 | | | |
| 10 | HARDWARE | STAINLESS ASTM F593 GROUP 2 | | | |
| | | STEEL ASTM A325 TYPE 1 | | | |
| 11 | BEARING | PTFE | | | |
| 12 | KEY | STEEL ASTM A36 | | | |
| 13 | SHAFT SEAL | EPDM | | | |
| 13 | SHAFT SEAL | BUNA-N (NBR) | | | |
| 14 | RETAINER | SAME AS BODY (1) | | | |
| | | STAINLESS 304 ASTM A276 | | | |
| 15 | SHAFT | STAINLESS 316 ASTM A276 | | | |
| | | STAINLESS 17-4PH ASTM A693 | | | |
| 16 | ARM* | DUCTILE IRON ASTM A536 65-45-12 | | | |
| 17 | WEIGHT* | DUCTILE IRON ASTM A536 65-45-12 | | | |


^{*} IF EQUIPPED

CAM #25-0539 Exhibit 4 Page 37 of 205



MATERIALS OF CONSTRUCTION RUBBER SEATED





| ITEM | DESCRIPTION | MATERIAL OPTIONS | |
|------|----------------------|---------------------------------|-------|
| 1 | BODY | DUCTILE IRON ASTM A536 65-45-12 | |
| | | STAINLESS 304 ASTM A276 | |
| 2 | BODY SEAT RING | STAINLESS 316 ASTM A276 | |
| | KING | BRONZE ASTM B62 | |
| | | EPDM | 1 |
| 3 | DISC SEAT | BUNA-N (NBR) | |
| | | VITON (FPM) | |
| 4 | DISC | DUCTILE IRON ASTM A536 65-45-12 | 1 |
| 5 | WASHER | STEEL ASTM A36 | |
| | | STAINLESS ASTM F593 GROUP 1 | |
| 6 | WETTED HARDWARE | STAINLESS ASTM F593 GROUP 2 | SS316 |
| | | STEEL ASTM A325 TYPE 1 | |
| 7 | ARM | DUCTILE IRON ASTM A536 65-45-12 | |
| 0 | CEAL | EPDM | |
| 8 | SEAL | BUNA-N (NBR) | |
| 9 | COVER | SAME AS BODY (1) | |
| | 5,4750,00 | STAINLESS ASTM F593 GROUP 1 | |
| 10 | EXTERIOR HARDWARE | STAINLESS ASTM F593 GROUP 2 | SS316 |
| | TIARDIVARE | STEEL ASTM A325 TYPE 1 | |
| 11 | BEARING | PTFE BRONZE | |
| 12 | KEY | STEEL ASTM A36 | |
| 10 | CHAFTCEAL | EPDM | |
| 13 | SHAFT SEAL | BUNA-N (NBR) | |
| 14 | RETAINER | SAME AS BODY (1) | |
| | | STAINLESS 304 ASTM A276 | |
| 15 | SHAFT | STAINLESS 316 ASTM A276 | |
| | | STAINLESS 17-4PH ASTM A693 | |
| 16 | ARM* | DUCTILE IRON ASTM A536 65-45-12 | |
| 17 | WEIGHT* | DUCTILE IRON ASTM A536 65-45-12 | |

* IF EQUIPPED




CAM #25-0539




FLANGED WITH OUTSIDE LEVER AND WEIGHT

| SIZE | A | В | С | D | E | F | WEIGHT (LBS) |
|-----------------|------------------|-----------------|------------------|-----------------|---------------|-----------------|-----------------|
| 2" | 8.00 | 5.4 | 4.75 | 6.0 | 4 | 0.75 | 37 |
| 2.5" | 8.50 | 5.8 | 5.5 | 7.0 | 4 | 0.75 | 44 |
| 3" | 9.50 | 6.3 | 6.00 | 7.2 | 4 | 0.75 | 51 |
| 4" | 11.50 | 7.1 | 7.50 | 9.0 | 8 | 0.75 | 79 |
| 5" | 13.00 | 8.0 | 8.50 | 10.0 | 8 | 0.75 | 101 |
| 6" | 14.00 | 8.8 | 9.50 | 11.0 | 8 | 0.88 | 128 |
| 8" | 19.50 | 10.2 | 11.75 | 13.5 | 8 | 0.88 | 238 |
| 10" | 24.50 | 11.4 | 14.25 | 16.0 | 12 | 1.00 | 374 |
| 12" | 27.50 | 12.8 | 17.00 | 19.0 | 12 | 1.00 | 418 |
| 14" | 31.00 | 16.7 | 18.74 | 21.0 | 12 | 1.13 | 737 |
| 16" | 36.00 | 17.5 | 21.25 | 23.5 | 16 | 1.13 | 968 |
| 18" | 38.00 | 18.9 | 22.75 | 25.0 | 16 | 1.25 | 1500 |
| 20" | 42.00 | 20.7 | 25.00 | 27.5 | 20 | 1.25 | 1600 |
| 24" | 48.00 | 23.9 | 29.50 | 32.0 | 20 | 1.38 | 2600 |
| 30" | 56.00 | 28.6 | 36.00 | 38.8 | 28 | 1.38 | - |
| 36" | 63.00 | 37.9 | 42.75 | 46.0 | 32 | 1.63 | - |
| 42" | 70.00 | 41.0 | 49.50 | 53.0 | 36 | 1.63 | - |
| 48" | 76.00 | 49.0 | 56.00 | 49.5 | 44 | 1.63 | _ |




CAM #25-0539 Exhibit 4 Page 39 of 205





BONDED SEAT SWING CHECK PART NUMBER MATRIX




EXAMPLE:

CVI08F-DDSB-PS1/0-Q

A 8" flanged Check valve with Ductile Iron body and disc, SS304 shaft, Bronze body seat, B. Vocettoga FE DE 12/9/24 NBR seals, PTFE bearings, SS304 hardware, AWWA C550 2-part epoxy coatings with outside lever & weight.

CAM #25-0539



VSI Waterworks LLC

tel: 1 (770) 740 0800 fax: 1 (770) 740 8777

email: sales@vsiwaterworks.com



As part of a process of on-going product development, VSI reserves the right to amend or change specifications without prior notice. Published data may be subject to change. For the latest specific our website at www.vsiwatexmonke.com

Page 42 of 205

City of Fort Lauderdale

NE 38th Street 42-Inch FM and NE 19th Avenue 24-Inch FM Replacement

Submittal Name: SHOP DRAWINGS - PLUG VALVE



| 1. Date of Submission | 12/06/2024 |
|--|---|
| 2. Project Number | P12384 |
| 3. Project Name | NE 38th Street 42-Inch FM and NE 19th Avenue 24-Inch |
| | FM Replacement |
| Contractor Identification | 23-FL.GOLF-001 |
| a. Contractor | David Mancini and Sons, Inc |
| b. Supplier | |
| c. Manufacturer | N/A |
| d. Manufacturer or supplier representative | N/A |
| 5. Identification of the Product | EXB-12.0-P12384-20-0 |
| 6. Reference to Contract Drawing | D02 |
| 7. Reference to Specification Section Number, page and paragraphs. | Technical Specifications 2.02 |
| 8. Indication of Contractor's approval. | Approved by DMSI |
| 9. Contractor's Certification Statement. (Refer to paragraph 1.03.F.2) | "By this submittal, I hereby represent that I have determined and verified all field measurements, field construction criteria, materials, dimensions, catalog numbers and similar data and I have checked and coordinated each item with other applicable approved shop drawings and all Contract requirements." |
| 10. Identification of deviations from the Contract, if any. | |
| 11. Reference to previous submittal (for resubmittals). | |



BY Vincent Locigno, PE DATE 12/9/24





to AWWA C517





IMPLEMENTATIONS

The Eccentric Plug valve is the industry standard for systems that will experience sludge or large particulate flow. VSI Eccentric Plug Valves are able to achieve an extremely high port area while keeping the operating time much lower than the traditional gate valve.


ECCENTRIC MOVEMENT

The most essential function of a valve is that it must isolate line flow. This action is easy to accomplish, but with traditional designs as pressure and size increase the torque required to close the valve increase exponentially.

To counteract this characteristic all VSI Eccentric Plug Valves incorporate an offset in the valve design. By offsetting the plug and shaft centerline from the valve body and pipe centerline a cam action is achieved. This action allows the plug to contact the valve body only in the last 5-10 degrees of movement. Through the rest of the valve motion the only torque transmitted to the operator will be from the low friction bearings and line force on the plug.

The cam action increases the seat force without increasing operator torque allowing for the use of more durable encapsulation materials that are often harder.





RESILIENT PLUG FACING

All VSI Eccentric Plug Valves are equipped as standard with a fully encapsulated resilient plug. By fully encapsulating the plug the service life of the valve is greatly extended by reducing corrosion of the plug. The resilient nature of the seat allows for driptight shut off. Should small solids become deposited upon the plug face, tight shut off is still guaranteed.



ADJUSTABLE/REPLACEABLE **PACKING**

The packing of the Series PVIF consists of multiple v-type packing rings and adjustable gland. The open bonnet on above ground valves allows for the adjustment and replacement of packing without removing the gearbox/operator

NUMEROUS ACTUATION OPTIONS

The standard ISO 5211 top mount allows VSI to offer a wide range of electric, pneumatic, hydraulic, failsafe, and other actuation packages

STANDARD LIFTING EYE

The lifting holes at all ends of the PVIF give a secure and easy attachment point that allows the valve to be confidently maneuvered into place on job sites. Equipped as a standard feature on all PVIF valves, making your install that much easier.

FULL PORT DESIGN

The rectangular port is of a "Full Port" type with a flow area equal to the nominal pipe to maintain excellent free flow, high Cv values, and low head loss. Pigging with semi-rigid foam type pigs is possible.

MULTIPLE COATING OPTIONS

The standard 2-part heavy duty coating can be optioned to a wide variety of coatings as required by the project requirements such as NSF 61 listed coatings, ceramic reinforced resin, or coal-tar epoxy

FULLY ENCAPSULATED PLUG

The plug of the Series PVIF is fully encapsulated with resilient rubber covering every surface exposed to the line. Full encapsulation eliminates corrosion and minimizes the possibility of delamination or damage to the seat.

CAM #25-0539

Exhibit 4 VSI Waterworks Page 46 of 205 VSI Waterworks 1205 Alpha Drive, Alpharetta, GA 30004

T: 770.740.0800 F: 770.740.8777 E: sales@vsiwaterworks.com



SAMPLE SPECIFICATION

1. FULL RECTANGULAR PORT PLUG VAVES FOR WATERWORKS SERVICE

- 1.1. This specification covers the design, manufacture, and testing of eccentric plug valves from 14 inch (350 mm) through 72 inch (1800 mm) under service pressure of up to 150 psig (1035 kPa).
- 1.2. Plug valves shall be resilient seated and of the quarter turn, non-lubricated, eccentric type.

2. <u>GOVERNING STANDARDS</u>

- 2.1. All eccentric plug valves shall be in full conformance with the design, manufacturing, and testing standards set forth by the American Water Works Association (AWWA) in Standard ANSI/AWWA C517.
- 2.2. When requested, manufacturer shall provide an Affidavit of Proof of Design Testing in accordance with AWWA C517.

3. CONNECTIONS

- 3.1. Flanged valves shall conform to all standards of ANSI B16.1, Class 125.
- 3.2. Mechanical joint valves shall conform to all standards of ANSI/AWWA C111/A21.11.

MARKINGS

- 4.1. Each valve shall be marked with the manufacturer's name, valve size, body material, and pressure rating cast into the body of the valve. Lettering shall be a minimum of 1/2 inch tall and project 1/10 inch from body.
- 4.2. All plug valves, except buried or submerged valves, shall be equipped with a type 304 or 316 stainless steel or Aluminum tag identifying body, plug, resilient seat, and stem material in addition to manufacturer's name, pressure rating, size, date of manufacturer, and date of testing.

5. DESIGN

- 5.1. Port areas of valves in relation to pipe areas shall not be less than 100%
- 5.2. Valves shall be equipped with a minimum 95% nickel seat directly bonded to a machined finished surface on valve body. Plated or removable seats are not acceptable.
- 5.3. Valve shall be equipped with a set of V-type stem packing with an adjustable gland. Valve stem packing shall be replaceable without removing the cover or bonnet of the valve.
- 5.4. Radial shaft bushings shall be supplied in the upper and lower bearing journals. Thrust bearings shall be supplied between the plug and body in both the upper and lower journal areas.
- 5.5. The valves shall be equipped with a mounting area for operators conforming to Manufacturers Standard Society(MMS) 101 or International Organization of Standardization(ISO) 52111. There shall be sufficient clearance to directly mount standardized operators with easily accessible fasteners.

6. MATERIALS

- 6.1. The valve body, cover, and bonnet if equipped shall be constructed of ASTM A536 Ductile Iron.
- 6.2. The plug shall be constructed of ASTM A536 Ductile Iron and shall be one piece. The resilient plug encapsulation shall conform to ASTM D429 testing.
- 6.3. Radial and thrust bearings shall be made of permanently lubricated type 316 stainless steel.
- 6.4. All submerged coatings shall conform to AWWA C550, be holiday free, and have a minimum total dry film thickness of 10 mils
- 6.5. All uncovered, submerged, or buried valves shall have type 304 or 316 stainless steel hardware unless specified.

7. OPERATORS

- 7.1. All manually operated valves 4 inch and larger shall be equipped with a worm gear actuator with position indicator. Direct 2" operator nut may be used when specified on 6" and under valves.
- 7.2. All actuators shall be permanently sealed and suitable for buried service.
- 7.3. All 2 inch square operating nuts, exposed hardware and shafts shall be made of corrosion resistant stainless steel.
- 7.4. All actuators equipped with handwheels shall have a maximum rim pull of 80lbs.

8. MANUFACTURER


- 8.1. Eccentric plug valves shall be VSI Series AWWAC517 as manufactured by Valve Solutions, Inc., Alpharetta, GA USA or approved equal.
- 8.2. All valves shall be warranted by manufacturer for a minimum of 12 months.


CAM #25-0539 Exhibit 4 Page 47 of 205





Materials of Construction





| Item | Description | Materials Available | Standard |
|-------------|----------------------------|-------------------------------|------------------------------|
| 1 | Cover | Same as Body | |
| | | Ductile Iron* | ASTM A536 65-45-12 |
| 2 | Body | Cast Iron | ASTM A126 Class B |
| _ | Dody | Stainless Steel 304 | ASTM A351 CF8 |
| | | Stainless Steel 316 | ASTM A351 CF8M |
| | | Ductile Iron* | ASTM A536 65-45-12 |
| 3 | Plug | Cast Iron | ASTM A126 Class B |
| J | rtug | Stainless Steel 304 | ASTM A351 CF8 |
| | | Stainless Steel 316 | ASTM A351 CF8M |
| | | Buna-N (NBR)* | |
| 4 | Plug | Chloroprene | |
| 4 | Encapsulation | EPDM | |
| | | Viton (FPM) | |
| 5 | Bonnet | Same as Body | |
| 6 | Gland | Same as Body | |
| 7 | Packing | Same as Plug Encapsulaton | |
| 8 | Exterior Hardware | Stainless 304* | ASTM F593/594 🗓 |
| · · · · · · | Exterior naroware | Stainless 316 | ASTM F593/594 ASTM F593/594 |
| 9 | Cover Seal | Same as Plug Encapsulation | |
| | | Stainless 316* | |
| 10 | Doorings | Stainless 304 | |
| 10 | Bearings | Reinforced PFTE | |
| | | Bronze | |
| 11 | Grit Guard | Nylon | |
| 12 | Grit Seal | Same as Plug Encapsulation | |
| 13 | Lower Cover ^[2] | Same as Body | |
| | | Fusion Bonded Epoxy, Black* | |
| NS | Coating/Lining | Two-Part Epoxy | |
| | | Coal-Tar Epoxy | |
| NS | Tag | Aluminum* | |
| | Tag | Stainless Steel | |
| NS | Assembly Lubricant | ANSI/NSF 61 Listed Silicone L | ubricant |
| NS | Operator | Varies | |

Additional material options available as special order.

- *Standard Material
- (1) Lower cover integral to body casting on 14"-24"
- (2) Lower journal cover standard on 30" and above


CAM #25-0539

Exhibit 4
Page 48 of 205
1205 Alpha Drive, Alpharetta, GA 30004
T: 770.740.0800 F: 770.740.8777
E: sales@vsiwaterworks.com

Full Port Plug Valves to AWWA C517



Design Standards



*Standard Option



CAM #25-0539 Exhibit 4

Page 49 of 205

Resistance Guide


| Designation | Common Names | Composition | Min/Max Temperature Range | General Properties | Resistant to: | Attacked by: |
|-------------|---------------|---|------------------------------|--|---|--|
| NBR* | NBR, Buna-N | Nitrile-butadiene | -30F/225F | Excellent resistance to petroleum-based fluids. Good physical properties | Many hydrocarbons, fats, oils, greases, hydraulic fluids, chemicals | Ozone, ketones, esters, aldehydes, chlorinated and nitro hydrocarbons |
| FPM | FPM, Viton® | Hexaflouroproply- ene-vinylidene fluoride | -10F/400F | Excellent oil and air resistances both at low and high temperatures. Very good chemical resistance | All aliphatic, aromatic, and halogenated hydrocarbons, acids, animal and vegetable oils | Ketones, low molec- ular weight esters and nitro containing compounds |
| PTFE | PTFE, Teflon® | Polytetrafluoro-eth- ylene | -100F/450F | Excellent abrasion resistance and chemically inert | Acids, harsh inorganic and organic chemicals, oils, oxidizing agents, and solvents | Molten alkali metals and fluorine at high temperatures |
| EPDM | ЕРДМ, ЕРМ | Ethylene-propyl- ene-diene Monomer | -40F/250F | Excellent ozone, chemical, and aging resistance. Poor resistance to petroleum-based fluids | Animal and vegetable oils, ozone, strong and oxidizing chemicals. | Mineral oils and solvents, aromatic hydrocarbons |

VSI Waterworks 1205 Alpha Drive, Alpharetta, GA 30004 T: 770.740.0800 F: 770.740.8777

E: sales@vsiwaterworks.com



Pressure/Temperature Ratings



In determining field pressure ratings for Series PVIF Plug Valves that are constructed of Ductile Iron the above chart should be used. Pressure cast on valve represents maximum seating pressure; maximum hydrostatic pressure is temperature dependent, and may be higher than nominal pressure rating.





Cold Working Pressure Rating


| SIZE | FORWARD CLOSEOFF W/GEAR | REVERSE CLOSEOFF W/ GEAR | FORWARD CLOSEOFF NUT AND/OR LEVER | REVERSE CLOSEOFF NUT AND/OR LEVER |
|------------|-------------------------------|--------------------------------|---|---|
| 14"+ CL125 | 150 PSI | 150 PSI | NA | NA |
| 14"+ MJ | 150 PSI | 150 PSI | NA | NA |
| 14"+ CL250 | 250 PSI | 150 PSI | NA | NA |




Flanged CL125 Barestem Dimensions









Vincent Locigno, PE DATE 12/9/24

| SIZE | A | В | С | D | E | F | G | H ⁽¹⁾ | J ⁽²⁾ | K ⁽³⁾ | L ⁽⁴⁾ |
|------|-------|------|-------|-------|------|-------|-------|------------------|-------------------------|------------------|------------------|
| 14" | 17.00 | 1.38 | 13.11 | 17.00 | 3.35 | 21.00 | 18.75 | 8 | 1.125 | 4 | 1-8UNC |
| 16" | 17.75 | 1.44 | 14.37 | 17.70 | 3.54 | 23.50 | 21.25 | 8 | 1.125 | 8 | 1-8UNC |
| 18" | 21.50 | 1.56 | 15.95 | 19.10 | 3.35 | 25.20 | 22.75 | 8 | 1.25 | 8 | 1.125-7UNC |
| 20" | 23.50 | 1.69 | 16.62 | 20.00 | 3.64 | 28.15 | 25.00 | 12 | 1.25 | 8 | 1.125-7UNC |
| 24" | 42.00 | 1.88 | 20.67 | 23.30 | 4.66 | 32.00 | 29.50 | 20 | 1.375 | 8 | 1.25-7UNC |
| 30" | 51.00 | 2.12 | 26,57 | 30.12 | 4.92 | 38.75 | 36.00 | 20 | 1.375 | 8 | 1.25-7UNC |
| 36" | 60.00 | 2.38 | 30.71 | 34.41 | 5.50 | 46.00 | 42.75 | 24 | 1.625 | 8 | 1.5-6UNC |
| 42" | 72.00 | 2.62 | 37.40 | 43.26 | 7.50 | 53.00 | 49.50 | 32 | 1.625 | 4 | 1.5-6UNC |
| 48" | 84.00 | 2.75 | 42.32 | 47.33 | 7.50 | 59.50 | 56.00 | 40 | 1.625 | 4 | 1.5-6UNC |


- (1) "H" represents the total number of through holes, per flange (2) "J" represents the size of the through holes for flange


- (3) "K" represents the total number of tapped holes, per flange (4) "L" represents the size of tapped holes and bolts used for flange


CAM #25-0539 Exhibit 4 Page 51 of 205




Mechanical Joint Barestem Dimensions











| SIZE | Α | В | C | D | E | F | G | $H^{(1)}$ | J ⁽²⁾ |
|------|-------|------|-------|-------|------|-------|-------|-----------|-------------------------|
| 14" | 24.50 | 0.79 | 13.11 | 17.00 | 3.35 | 20.31 | 18.75 | 0.88 | 6 |
| 16" | 27.25 | 0.85 | 14.37 | 17.72 | 3.54 | 22.64 | 21.00 | 0.88 | 8 |
| 18" | 29.25 | 1.00 | 15.95 | 19.10 | 3.35 | 25.00 | 23.25 | 0.88 | 8 |
| 20" | 31.00 | 1.02 | 16.62 | 20.00 | 3.64 | 27.16 | 25.50 | 0.88 | 10 |
| 24" | 42.00 | 1.02 | 20.67 | 23.31 | 4.66 | 31.89 | 30.00 | 0.88 | 12 |
| 30" | 51.00 | 1.31 | 26.57 | 30.12 | 4.92 | 39.12 | 36.88 | 1.13 | 12 |
| 36" | 60.00 | 1.45 | 30.71 | 34.41 | 5.50 | 46.00 | 43.75 | 1.13 | 16 |
| 42" | 72.00 | 1.45 | 37.40 | 43.26 | 7.50 | 53.12 | 50.62 | 1.38 | 20 |
| 48" | 84.00 | 1.45 | 42.32 | 47.33 | 7.50 | 60.00 | 57.50 | 1.38 | 24 |


- (1) "H" represents the size of through holes, bolt size is 1/8" smaller
 Flange's drilling/bolting and bell end/gasket groove dimensions per AWWA C111
- (2) "J" represents the total number through holes, per flange




Flanged With Worm Gear & HW









| SIZE | A | В | С | D | E | F | G | H ⁽¹⁾ | J ⁽²⁾ | K ₍₃₎ | L ⁽⁴⁾ | P |
|------|-------|------|-------|-------|------|-------|-------|------------------|------------------|------------------|------------------|------|
| 14" | 17.00 | 1.38 | 13.11 | 17.00 | 3.35 | 21.00 | 18.75 | 8 | 1.125 | 4 | 1-8UNC | 24 |
| 16" | 17.75 | 1.44 | 14.37 | 17.70 | 3.54 | 23.50 | 21.25 | 8 | 1.125 | 8 | 1-8UNC | 24 |
| 18" | 21.50 | 1.56 | 15.95 | 19.10 | 3.35 | 25.20 | 22.75 | 8 | 1.25 | 8 | 1.125-7UNC | 20 |
| 20" | 23.50 | 1.69 | 16.62 | 20.00 | 3.64 | 28.15 | 25.00 | 12 | 1.25 | 8 | 1.125-7UNC | 24 |
| 24" | 42.00 | 1.88 | 20.67 | 23.30 | 4.66 | 32.00 | 29.50 | 20 | 1.375 | 8 | 1.25-7UNC | 24 |
| 30" | 51.00 | 2.12 | 26,57 | 30.12 | 4.92 | 38.75 | 36.00 | 20 | 1.375 | 8 | 1.25-7UNC | 27.5 |
| 36" | 60.00 | 2.38 | 30.71 | 34.41 | 5.50 | 46.00 | 42.75 | 24 | 1.625 | 8 | 1.5-6UNC | 31.5 |
| 42" | 72.00 | 2.62 | 37.40 | 43.26 | 7.50 | 53.00 | 49.50 | 32 | 1.625 | 4 | 1.5-6UNC | 35.5 |
| 48" | 84.00 | 2.75 | 42.32 | 47.33 | 7.50 | 59.50 | 56.00 | 40 | 1.625 | 4 | 1.5-6UNC | 31.5 |

- (1) "H" represents the total number of through holes, per flange (2) "J" represents the size of the through holes for flange (3) "K" represents the total number of tapped holes, per flange


- (4) "L" represents the size of tapped holes and bolts used for flange


CAM #25-0539 Exhibit 4 Page 53 of 205


E: sales@vsiwaterworks.com




Mechanical Joint With Worm Gear & 2" Nut Op









| chen moore and associates |
|--|
| NO EXCEPTIONS TAKEN FURNISH WITH CHANGES NOTED REJECTED REJECTED |
| This roles is only for general conformance with sealing encouncy of the operated and general compliance and present and present and general compliance of the present and present and the pres |


| SIZE | A | В | С | D | E | F | G | H ⁽¹⁾ | J ⁽²⁾ |
|------|-------|------|-------|-------|------|-------|-------|------------------|-------------------------|
| 14" | 24.50 | 0.79 | 13.11 | 17.00 | 2.00 | 20.25 | 18.75 | 0.88 | 6 |
| 16" | 27.25 | 0.85 | 14.37 | 17.72 | 2.00 | 22.50 | 21.00 | 0.88 | 8 |
| 18" | 29.25 | 1.00 | 15.95 | 19.10 | 3.15 | 24.75 | 23.25 | 0.88 | 8 |
| 20" | 31.00 | 1.02 | 16.62 | 20.00 | 3.55 | 27.00 | 25.50 | 0.88 | 10 |
| 24" | 42.00 | 1.02 | 20.67 | 23.31 | 3.98 | 31.50 | 30.00 | 0.88 | 12 |
| 30" | 51.00 | 1.31 | 26.57 | 30.12 | 5.47 | 39.12 | 36.88 | 1.13 | 12 |
| 36" | 60.00 | 1.45 | 30.71 | 34.41 | 6.61 | 46.00 | 43.75 | 1.13 | 16 |
| 42" | 72.00 | 1.45 | 37.40 | 43.26 | 6.77 | 53.12 | 50.62 | 1.38 | 20 |
| 48" | 84.00 | 1.45 | 42.32 | 47.33 | 7.36 | 60.00 | 57.50 | 1.38 | 24 |

- (1) "H" represents the size of through holes, bolt size is 1/8" smaller
 - Flange's drilling/bolting and bell end/gasket groove dimensions per AWWA C111
- (2) "J" represents the total number through holes, per flange



STANDARD OPERATOR TYPES

SINGLE STAGE WORM GEAR WITH SPUR SECONDARY GEAR





Vincent Lociono PE DATE 12/9/24


HANDWHEEL *****



2-INCH NUT OP.




CHAINWHEEL




CAM #25-0539 Exhibit 4 Page 55 of 205



FLOW CHARACTERISTICS



| SIZE | Cv | Kv |
|------|-------|-------|
| 14" | 6085 | 5257 |
| 16" | 8199 | 7084 |
| 18" | 12168 | 10513 |
| 20" | 15710 | 13573 |
| 24" | 25565 | 22088 |
| 30" | 38315 | 33104 |
| 36" | 58623 | 50650 |
| | | |







BY Vincent Locigno, PE DATE 12/9/24


VSI Waterworks

1205 Alpha Drive, Alpharetta, GA 30004 T: 770.740.0800 F: 770.740.8777 E: sales@vsiwaterworks.com





PART NUMBER MATRIX



* Standard Material

1 - May not be available for all configurations/sizes

EXAMPLE:

PVIF14F-DDN-3S1/WC-J

A 14" flanged rectangular full port plug valve with Ductile Iron body and plug, NBR plug encapsulation, SS316 bearings, SS304 hardware, Fusion bonded epoxy, worm gearbox with chainwheel operator.

DOC#:

C517-36-POD

AWWA C517-09 Proof of Design Test Certification (36" Resilient Seated Eccentric Plug Valve)

ITEM TESTED:

VSI C517 Series Resilient Seated Eccentric Plug Valve - 36 inch size (150psi) Ductile Iron Body and Bonnet 95% Nickel Bonded Seat Ductile Iron Plug encapsulated in NBR

PURPOSE:

To perform the Proof of Design test requirements laid out in American Water Works Association (AWWA) Standard C517, Resilient Seated Cast Iron Eccentric Plug Valves.

RECORD OF TEST:

PLUG STRUCTURE TEST: The test valve was mounted to the test heads, and the valve put into the closed position. A pressure of 300 psi was then applied to the seat side of the plug for 60 seconds. The pressure was then released, and 300 psi was applied to the back side of the plug for 60 seconds. After the test pressure was released, the plug was inspected. There were no signs of deformation nor breakage found.

LIFE CYCLE TEST: The test valve was mounted to the test heads, and put into the closed position. A test pressure of 150 psi was applied to the seat side of the valve, and zero pressure on the back side. The valve was then operated from fully closed to fully open 5,000 times. The test took place over a period of 21 days. Upon completion of the life cycle test, a hydrostatic seat test was performed. A test pressure of 150 psi was applied to the seat side of the valve and held for 60 seconds. The test pressure was then relieved and applied to the back side of the plug for 60 seconds. There were no visible signs of leakage from the stem, seat, or any other pressure constraining joints.

POST TEST INSPECTION: Upon completion of all the tests, the valve was disassembled, and inspected. There were no signs of extensive wear, cracking, or bonding failure on the valves corrosion-resistant seating surfaces.

CERTIFICATION:

PROOF OF DESIGN CERTIFICATION

Based on the above test record, we here by certify that the test valve has successfully met all of the proof of design requirements in AWWA C517 and therefore qualifies similar valves in the Series C517 24 inch through 42 inch product line, with equal or lesser pressure classes to the same standards.

| TESTED BY:Robert Wa | Robert wan gang, Valve Solutions, Inc. | DATE: <u>05/31/2010</u> | |
|---------------------|--|--|--------|
| CERTIFIED BY: | Michael. fan el Fan, Tianjin Flow Security Valve Co., Ltd | DATE: <u>05/31/2010</u> | |
| 36" RESILIENT SEAT | ED ECCENTRIC PLUG VALVE | ©%A\T₩25-0539 Ex \05\/\8 1/203 | LO |

DOC#:

C517-42-POD

AWWA C517-09 Proof of Design Test Certification (42" Resilient Seated Eccentric Plug Valve)

ITEM TESTED:

VSI C517 Series Resilient Seated Eccentric Plug Valve - 42 inch size (150psi) Ductile Iron Body and Bonnet 95% Nickel Bonded Seat Ductile Iron Plug encapsulated in NBR

PURPOSE:

To perform the Proof of Design test requirements laid out in American Water Works Association (AWWA) Standard C517, Resilient Seated Cast Iron Eccentric Plug Valves.

RECORD OF TEST:

PLUG STRUCTURE TEST: The test valve was mounted to the test heads, and the valve put into the closed position. A pressure of 300 psi was then applied to the seat side of the plug for 60 seconds. The pressure was then released, and 300 psi was applied to the back side of the plug for 60 seconds. After the test pressure was released, the plug was inspected. There were no signs of deformation nor breakage found.

LIFE CYCLE TEST: The test valve was mounted to the test heads, and put into the closed position. A test pressure of 150 psi was applied to the seat side of the valve, and zero pressure on the back side. The valve was then operated from fully closed to fully open 5,000 times. The test took place over a period of 21 days. Upon completion of the life cycle test, a hydrostatic seat test was performed. A test pressure of 150 psi was applied to the seat side of the valve and held for 60 seconds. The test pressure was then relieved and applied to the back side of the plug for 60 seconds. There were no visible signs of leakage from the stem, seat, or any other pressure constraining joints.


POST TEST INSPECTION: Upon completion of all the tests, the valve was disassembled, and inspected. There were no signs of extensive wear, cracking, or bonding failure on the valves corrosion-resistant seating surfaces.

CERTIFICATION:

PROOF OF DESIGN CERTIFICATION

Based on the above test record, we here by certify that the test valve has successfully met all of the proof of design requirements in AWWA C517 and therefore qualifies similar valves in the Series C517 24 inch through 42 inch product line, with equal or lesser pressure classes to the same standards.

| TESTED BY: Robert War | Robert uang g, Valve Solutions, Inc. | DATE: <u>06/07/2010</u> |
|--------------------------|---|----------------------------------|
| CERTIFIED BY: Michae | Michael fam Fan, Tianjin Flow Security Valve Co., Ltd | DATE: <u>06/07/2010</u> |
| 42" RESILIENT SEATE | D ECCENTRIC PLUG VALVE | ©%A\T#25-0539 E×1066/407/2010 |



VSI Waterworks LLC

tel: 1 (770) 740 0800 fax: 1 (770) 740 8777

email: sales@vsiwaterworks.com



As part of a process of on-going product development, VSI reserves the right to amend or change specifications without prior notice. Published data may be subject to change. For the latest specific our website at www.vsiwatexmonke.com



VSI Waterworks 2" - 72" AWWA C517 ECCENTRIC PLUG VALVES

INSTALLATION, OPERATION AND MAINTENANCE MANUAL





INSTALLATION, OPERATION AND MAINTENANCE VSI AWWA C517 ECCENTRIC PLUG VALVES

TABLE OF CONTENTS

| SCOPE | 3 |
|----------------------------------|---|
| WARNINGS | 3 |
| GENERAL | 4 |
| UNLOADING | 4 |
| STORAGE | 4 |
| INSPECTION PRIOR TO INSTALLATION | 4 |
| INSTALLATION | 4 |
| TESTING | 6 |
| RECORDS | 7 |
| OPERATION | 7 |
| MAINTENANCE | 7 |
| TROUBLESHOOTING | 9 |

INSTALLATION, OPERATION AND MAINTENANCE VSI AWWA C517 ECCENTRIC PLUG VALVES



SCOPE:

This installation, operation, and maintenance manual covers the VSI AWWA C517 resilient seated eccentric plug valve and should be read and understood thoroughly by all parties responsible for installation and continued use/maintenance.

WARNINGS:

The critical safety messages within this manual are labeled with an exclamation symbol within a red triangle flag. Care should be taken to thoroughly read and understand these warnings before proceeding to ensure no damage to equipment occurs. Failure to follow all warnings could result in injury or death.



WARNING!

All parties that take part in any installation or continued use/maintenance are cautioned to be vigilant in the possible exposure to media that is contained within the valve and its pipeline. Because of the vast range of media that could be within the valve, protection from pipeline media is not within the scope of this manual. All personnel should be aware of the media within the valve and take appropriate precautions when exposure is possible while installing or servicing the valve.

RECEIVING:

The VSI AWWA C517 Resilient Seated Eccentric Plug Valve is rugged and will be packaged to provide protection during most shipping incidents, however care should be taken to inspect the valve on receipt for any possible shipping damage. Inspection should be performed as soon as practical. Failure to promptly notify VSI of any shipping damage may invalidate any claim for shipping damage. Most shipments from VSI will be made FOB Origin, unless noted on the sales documents, the purchaser will own the freight while in transit, assumes all risk while in transit, and will be responsible for reporting shipping damage promptly to the carrier.

PARTS:

Order parts from your Valve Solutions Inc. sales representative. Please include the serial number, located on the valve tag, when ordering parts.



WARNING!

Read all applicable instructions and directions prior to any maintenance, installation or troubleshooting.



INSTALLATION, OPERATION AND MAINTENANCE **VSI AWWA C517 ECCENTRIC PLUG VALVES**

SECTION 1: GENERAL

Plug valves are a significant component of any water distribution system or treatment plant operation. Valve failure due to faulty installation, improper operation, or maintenance in such systems could result in damage, downtime, and costly repairs. In buried or underground installations, problems or malfunctions can result in extensive and costly unearthing operations to correct or eliminate the problem. Many problems with plug valves can be traced to improper installation, operation, or maintenance procedures.

SECTION 2: UNLOADING

Inspect valves on receipt for damage in shipment and conformance with quantity and description on the shipping notice and order. Unload valves carefully to the ground without dropping. On valves larger than 6 in. (150 mm), use forklifts or slings under skids. On smaller valves, do not lift valves with slings or chain around actuator or through waterway. Lift these valves with eyebolts or rods through flange holes or chain hooks at the ends of valve parts.

SECTION 3: STORAGE

If it is not practical to store the valve indoors, protect the valve and actuators from weather and the accumulation of dirt, rocks, and debris. When valves fitted with power actuators and controls are stored, energize electric actuators or otherwise protect electrical-control equipment to prevent corrosion of electrical contacts due to condensation resulting from temperature variation. Do not expose resilient seats to sunlight or ozone for any extended period. Also see the manufacturer's specific storage instructions.

SECTION 4: INSPECTION PRIOR TO INSTALLATION

Make sure valve ends and seats are clean. Check all exposed bolting for loosening in transit and handling and tighten to manufacturer's recommendations. Open and close the valve to make sure it operates properly and that stops or limit switches are correctly set so that the plug seats fully. Close the valve before installing. Check coatings for damage and repair as required.

SECTION 5: INSTALLATION

It is strongly recommended that instruction manuals supplied by the manufacturer be reviewed in detail before installing plug valves. Be sure the inspection, as described in Sec. 4, is carried out at the job site prior to installation.

Sec. 5.1 Handling

Handle valves carefully when positioning, avoiding contact or impact with other equipment or structures.

INSTALLATION, OPERATION AND MAINTENANCE VSI AWWA C517 ECCENTRIC PLUG VALVES



Sec. 5.2 Service Conditions

Valves are to be installed in accordance with the manufacturer's instructions.

5.2.1 Clean service. Eccentric plug valves used for fluids free of suspended solids may be installed in any orientation. If practical, the valves shall be installed so the pipe line pressure is exerting force on the plug from opposite the seat end of the valve (direct pressure).




Image courtesy of Robert O'Neill

Figure 1. Recommended installation position for suspended solids service

5.2.2 Other service. Eccentric plug valves used for fluids containing suspended solids should be installed as shown in Figure 1. When installed in horizontal pipes, the axis of the plug is to be horizontal, with flow entering the valve body from the seat end. The plug is to rotate counterclockwise to open, keeping the plug in the upper half of the body. When installed in vertical pipes, the seat end shall be oriented as shown in Figure A-1.

Sec. 5.3 Buried Installations

When practical, valves in buried installations should be located in unpaved areas.

Sec. 5.4 Cleaning

Be sure valve interiors, ends, and adjacent piping are cleaned of foreign material prior to making up valve-to-pipe joint connection.



INSTALLATION, OPERATION AND MAINTENANCE VSI AWWA C517 ECCENTRIC PLUG VALVES

Sec. 5.5 Pipe Ends

Prepare pipe ends and install valves in accordance with the pipe manufacturer's instructions for the joint used. Do not deflect the pipe-valve joint. Do not use a valve as a jack to pull pipe into alignment. In plant piping, the valve shall be installed so as to minimize the bending stresses in the valve end connection with pipe loading.

Sec. 5.6 Installation

For mechanical-joint end valves, lubrication and additional cleaning should be provided by brushing both the gasket and the plain end of the mating pipe with soapy water or pipe lubricant just before slipping the gasket onto the plain end and assembling the joint. When tightening bolts, it is essential that the gland be brought up toward the bell flange evenly, maintaining approximately the same distance between the gland and the face of the flange at all points around the socket. This may be achieved by first partially tightening the bottom bolt, then the top bolt, next the bolts at either side, and finally, the remaining bolts. This process should be repeated until all bolts are fully torqued.

Sec. 5.7 Valve Boxes

Buried valves installed with valve boxes shall be installed so that the valve box does not transmit shock or stress to the valve actuator as a result of shifting soil or traffic load.

Sec. 5.8 Valves Installed in Vaults

When valves are installed in vaults, the vault design shall provide space for removal of the valve-actuator assembly for purposes of repair. Consideration should be given to the possible entry of groundwater or surface water and to the need to provide for disposal thereof. The valve operating nut should be accessible from the top opening of the vault with a tee wrench.

SECTION 6: TESTING

When resilient-seated cast-iron eccentric plug valves are used to isolate sections of a pipeline for testing, it is important to realize that eccentric plug valves are typically factory adjusted to hold pressure only up to the specified shutoff pressure in the direct pressure direction. Prior to any field pressure test under conditions different from above, it is recommended that the valve manufacturer be contacted for approval. Otherwise, test pressures above the valve design pressure may cause leakage, permanent damage, or structural failure to the valve and injury or death to the operator.

Sec. 6.1 Leaks

In order to prevent the loss of time due to searching for leaks, it is recommended, where feasible, that excavations for buried valves not be backfilled until after pressure tests have been completed.

Sec. 6.2 Seat Leakage

Seat leakage can occur from foreign material in the line. If this occurs, open the valve 5° to

INSTALLATION, OPERATION AND MAINTENANCE VSI AWWA C517 ECCENTRIC PLUG VALVES



10° to obtain high-velocity flushing action, then close. Repeat several times to clear seats for tight shutoff. Do not force valves for a tighter seal. Plug valves are provided with an externally adjustable closed stop on the actuator to provide a tighter seal. See the instruction manual provided by the manufacturer for the correct adjustment procedure.

SECTION 7: RECORDS

On completion of installation, the valve location, size, make, type, date of installation, number of turns to open, direction of opening, and any other information deemed pertinent should be entered on the owner's permanent records.

SECTION 8: OPERATION

Sec. 8.1 Design Pressure

Do not permit the use or operation of any valve at pressures above the rated design pressure of the valve.

Sec. 8.2 Input Torque

Do not exceed 250 ft-lb (339 N·m) input torque on actuators with wrench nuts and do not exceed 200 lb (890 N) rim pull for handwheels or chainwheels. If portable auxiliary actuators are used, size the actuator or use a torque-limiting device to prevent application of torque exceeding 250 ft-lb (339 N·m). If an oversize actuator with no means of limiting torque is used, stop the actuator before the valve is fully opened or closed against stops and complete the operation manually. Be sure to check the actuator directional switch against the direction indicated on the wrench nut, handwheel, or records before applying opening or closing torque.

Sec. A.8.3 Sticking

If a valve is stuck in some intermediate position between open and closed, check first for jamming in the actuator. If nothing is found, the interference is inside the valve. In this case, do not attempt to force the plug open or closed, because excessive torque in this position can severely damage internal parts.

SECTION 9: MAINTENANCE

Maintenance of resilient-seated plug valves by the owner is generally limited to actuators and shaft seals. Unless the owner has skilled personnel and proper equipment, any major internal problem will probably require removal of the valve from the line and return to the manufacturer for repair.

Sec. 9.1 Normal Maintenance

Normal maintenance is in the area of shaft seals and actuators. Seal leakage, broken parts, hard operation, and, in some cases, seat leakage should be corrected by a repair crew as soon as possible after a defect is reported.



INSTALLATION, OPERATION AND MAINTENANCE VSI AWWA C517 ECCENTRIC PLUG VALVES

Sec. 9.2 Valve Exercising

Each valve should be operated through a full cycle and returned to its normal position on a time schedule that is designed to prevent a buildup of lubrication or other deposits that could render the valve inoperable or prevent a tight shutoff. The interval of time between operations of valves in critical locations or valves subjected to severe operating conditions should be shorter than for other less important installations, but it can be whatever time period is found to be satisfactory based on local experience. For gear operators, the number of turns required to complete the operation cycle should be recorded and compared with permanent installation records to ensure full plug travel.

Sec. 9.3 Field Repairs

If repairs are to be made in the field, repair crews should take a full complement of spare parts to the job site. Be sure to review the valve manufacturer's instructions prior to any repair work.

Sec. 9.4 Isolation

Provision should be made to stop line flow and isolate the valve from line pressure prior to performing any corrective maintenance.

Sec. 9.5 Repair Testing

After completing repairs, cycle the valve through one complete operating cycle and, after line pressure has been restored, inspect for leakage.

Sec. 9.6 Valve Removal

If major repairs require the removal of the valve for repair, be sure to notify interested parties in the water department and fire department that the valve and line are out of service. On completion of repair and reinstallation, notify the same personnel of the return of the valve and line to service.





SECTION 10: TROUBLESHOOTING

| Problem | Cause | Correction |
|---|--|---|
| The operator or shaft will not turn | Interference between valve box and shaft key | Reposition valve box if necessary |
| | Uneven tightening of gland plate bolts | Loosen then retighten bolts and nuts evenly |
| | Corrosion or debris between the stem and packing | Consult VSI for disassembly procedures and clean stem, stuffing, and stem nut |
| | Debris blocking movement of plug | Consult VSI for disassembly procedures and clean out debris |
| | RARE: Seized worm gear | Inspect and replace if necessary |
| Leakage between the body and cover of valve | Bolts and nuts may be loose or tightened irregularly | Loosen then retighten bolts and nuts evenly |
| | Bonnet o-ring may be damaged | Consult VSI for disassembly procedures and replace o-ring |
| | RARE: Crack in body or bonnet | Inspect and replace if necessary |
| Leakage at the stem | Damaged stuffing | Consult VSI for disassembly procedures and replace damaged parts if needed |
| | Loose packing | Tighten the packing gland nuts until leakage stops or replace packing |
| Valve fails pressure test | Valve is not completely closed | Close valve completely |
| or a leak present in the line | Debris trapped between plug and seat | Throttle valve from fully closed to approximately 25% open several times under line flow to clear debris. If unsuccessful follow instructions for disassembly and remove debris |
| | Rubber plug or metal seat is damaged | Consult VSI for disassembly procedures to inspect for damage. If present replace damaged parts. |



2601 Wiles Rd Pompano Beach Florida 33073 PH: (954) 977-3556 FAX: (954) 944-2040

CONTRACT: P12384

PROJECT: Coral Ridge Force Main Replacement CONTRACTOR: David Mancini & Sons, Inc. (DMSI)

DATE: 2/4/2025

DESCRIPTION: Additional cost related to Repump B connection with 36-Inch above ground bypass no includeded on the scope of work

on the DCP.

SUMMARY OF DIRECT COSTS

| CHAIL | MANT OF DIRECT COSTS | | | |
|-------|--|-------|-----------|------------|
| 1 | TOTAL LABOR | 5 | 85,527.96 | |
| 2 | TOTAL EQUIPMENT | | | 71,374.80 |
| 3 | TOTAL MATERIAL | | \$ | 420,467.87 |
| 4 | TOTAL SUBCONTRACTORS | | \$ | 126,980.61 |
| | SUBTOTAL | | \$ | 704,351.24 |
| 5 | CONTRACTOR'S MARKUP | 8.00% | \$ | 56,348.10 |
| 7 | GENERAL CONDITIONS [Items (3+4+5)/Construction Cost] 5.35% | | | 37,682,79 |
| 8 | TAXES | | 5 | 25,278.07 |
| | Total Direct Cost | | 5 | 798,382.13 |

SUMMARY OF TIME IMPACT (REQUEST FOR ADDITIONAL TIME)

DMSI reserves the right to claim for additional contract time if the critical path is affected after approval.

Submitted by:

andra Suarez 02/04/2025 Alejandra Suarez

Assistant Project Manager David Mancini and Sons, Inc.

Approved by:

Cyrill Garcia Project Manager City of Fort Lauderdale



LABOR COSTS

| SUMMARY - LABOR COSTS | | | 700 |
|-----------------------|-------------|----|-----------|
| SUPERVISION | | 5 | 20,175.00 |
| CREW | | \$ | 28,545.00 |
| LABOR BURDEN (75,55%) | | \$ | 36,807.96 |
| | TOTAL LABOR | \$ | 85,527.96 |

| LABOR BURDEN MULTIPLIER (LBM) | 58.20% |
|--|--------|
| Social Security Contributions & Excise and Payroll | 6.20% |
| Medicate Rate | 1.45% |
| Unemplayment | 5.49% |
| Workmens Compensation | 7.16% |
| Health Benefits | 14.20% |
| Retirement Benefits | 23.70% |
| VACATION MULTIPLIER (VM) | 13.00% |
| Sick Leave (1 week out of 52) | |
| Vacation (2 weeks out of 52) | |
| Holiday Pay (1 week out of 52) | |
| Insurance Schedule | 4.35% |
| General Liability Insurance | 4.35% |

| Total Labor Burden Rate | 75.55% |
|-------------------------|--------|
| | |

| SUPERVISION | Hourly Rate (Salary) Hourly Overtime Ra | | Hourly Overtime Rate | Hours (Salary) | Hours Overtime | Total Cost | |
|-------------------|---|-------|----------------------|----------------|----------------|------------|-----------|
| Project Manager | \$ 6 | 50.D0 | | 30.00 | | \$ | 1,800.00 |
| Superintendent | \$ 5 | 55.00 | | 75.00 | | \$ | 4,125.00 |
| Crew Foreman | \$ | 17.50 | | 150.00 | | \$ | 7,125.00 |
| Crew Foreman | \$ 4 | 17.50 | | 150.00 | | 5 | 7,125.00 |
| TOTAL SUPERVISION | | | | | | \$ | 20,175.00 |

| MAINLINE CREW - DMSI | DMSI Hourly Rate Hourly Overtime Rate | | vertime Rate | Hours | Hours Overtime | 10 | Total Cost | |
|----------------------|---------------------------------------|-------|--------------|-------|----------------|-------|------------|-----------|
| Excavator Operator | \$ | 30.00 | \$ | 45.00 | 120.00 | 30.00 | 5 | 4,950.00 |
| Loader Operator | \$ | 27.00 | \$ | 40.50 | 120.00 | 30.00 | \$ | 4,455.00 |
| Pipe Layer | \$ | 28,00 | 5 | 42.00 | 120.00 | 30,00 | 5 | 4,620.00 |
| Skilled Laborer | \$ | 24,00 | \$ | 36.00 | 120.00 | 30.00 | \$ | 3,960.00 |
| Skilled Laborer | \$ | 24.00 | \$ | 36.00 | 120.00 | 30.00 | \$ | 3,960.00 |
| Laborer | \$ | 20,00 | 5 | 30,00 | 120.00 | 30,00 | 5 | 3,300.00 |
| Laborer | \$ | 20.00 | 5 | 30.00 | 120.00 | 30,00 | \$ | 3,300.00 |
| TOTAL CREW | | | | | | | \$ | 28,545.00 |

| ASSEMBLY CREW - DMSI | В | ourly Rate | Hourly O | vertime Rate | Hours | Hours Overtime | 1.3 | Total Cost |
|----------------------|----|------------|----------|--------------|--------|----------------|-----|------------|
| Excavator Operator | 5 | 30.00 | 5 | 45.00 | 120.00 | 30.00 | 5 | 4,950.00 |
| Loader Operator | \$ | 27.00 | 5 | 40.50 | 120.00 | 30.00 | 5 | 4,455.00 |
| Pipe Layer | \$ | 28.00 | \$ | 42.00 | 120,00 | 30.00 | 5 | 4,620,00 |
| Skilled Laborer | \$ | 24.00 | \$ | 36.00 | 120.00 | 30.00 | \$ | 3,960.00 |
| Skilled Laboret | \$ | 24.00 | 5 | 35.00 | 120.00 | 30.00 | 5 | 3,960.00 |
| Laborer | \$ | 20,00 | \$ | 30.00 | 120.00 | 30,00 | 5 | 3,300,00 |
| Laborer | 5 | 20,00 | \$ | 30,00 | 120.00 | 30,00 | 5 | 3,300,00 |
| TOTAL CREW | | | | | | | | 28,545.00 |

EQUIPMENT, MATERIAL & SUBCONTRACTOR COSTS



| EQUIPMENT COSTS - RENTAL RATE BLUE BOOK | - | | | | |
|---|----|------------|---------------|-----|------------|
| Skid-Steer | Wo | rking Rate | Working Hours | 114 | Total Cost |
| CAT 272D | \$ | 84.69 | 150.00 | 5 | 12,703.50 |
| Loaders | | | | 10 | |
| CAT 938M | 15 | 65.42 | 150.00 | 5 | 9,813.00 |
| Excavators | | | | 1 | |
| CAT 308 | \$ | 68.14 | 150,00 | 5 | 10,221.00 |
| CAT 325 | \$ | 133.24 | 150.00 | 5 | 19,986.00 |
| Trucks | | | | | |
| Pick-Up Truck - Chevy Silverado 2500 - Foreman | \$ | 23.39 | 60.00 | 5 | 1,403.40 |
| Pick-Up Truck - Chevy Silverado 2500 - Foreman | 5 | 23.39 | 50.00 | 5 | 1,403.40 |
| Miscellaneous Equipment | | | | | |
| Trash Pump | \$ | 9.83 | 150,00 | 5 | 1,474.50 |
| Steel Plates - 8'x20' (6 On Site 560 per plate PER DAY) | 5 | 360.00 | 15.00 | 5 | 5,400,00 |
| Air Compressor Sullair 375 | \$ | 59.80 | 150.00 | 5 | 8,970.00 |
| TOTAL EQUIPMENT | | | | 5 | 71,374.80 |

| MATERIAL COSTS | | | | | | |
|----------------------------|-----|------|-----|------------|----|------------|
| Material Description | QTY | Unit | | Unit Cost | - | otal Cost |
| 36" FLGXPE DIP 6' | 1 | ĒΑ | 1 5 | 9,988.24 | 5 | 9,988,24 |
| 36" FLGXPE DIP 4" | 1 | EA | 5 | 7,641.18 | 5 | 7,641.18 |
| 36" FLGXFLG DIP 7" | 2 | EA | 5 | 8,089.41 | \$ | 16,178.82 |
| 36" MEGA FLANGE REST ADPT | -1- | EA. | 5 | 3,708,38 | 5 | 3,708.38 |
| 36" FLG 90 BEND | 2 | EA | 5 | 14,002.40 | 5 | 28,004,80 |
| 36" FLG ACC KIT NEOPRENE | 1,0 | EA | 5 | 1,158.83 | 5 | 11,588.30 |
| 36" FLG PLUG VALVE W/GEAR | 1 | EA | 5 | 49,916.85 | 5 | 49,916.85 |
| 36" FLG CHECK VALVE | 1 | EA | 15 | 48,348.31 | 5 | 48,348.31 |
| 2"BALL CORP | 1 | EA. | - 5 | 315.00 | 5 | 315.00 |
| 2" X 4" 55 NIPPLE | 1 | EA | \$ | 14.00 | .5 | 14.00 |
| 36"X2" DBL STRP SS | 1 | EA. | 5 | 720.00 | 5 | 720.00 |
| 2" SEWAGE AIR RELEASE VLV | -1 | EA. | 5 | 1,040.00 | 5 | 1,040.00 |
| 42" MI LONG SLEEVE | 1 | EA | 5 | 8,338.99 | 5 | 8,338,99 |
| 42" MEGALUG DIP W/ACC | 10 | EA | 5 | 2.417.08 | 5 | 24,170.80 |
| 42" MJ 45 BEND | 1 | EA. | 5 | 11,719.18 | 5 | 11,719.18 |
| 42" X 35" MLTEE | 1 | EA | 5 | 19,636,05 | 5 | 19,635.05 |
| 36" MEGALUG DIP W/ACC | 15 | EA | 5 | 1,693.30 | 5 | 8,466.50 |
| 36" MJ 90 BEND | 1 | EA. | 5 | 9,596.14 | 5 | 9,596.14 |
| 36" MJ PLUG VALVE | 1 | EA | 5 | 50.939.33 | 5 | 50,939.33 |
| ALC MAY PENG VALVEY | 1 | EA. | 5 | 103,264,00 | 5 | 103,264.00 |
| 72" ARV MANHOLE / TOP SLAB | 1 | EA | 5 | 2,648.00 | 5 | 2,648,00 |
| 690-AH-M PL R/C | 1 1 | EA | 5 | 4,225.00 | 5 | 4,225.00 |
| SUBTAX | | | 15 | 50.00 | 5 | 50.00 |
| SUBTOTAL | | | | | 5 | 420,467.87 |
| TAXES | | | | | 5 | 25,278.07 |
| TOTAL MATERIAL | | | | 1.1 | 5 | 445,745.94 |

| SUBCONTRACTORS COSTS | | | | | | |
|------------------------------|-----|------|-----------|-----------|------------|------------|
| Description | QTY | Unit | Unit Cost | | Total Cost | |
| CMA | 1 | LS | 5 | 62,400.00 | 5 | 62,400.00 |
| A&N Brothers Concrete | 1 | 15 | 5 | 7,600.00 | 5 | 7,600.00 |
| SUPERMIX Flowable Fill 18 CY | 1 1 | LS | 5 | 3,228.40 | 5 | 3,228,40 |
| Rangeline (IF NEEDED) | 1 | 1.5 | 5 | 50,096.00 | 5 | 50,096.00 |
| MW PUMPS (IF NEEDED) | 1 | 1.5 | 5 | 3,656.21 | 5 | 3,656.21 |
| TOTAL SUBCONTRACTOR | | | | | 5 | 126,980.61 |
| | | | | | | |

Where is the ARV and manhole?

-ARV MH TOP SLAB WITH RIM AND COVER FOR LINESTOP IN DRIVEWAY



P12383 & P12384 – CORAL RIDGE FORCE MAIN REPLACEMENT PROJECT

LABOR BURDEN BREAKDOWN

- A. 6.20 % SOCIAL SECURITY RATE
- B. 1.45 % MEDICARE RATE
- C. 5.49 % UNEMPLOYMENT
- D. 7.16 % WORKERS COMP
- E. 4.35 % GENERAL LIAB
- F. 14.20 % HEALTH INS
- G. 23.70 % RETIREMENT
 - H. 13.00 % VAC/HOLIDAY

Burden Rate: 75.55%

DMSI offers our employees the following paid-off time:

- (2) Weeks Paid Vacation
- (3) Weeks Holiday paid, including time between Christmas and New Year
- (1) Week for Sick Time

Based on this, a DMSI employee works 46 weeks a year and gets paid for 52. Therefore, the yearly burden for General Liability, Health Insurance, Retirement, and vacation Holiday Time must be INCREASED based on the calculation below to cover the six non-revenue weeks (for DMSI), whereas DMSI compensates the employee.

Items A-C Above are standard rates through the federal government and the State of Florida.

Item D – Is DMSI's Workman's Comp rate for Sewer when this project was bid and the Contract executed.

Item E – Is DMSI's G/L rate (1.89%) plus 2.46% to cover the non-revenue paid weeks (See Below) (\$21.87x40x6=\$5,248.80x1.89%=\$992.02/\$21.87x40x46 or an additional 2.46%)

Item F – Insurance burden is calculated using the average hourly employee rate multiplied by 40/hrs. per week for 46 weeks worked, dividing this by the average cost of yearly insurance premiums for hourly employees. (Average hourly rate \$21.87x 40 hours x 46 weeks/year divided by the average cost of SGL coverage 476.18/mo. x 12)

Item G - (RETIREMENT 11% + Bonus, which is merely part of the employee's yearly compensation package, of 10% plus the average hourly rate \$21.87 x 40 x 6 weeks non-working = \$5,248.80, we pay 21% of this income as retirement benefit so we need to add \$1,102.25 to 46 weeks of working to cover these costs or an additional 2.7%)



ITEM H - (6weeks/46weeks of working to cover costs of vacation and holiday)

By signing below, I certify that the information provided is true and correct to the best of my knowledge.

Sincerely,

Fabio Angarita

Vice president

David Mancini and Sons, Inc.


Note:


Our financial statement is proprietary and confidential, so we do not wish it to be made public. Our records are available for your appropriate staff to review at our Pompano Beach, FL office.


Please advise us 48 hours in advance.


If you have any questions about our financial information, please call our Financial Controller, Kimberley Weldon, at (954) 977-3556.

|) | Task Name | Duration | Start | 25 Jul 6, 25 Jul 20, 25 Jul 20, 25 Jul 20, 25 M T W T F S S M T W T F S S M T W T F S S M T W |
|----|--|----------|-------------|---|
| 1 | Repump connection with bypass | 15 days | | |
| 2 | Mobilization | 1 day | Mon 7/7/25 | Mobilization > 7/7 |
| 3. | Linestops and Bypass installation | 1 day | Mon 7/7/25 | Linestops and Bypass installation |
| 4 | linestops setup | 1 day | Tue 7/8/25 | linestops setup |
| 5 | 42" Pipe Connection | 1 day | Tue 7/8/25 | 42" Pipe Connection |
| 6 | Removal of existing bypass | 2 days | Wed 7/9/25 | Removal of existing bypass *********************************** |
| 7 | Bypass assembly | 3 days | Fri 7/11/25 | 1 |
| 8 | Installation of 36" plug valves | 1 day | Fri 7/11/25 | Installation of 36" plug valves |
| 9 | Installation of 36" check valve | 1 day | Mon 7/14/25 | Installation of 36" check valve |
| 10 | Installation of 36" pipe and fitting | 1 day | Tue 7/15/25 | Installation of 36" pipe and fitting |
| 11 | Excavation | 1 day | Wed 7/16/25 | Excavation |
| 12 | Flowable fill | 1 day | Thu 7/17/25 | Flowable fill Z |
| 13 | Form and pour reinforced concrete footer | 2 days | Fri 7/18/25 | Form and pour reinforced concrete footer |
| 14 | Form and pour concrete pipe supports | 2 days | Tue 7/22/25 | Form and pour concrete pipe supports |
| 15 | Roadway build-up | 2 days | Thu 7/24/25 | Roadway build-up |
| 16 | Demobilization | 1 day | Mon 7/28/25 | Demobilization 7/28 |











All prices shown in US Dollars (\$)


Rental Rate Blue Book*

February 6, 2024

Caterpillar 308E2 CR (disc. 2020)

Crawler Mounted Hydraulic Excavators

Size Class: 6.5 - 8.4 mt Weight: N/A



Configuration for 308E2 CR (disc. 2020)

Horsepower 65.0 hp Operating Weight 18519 lbs
Power Mode Diesel

Blue Book Rates

** FHWA Rate is equal to the monthly ownership cost divided by 176 plus the hourly estimated operating cost.

| | | Ownership Costs | | | Estimated Operating Costs | FHWA Rate** |
|--|----------------|-----------------|--------------|-------------|------------------------------|-------------|
| | Monthly | Weekly | Daily | Hourty | Hourty | Hourty |
| Published Rates | USD \$6,930 00 | USD \$1,940.00 | USD \$485.00 | USD \$73.00 | USD \$28.76 | USD \$58.1# |
| Adjustments | | | | | 1000 | |
| Region (100%) | 100 | - | | - | 7-2 | |
| Model Year (2020: 100%) | | | | 3.00 | | |
| Adjusted Hourly Ownership Cost (100%) | - | - | 8 | 375 | | |
| Hourly Operating Cost (1004b) | | | | | 100000 | |
| Total: | USD \$6,930.00 | USD \$1,940.00 | USD \$485.00 | USD \$73.00 | USD \$28.76 | USD \$68.14 |

 Non-Active Use Rates
 Hourly

 Standby Rate
 USO \$21.66

 Idling Rate
 USD \$46.22

Rate Element Allocation

| the Table | A 2 4 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 | 0.10 |
|-----------------------------|---|-------------------|
| Element | Percentage | Value |
| Depreciation (ownership) | 30% | USD \$2,079 00/mu |
| Overhaul (ownership) | 45% | USO \$3,118.50/mo |
| CFC (ownership) | 15% | USD \$1,039,50/ma |
| Indirect (ownership) | 10% | USD \$693,00/mo |
| Fuel (operating) @ USD 4.15 | 23.78% | USD \$6.84/hr |

Revised Date: 1st quarter 2024

These are the most accurate rates for the selected Revision Date(s). However, due to more frequent online updates, these rates may not match Rental Rate Blue Book-Print. Visit the Cost Recovery Product Guide on our Help page for more information.

The equipment represented in this report has been exclusively prepared for DAVID MANCINI (dinancinijr@dmsi.co)



All prices shown in US Dollars (\$)


Rental Rate Blue Book*

February 6, 2024

Caterpillar 325

Crawler Mounted Hydraulic Excavators

Size Class 21.5 - 24.4 mt Weight:



Configuration for 325

Bucket Capacity 1.2 cu.yd Horsepower 174 hp
Operating Weight 49604 lbs Power Mode Diesel

Blue Book Rates

** FHWA Rate is equal to the monthly ownership cost divided by 176 plus the hourly estimated operating cost.

| | | Ownership | Costs | | Estimated Operating Costs | FHWA Rate** |
|--|-----------------|----------------|----------------|--------------|------------------------------|-----------------------|
| | Monthly | Weekly | Daity | Hourly | Hourty | Hourty |
| Published Rates | USD \$14,760.00 | USD \$4,135.00 | USD \$1,035.00 | USD \$155.00 | USD \$49.38 | USD \$133.24 |
| Adjustments | | | | | F-20- | |
| Region (100%) | 100 | 1 | - | 1 | 12-20 | |
| Model Year (2024: 100%) | 100 | 8 | - | 7 | | |
| Adjusted Hourly Ownership Cost (100%) | ~ | - | | - 98 | | |
| Hourly Operating Cost (100%) | | | | | 100 | The second section is |
| Total: | USD \$14,760.00 | USD \$4,135.00 | USD \$1,035.00 | USD \$155.00 | USD \$49.38 | USD \$133.24 |

 Non-Active Use Rates
 Hourly

 Standby Rate
 USD \$46,13

 Idling Rate
 USD \$97,70

Rate Element Allocation

| Element | Percentage | Value |
|-----------------------------|------------|---------------------|
| Depreciation (ownership) | 30% | USD \$4,428 00/ma |
| Overhaul (ownership) | 45% | USD \$6,642.00/mio. |
| CFC (ownership) | 15% | USD \$2,214,00/mg |
| Indirect (ownership) | 10% | USD \$1,476.00/ina |
| Fuel (operating) @ USD 4.15 | 28.03% | USD \$13,84/hr |

Revised Date: 1st quarter 2024

These are the most accurate rates for the selected Revision Date(s). However, due to more frequent online updates, these rates may not match Rental Rate Blue Book® Print. Visit the Cost Recovery Product Guide on our Help page for more information.

The equipment represented in this report has been exclusively prepared for DAVID MANCINI (dinancinijr@dmsi.co)



All prices shown in US Dollars (\$)

Rental Rate Blue Book*

February 6, 2024

Caterpillar 938M

4-Wd Articulated Wheel Loaders

Size Class 175 - 199 hp Weight N/A



Configuration for 938M

Horsepower 168.0 hp Operator Protection ROPS/FOPS
Power Mode Diesel

** FHWA Rate is equal to the monthly ownership cost divided by 176 plus the hourty estimated operating cost.

Blue Book Rates

Ownership Costs Estimated Operating FHWA Rate* Costs Monthly Weekly Daily Hourly Hourty Hourty **Published Rates** USD \$6,410.00 LISD \$1,795.00 USD \$450,00 USD \$68.00 USD \$29.00 USD \$85,42 Adjustments Region (100%)

 Non-Active Use Rates
 Hourly

 Standby Rate
 USD \$24.77

 Idling Rate
 USD \$49,38

Rate Element Allocation

| Element | Percentage | Value |
|-----------------------------|------------|--------------------|
| Depreciation (ownership) | 39% | USD \$2,499.90/ma |
| Overhaul (ownership) | 32% | USD \$2,051.20/ma |
| CFC (ownership) | 18% | USD \$1,153,90/mo. |
| Indirect (ownership) | 11% | USD \$705,10/mg |
| Fuel (operating) @ USD 4.15 | 44,69% | USD \$12,96/hr |

Revised Date: 1st quarter 2024

These are the most accurate rates for the selected Revision Date(s). However, due to more frequent online updates, these rates may not match Rental Rate Blue Book® Print. Visit the Cost Recovery Product Guide on our Help page for more information.

The equipment represented in this report has been exclusively prepared for DAVID MANCINI (dmancinijr@dmsi.co)



All prices shown in US Dollars (\$)

Rental Rate Blue Book*

February 6, 2024

GMC\CHEVY 2500

On-Highway Light Duty Trucks

Size Class: 300 hp & Over Weight: N/A



Configuration for 2500

Axle Configuration 4.0 x 2.0 Horsepower 310.0 hp Ton Rating 3.0 / 4.0 Cab Type Power Mode

Crew Diesel

Blue Book Rates

** FHWA Rate is equal to the monthly ownership cost divided by 176 plus the hourly estimated operating cost

| | | Ownership Costs | | | | FHWA Rate** |
|--|--------------|-----------------|-------------|------------|-------------|-------------|
| | Monthly | Weakly | Daily | Hourly | Hourty | Hourly |
| Published Rates | USD 5710,00 | USD \$200.00 | USD \$50,00 | USD \$8,00 | USD \$19.36 | USD \$23.39 |
| Adjustments | | | | | | |
| Region (100%) | 2-4 | 140 | - | 4.5 | | |
| Model Year (2024: 100%) | | | | | | |
| Adjusted Hourly Ownership Cost (100%) | ~ | ~ | - | 1755 | | |
| Hourly Operating Cost (100%) | | | | | | |
| Total: | USD \$710.00 | USD \$200.00 | USD \$50.00 | USD \$8.00 | USD \$19.36 | USD \$23.39 |

 Non-Active Use Rates
 Hourly

 Standby Rate
 USD \$2.66

 Id=ng Rate
 USD \$19.45

Rate Element Allocation

| Element | Percentage | Value |
|-----------------------------|------------|-----------------|
| Depreciation (ownership) | 35% | USD \$248.50/mg |
| Overhaul (ownership) | 34% | USD \$241.40/mg |
| CFC (ownership) | 13% | USD \$92.30/ma |
| Indirect (ownership) | 18% | USD \$127.80/mg |
| Fuel (operating) @ USD 4.15 | 79 65% | USD \$15.42/hr |

Revised Date: 1st quarter 2024

These are the most accurate rates for the selected Revision Date(s). However, due to more frequent online updates, these rates may not match Rental Rate Blue Book* Print. Visit the Cost Recovery Product Guide on our Help page for more information.

The equipment represented in this report has been exclusively prepared for DAVID MANCINI (dmancinijr@dmsi.co)



All prices shown in US Dollars (\$)

Rental Rate Blue Book*

February 6, 2024

Sullair 375HDPQCA

Portable Rotary Screw Air Compressors

Size Class: 250 - 599 cu ft/min Weight: 4150 lbs



Configuration for 375HDPQCA

Air Delivery Rating Power Mode 375.0 cu ft/min Diesel Horsepower

130.0

Blue Book Rates

** FHWA Rate is equal to the monthly ownership cost divided by 176 plus the hourly estimated operating cost.

| | | Ownership (| Ownership Costs | | Estimated Operating Costs | FHWA Rate** |
|--|----------------|----------------|-----------------|-------------|------------------------------|-------------|
| | Monthly | Weekly | Daity | Hourly | Hourty | Hourly |
| Published Rates | USD \$4,235.00 | USD \$1,185.00 | USD \$295.00 | USD \$44.00 | USD \$35.74 | USD \$59.80 |
| Adjustments | | | | | | 7.00 |
| Region (100%) | · · | - | | 100 | | |
| Model Year (2024: 100%) | 0 | 100 | - | 10.27 | | |
| Adjusted Hourly Ownership Cost (100%) | - | - | - | 100 | | |
| Hourly Operating Cost (100%) | | | | | town 18 | Carried I |
| Total: | USD \$4,235.00 | USD \$1,185,00 | USD \$295.00 | USD \$44.00 | USD \$35.74 | USD \$59.80 |

| Non-Active Use Rates | Hourly |
|----------------------|-------------|
| Standby Rate | USD \$7.94 |
| Idling Rate | USD \$43,46 |

Rate Element Allocation

| Percentage | Value |
|------------|----------------------------|
| 15% | USD \$635.25/mg |
| 67% | USD \$2,837.45/mg |
| 1096 | USD \$423.50/mg |
| 8% | USD \$338.60/mm |
| 54 28% | USD \$19,40/hr |
| | 15%6 67% 10%6 8%6 |

Revised Date: 1st quarter 2024

These are the most accurate rates for the selected Revision Date(s). However, due to more frequent online updates, these rates may not match Rental Rate Blue Book® Print. Visit the Cost Recovery Product Guide on our Help page for more information.

The equipment represented in this report has been exclusively prepared for DAVID MANCINI (dmancinijr@dmsi.co)

All American Precast

1300 NW 4 Street Homestead, FL 33030 US +13054182795 ADMIN@ALLAMERICANPRECAST.COM www.allamericanprecast.com



Estimate

ADDRESS

DAVID MANCINI & SONS INC

2601 Wiles Road

Pompano Beach, FL 33073

SHIP TO

CITY OF FT LAUDERDALE

PROJECT # 12384

NE 38th ST 42-INCH FM

MAIN REPLACEMENT

FORT LAUDERDALE FL

P.O. NUMBER FLGOLF-06 SALES REP

Al

ESTIMATE # 12206D1 DATE 08/07/2024

JOB NAME

PROJ 12384 NE 38th ST

| ACTIVITY | QTY | RATE | AMOUNT |
|---|-----|----------|------------|
| 60" RD ARV MANHOLE 60" RD ARV MANHOLE W/ TOP SLAB & USF # 690-AH-M "CITY OF FT LAUDERDALE ARV SEWER" R/C. | 7 | 6,378.00 | 44,646.00T |
| Castings NAME CHANGE "CITY OF FT LAUDERDALE" ARV SEWER ON LID. | 1 | 2,500.00 | 2,500.00 |
| Castings 60" RD ARV MANHOLE W/ TOP SLAB. Add on 05/09/2024 | 2 | 2,153.00 | 4,306.00T |
| 72" RD ARV MANHOLE 72" RD ARV MANHOLEW/ TOP SLAB. | .3 | 2,648.00 | 7,944,00T |
| Castings TEMP "M" COVERS | 12 | 150.00 | 1,800.00 |
| Castings 690-AH-M PL R/C. | 5 | 4,225.00 | 21,125.00 |
| 02 Delivery included. Any paint / coatings not quoted. Casting lead time 6 to 8 weeks. Ram-nek \$90 per box as needed. | 1 | 0.00 | 0.00 |
| Note: All American Precast Manufacturing, Corp is a material supplier. We are to be paid per invoice or statement, not per customer's contract draws. | 1 | 0.00 | 0.00 |
| | | | |

1.Proposals are valid for up to 30 calendar days, pricing may be subject to change after 30 days. All American Precast manufacturing, Corp reserves the right to withdraw proposal, Engineering fees if required must be requested.



01/14/25 Date

Customer David Mancini & Sons

2601 Wiles Rd

Deerfield Beach, 33073

Project Coral Ridge Bypass

TBD

Ryan Kaltz Contact Phone 954-826-8639 Rkaltz@Dmsi.co Email

Term 4 week

PO: Pending

| Qty | ltem | Day | Week | 4 Week | 4 week |
|-----|-----------------------------|---------|---------|----------|------------|
| 100 | 24" Steel Pipe Per Ft | \$1.67 | \$5.00 | \$15.00 | \$1,500.00 |
| 3 | 24" Flange Fibow 90 | \$27.78 | \$83.33 | \$250.00 | \$750.00 |
| 1 | Misc. Nuts, Balts, Silicone | 519.44 | \$58.33 | \$175.00 | \$175.00 |

TOTAL RENTAL

\$2,425.00

| Services | ltern . | Price | Total |
|----------|----------|----------|----------|
| 2 | Delivery | \$250.00 | \$500.00 |
| 2 | Pick up | \$250.00 | \$500.00 |

\$1,000.00 Services Total

> Subtotal \$3,425.00

Env. Fee \$24.25 **Estimated Tax** \$206.96 Estimated Total* \$3,656.21

*This is an estimate. Actual site conditions can vary which may effect

the final pricing.

Customer Responsibilities:

Point of discharge.

Fueling, unless otherwise noted by contractor...

Power source, materials and labor for electric units.

Heavy equipment for loading , unloading, set up and tear down of equipment (U.O.N)

Discharge Permit and fees.

Monitoring of Dewatering Equipment

Ballast Rock for turbidity control and stability if needed.

Cleaning of sediment tank's



FEL-POMPANO BEACH WW #125 1950 NW 18TH STREET POMPANO BEACH, FL 33069-1394

Phone: 954-973-8100 Fax: 954-917-3134 Deliver To:

From: Matt Briggle

matt.briggle@ferguson.com

Comments:

Page 1 of 2

22:05:49 OCT 02 2024

FEL-POMPANO BEACH, FL WW #125

Price Quotation Phone: 954-973-8100 Fax: 954-917-3134

Bid No: B574476

Bid Date:

Quoted By:

Customer:

10/02/24 MB

MB.

DAVID MANCINI & SONS INC.

2601 WILES ROAD

CORAL RIDGE FM REPLACEMENT POMPANO BEACH, FL 33073 Cust Phone: 954-977-3556

Terms: NET 10TH PROX

Ship To: DAVID MANCINI & SONS INC.

2601 WILES ROAD

CORAL RIDGE FM REPLACEMENT POMPANO BEACH, FL 33073

Cust PO#: Job Name: CORAL RIDGE FM REPLACEMEN

| em | Description | Quantity | Net Price | UM | Total |
|---------------------------------------|--------------------------------|----------|------------|-----|-----------|
| JLSP4LA42 | 42 MJ C153 P-401 LONG SLV L/A | 1 | 8338.990 | EA | 8338.99 |
| J4P4LA42 | 42 MJ C153 P-401 45 BEND L/A | 1 | 11719.180 | EA | 11719.18 |
| 118MJ36 | 36 MJ N/LUBE PLUG VLV L/A | 1 | 50939,330 | EA | 50939.33 |
| MJPLUGVLV42 | 42 MJ PLUG VALVE - SEE SPEC | 2 | 103264.000 | EA. | 206528.00 |
| MJTLA4236 | 42X36 MJ TEE C153 CL | 1 | 19636.050 | EA | 19636.05 |
| P4LA36 | 36 MJ C153 P-401 90 BEND L/A | 1 | 9596,140 | EA | 9596,14 |
| PP436P | 36X4'0 FLGXPE P-401 BT DI SPL | 2 | 7641.180 | EA. | 15282.36 |
| P436K | 36X2'0 FLGXFLG P-401 BT DI SPL | 2 | 8089.410 | EA | 16178.82 |
| PP436U | 36X6'0 FLGXPE P-401 BT DI SPL | -4 | 9988,240 | EA | 9988,24 |
| 3600 | 36 MEGAFLANGE FLG ADPT | 2 | 3708,380 | EA. | 7416.76 |
| 436 | 36 DI 125# FLG P-401 90 BEND | - 2 | 14002:400 | EA | 28004.80 |
| F36PV | 36 FLG PLUG VLV | 1 | 49916,850 | EA | 49916.85 |
| FCV36 | 36 FLG CHK VLV | . 1 | 48348,310 | EA | 48348.31 |
| E42 | 42 DI MJ WDG RTNR GLAND 'ONEL | 10 | 2417.080 | EA | 24170.80 |
| DE36 | 36 DI MJ WDG REST GLND 'ONELO | 5 | 1693,300 | EA | 8466,50 |
| | 36 SS FLG ACC SET | 10 | 1158,830 | EA | 11588.30 |
| | ARV | | | | |
| A A A A A A A A A A A A A A A A A A A | 36X2 IP DBL STRP SS EPOX SDL | 1 | 720,000 | EA | 720,00 |
| 17007NL | LF 2 MIP X FIP BALL CORP | 4 | 315.000 | EA | 315.00 |
| | 2 SEWAGE AIR RELEASE VLV | 1 | 1040.000 | EA. | 1040.00 |
| NKP | 2X4 SS S40 316L WLD NIP | 1 | 14.000 | EA | 14.00 |

Net Total: \$528208.43 Tax: \$31742.51 Freight: \$0.00 Total: \$559950.94



500 West Cypress Creek Road, Suite 600

Fort Lauderdale, FL 33309 Office: +1 (954) 730-0707



December 12th, 2024

Fabio Angarita David Mancini & Sons, Inc. 2601 Wiles Road Pompano Beach, FL 33073

Subject:

City of Fort Lauderdale

P12384 Coral Ridge Force Main - Phase 4 RCO #2 - 36-inch Bypass at Repump B

Dear Mr. Angarita,

During the design of the force main in Phase 4 of the City of Fort Lauderdale Force Main Project (P12384), the City of Fort Lauderdale has requested that DMSI replace the existing 36-inch aboveground bypass at Repump B. The work required to install a new bypass necessitates additional design and inspection services from CMA that were not included in the original Design Citeria Package (DCP).

As requested by the City of Fort Lauderdale, CMA will include in our Phase 4 submittal plans a detailed design encompassing all necessary piping, valves, connection points, and pipe supports to meet City standards. This design will also incorporate the above-ground bypass under the same permit. Additionally, CMA will provide restoration design plans for all areas impacted during the construction of the bypass. To support the construction process, CMA will provide an inspector onsite during the installation of the 36-inch above-ground bypass. This request also includes the redesign of the connection location to the existing 42-inch influent line at the Master Repump station as discussed in the field with City staff.

Please note that CMA will not perform any modeling or flow calculations as part of this work. The design plans will incorporate the existing system and be replaced in kind.

This additional scope of work has resulted in unanticipated costs for CMA related to the design and construction inspection of the bypass and new connection locations to the existing force main system The estimated total cost for these additional services is \$62,400.

Please feel free to contact me if you have any additional questions at +1 (561) 744-8282 or via email at vlocigno@chenmoore.com.

Respectfully submitted,

Vincent Locigno

Chen Moore and Associates Vincent Locigno, PE Project Engineer



Rangeline will provide the following Material:

| Quantity | Description | Unit Price | Total |
|----------|--|------------|------------|
| 1 | Night Work Option for the 42" Double Line stop Service | \$9,545,00 | \$9,545.00 |
| 4 | Night Work Option for the 42" Double Re-Stop Service | \$5,574.00 | \$5,574.00 |

Rangeline Group will perform the following Double Line Stop:

| Quantity | Size | Pipetype | Product | Double Line Stop With Bypass | Total | Line Stop Equipment Overnight charges after 7PM on 5th Day "When Equipment is on the Pipe" |
|----------|------|----------|------------|------------------------------------|-------------|--|
| 1-1 | 42" | Dí. | Force Main | \$84,520,00 | \$84,520.00 | \$1,500.00 Per Day, Per Line Stop |

Rangeline Group will perform the following Double Re-Stop:

| Quantity | Size | Pipetype | Product | Double Re- Stop With Bypass | Total | Line Stop Equipment Overnight charges after 7PM on 5th Day "When Equipment is on the Pipe" |
|----------|------|----------|------------|-----------------------------------|-------------|--|
| 1 | 42" | DI | Force Main | \$44,522.00 | \$44,522.00 | \$1,500.00 Per Day, Per Line Stop |

PLEASE NOTE: Rangeline will make every attempt to remove the completion plug and re-insert the line stopper. Ihrough. The existing fitting. If the completion plug cannot be removed, the existing line stop fitting will have to be abandoned and a new line stop fitting and location will be needed in order to shut the system down.

Note: Rangeline cannot guarantee a 100% shutdown due to debris, mineral deposits, solids and/or sediments in the pipe.

Prices are based on the following below:

- Rangeline will provide epoxy coated linestop fittings with stainless steel hardware for the double linestop services, and use existing and serviceable linestop fittings for the double re-stop services.
- If the project is cancelled after NON-AIS(standard) materials are ordered, there will be a restocking fee.
- Rangeline will provide (2) 24" 150# flanged outlets for customer to connect Bypass Piping to the 42" double line stop or double re-stop sets. Customer must provide and install all Bypass Piping and related materials.
- When equipment is placed on the pipeline system, whether the Re-Stop is in the main or not, per day charges will apply.
- Please allow (7 14 days) notice for scheduling after receipt of materials to ensure availability. Projects that
 require shorter lead times may incur additional charges.
- Contractor must encase each line stop fitting in concrete.
- If the type of pipe changes from what we have quoted above, prices and scheduling may vary. Contractor or Municipality is responsible for verifying the type of pipe and it's O.D.
- Rangeline may require a pre-construction meeting or site visit prior to scheduling any services.
- Normal daytime hours (7:00AM- 7:00 PM EST) Monday through Friday. Technician(s) will have a \$375.00 per hour after hours charge, portal-to-portal. Additional Expenses will be charged at our cost plus 20%.
- Rangeline will allow (3) Mobilizations/De-Mobilizations to the jobsite per double line stop and (2) Mobilizations/De-Mobilizations to the jobsite per double re-stop. Additional trips will be \$750.00 per trip. Mobilization charges are applied when the technician leaves the shop or jobsite to start or after completion of the project.

Rangeline Tapping Services
7256 Westport Place Ste A West Palm Beach, FL 33413



A & M Brothers Concrete Corp.

95 NE 12 Street Homestead Fl, 33030 Phone: (786) 296 5979 a.m.concrete@hotmail.com PROPOSAL / CONTRACT
PROPOSAL VALID FOR 90 CALENDAR DAYS
CALENDAR DAYS
Date: FEBRUARY 04, 2025

CONTRACTOR: DAVID MANCINI & SONS INC.

Attn: Alejandra Suarez Email: ASuarez@dmsi.co PHONE: (786)-284-2268 COUNTY: BROWARD

PROJECT NAME: CORAL RIDGE ABOVE GROUND PIPE SUPPORT

| Item | Description | Unit | Unit price | Quantity | Total Amount |
|---------|--|---------|--------------------|--|--------------|
| 1 | 5' X 18" ABOVE GROUND PIPE SUPPORT WITH #5 REBAR 12" ON CENTER TOP AND BOTTOM EACH WAY | EACH | \$ 3,800.00 | 2 | \$ 7,600.00 |
| | Note: Final Invoice base on Field measurements | | TOTAL | | \$ 7,600.00 |
| P | RICE INCLUDES LABOR, MATERIALS, EQUIPMENT A | ND 3,00 | 0 REG OR 2,5 | 00 DOT PSI | CONCRETE |
| | ffice, Inspections, Concrete Cylinder Test are NOT Included | | ance of Traffic NC | | |
| | terials, Grading and Base Preparation are NOT Included | | out/As Built NOT | 27-27-27-20- | |
| Lime ro | ock Base and Subgrade are NOT Included. | | Pump are NOT I | The state of the s | |

PAYMENT TO A & M Brothers Concrete Corp. is due within 30 days of receipt of this invoice. Any payment not received timely, shall be subject to interest at the rate of 1.5 % per month. In the event of legal action is required to enforce this invoice, A & M Brothers Concrete shall be entitled to recover its attorneys' fees and costs.

ACCEPTANCE OF PROPOSAL/CONTRACT:

DAVID MANCINI & SONS

Signature

| The above prices, specifications and conditions are specified. Payment will be made as outlined above | satisfactory and are hereby accepted. You are authorized to do the wor | k as |
|--|--|------|
| Date | Name / Title | |
| | | |

CONFIDENTIAL







| SNO WZZOCIWA | | PREMIER PE | RODUCER |
|----------------|--|---------------------------------------|------------|
| Customer Name | David Mancini & Sons - Alejandra Suarez | Phone: 954-97 | 7-3556 |
| Address | 2601 Wiles Road, Pompano Beach, FL 33073 | Fax: | |
| Project Name | Coral Ridge FM Replacement - Proj 23-FL.GOLF | Cell: 305-775-5340 asuarez@dmsi.co | |
| Address | NE 50th Court & 15th Ave, Ft Lauderdale, 33334 | | |
| Mix Code | Description | U,O.M. | Price |
| | * As Requested * | | |
| 06-FF-95 | FDOT FLOWABLE FILL EXCAVATABLE 100 PSI | Cubic Yard | \$173.00 |
| | | | |
| | | | |
| | SERVICE CHARGES | | |
| | Environmental Load Charge | Load | \$25.00 |
| Currently | FUEL SURCHARGE - ADJUSTED WEEKLY 1/16/2025 | Load | \$32.20 |
| :00am-12:30pm | Saturday Delivery Charge | Cubic Yard | TBD |
| :00 pm-6:00 am | Plant Opening 4-HR Minimum Monday - Friday | FLAT | TBD |
| SHORT257 | Minimum Load Charge - Less than 7 CY | Load | \$250.00 |
| | Return Concrete Handling & Disposal Fee | Cubic Yard | \$35.00 |
| | Order Cancellation Fee | FLAT | \$1,500.00 |
| 1/6/2025 | Effective Date | Expiration Date | 3/31/202 |
| Escalation | TBD 7/1/2025 | | |

Supermix at all times reserves the right to increase the quoted prices without notice that reflect an increase in raw material costs, changes in market conditions, or surcharges incurred by Supermix, and to cancel or defer any quote in the event Supermix becomes delayed or prevented by shortages or allocations of raw materials. Supermix shall not be liable to Buyer, any of its counterparties, or any third parties for damages as a result of any such price change, delay, or cancellation.

| Supermix | Peter Kaczorowski | Office: 954.480.9333 | .9333 Cell: 954.214.4937 893 Email: <u>pete@supermix.com</u> | |
|----------------|-------------------|----------------------|---|--|
| Representative | Account Manager | Fax: 954.480.2893 | Email: <u>pete@supermix.com</u> | |

Accepted by: Date:

City of Fort Lauderdale

NE 38th Street 42-Inch FM and NE 19th Avenue 24-Inch FM Replacement.

Submittal Name: SHOP DRAWINGS - CHECK VALVE



| Date of Submission | 12/6/2024 |
|---|--|
| 2. Project Number | P12384 |
| 3. Project Name | NE 38th Street 42-Inch FM and NE 19th Avenue 24-Inch FM Replacement |
| Contractor Identification | 23-FL.GOLF-001 |
| a. Contractor | David Mancini and Sons, Inc |
| b. Supplier | |
| c. Manufacturer | N/A |
| d. Manufacturer or supplier representative | N/A |
| 5. Identification of the Product | EXB-12.0-P12384-02-1 |
| 6. Reference to Confract Drawing | D02 |
| Reference to Specification Section Number, page and paragraphs. | Technical Specifications 2.03 |
| 8. Indication of Contractor's approval. | Approved by DMSI |
| Contractor's Certification Statement. (Refer to paragraph 1.03.F.2) | "By this submittal, I hereby represent that I have determined and verified all field measurements, field construction criteria, materials, dimensions, catalog numbers and similar data and I have checked and coordinated each item with other applicable approved sho drawings and all Contract requirements." |
| 10. Identification of deviations from the Contract, if any. | |
| 11. Reference to previous submittal (for resubmittals). | |





AWWA C508 Swing Check Valves

Index

| Brochure | 1 |
|--|---|
| Design Standards | 3 |
| Pressure vs Temp Ratings | 4 |
| Technical Drawings | |
| 2"-48" Swing Check Valve AWWA C508 | |
| Standard Material of Construction Rubber Seated | 6 |
| Flanged w/ Outside Lever & Weight CVI Dimensions | 7 |
| 36" Check Valve Drawing with Materials | 8 |







2"-48" CVI BONDED SEAT SWING CHECK

BONDED SEAT SWING CHECK VALVE


VSI offers the simplified bonded seat type check valve for pump and lift stations where a standard duty valve is acceptable and external accessories are not required. It still exemplifies VSI's commitment to providing a quality product.

- Body seats are permanently bonded nonreplaceable, reducing possible leakage paths.
- Disc seats are replaceable by way of replacing the entire disc.
- The shaft extends only to one side, reducing seal friction and possible leakage paths.




SIMPLE INTERNALS

VSI Bonded Seat Swing Check Valves are built with simplicity in mind for use in general duty applications. They feature minimal internal hardware and robust coatings for long service life in many less demanding applications.



REPLACEABLE DISC

VSI Swing Check Valves incorporate a replaceable bonded seat, which can be removed without taking the valve out from the line. Simply remove the sealed cover, and change out the entire disc.



CAM #25-0539

Exhibit 4 V5: Waterworks Page 95 of 205 1015 Alpha Orive, Alpharetta, GA 30004 T 770-740-0800 F: 770,740,8777 E: sales@vsiwaterworks.com



DESIGN STANDARDS

| Size Range | 6"-48" Flanged End | |
|-----------------|---------------------------|--|
| Construction | AWWA C508 | |
| | ASME B16.34 | |
| | AP1 600 | |
| Coatings | AWWA C550* | |
| Connections | ANSI B16.1 Class 125* | |
| | ANSI B16.1 Class 250 | |
| | ANSI B16.5 Class 150 | |
| | ANSI B16.5 Class 300 | |
| Lay Length | AWWA C508 Appendix A Full | |
| | 150 5752 | |
| Classifications | 150 PSIG | |
| | 175 PSIG | |
| | 200 PSIG* | |
| | 250 PSIG* | |

^{*}Standard Option






RESISTANCE GUIDE

| Designation | Common Names | Composition | Min/Max Temperature Range | General Properties | Resistant to: | Attached by: |
|-------------|---------------|---|------------------------------|--|---|--|
| EPDM | EPBM, EPM | Ethylene-propyl- ene-diene Monomer | -40F/250F | Excellent ozone, chemical, and aging resistance. Poor resistance to petroleum-based fluids | Animal and vegetable oils, ozone, strong and oxidizing chemicals. | Mineral oils and solvents, aromatic hydrocarbons |
| NBR | NBR, Buna-N | Nitrile-butadiene | -30F/225F | Excellent resistance to petroleum-based fluids, Good physical properties | Many hydrocarbons, fats, oils, greases, hydraulic fluids, chemicals | Ozone, ketones, esters, aldehydes, chlorinated and nitro hydrocarbons |
| FPM | FPM, Viton® | Hexaflouroproply- ene-vinylidene fluoride | -10F/400F | Excellent oil and air resistances both at low and high temperatures. Very good chemical resistance | All aliphatic, aromatic, and halogenated hydrocarbons, acids, animal and vegetable oils | Ketones, low molec- ular weight esters and nitro containing compounds |
| PTFE | PTFE, Teflon® | Polytetrafluoro-eth- ylene | -100F/450F | Excellent abrasion resistance and chemically inert | Acids, harsh inorganic and organic chemicals, oils, oxidizing agents, and solvents | Molten alkali metals and fluorine at high temperatures |

CAM #25-0539



PRESSURE/TEMPERATURE RATINGS




In determining field pressure ratings for Series CVI Check Valves that are constructed of Ductile Iron the above chart should be used. Pressure cast on valve represents maximum seating pressure; maximum hydrostatic pressure is temperature dependent, and may be higher than nominal pressure rating.




CAM #25-0539 Exhibit 4 Page 97 of 205



MATERIALS OF CONSTRUCTION METAL SEATED VALVES





| ITEM | DESCRIPTION | MATERIAL OPTIONS | | | |
|------|----------------------|---------------------------------|--|--|--|
| 31= | BODY | DUCTILE IRON ASTM A536 65-45-12 | | | |
| | Way V | STAINLESS 204 ASTM A276 | | | |
| 2 | BODY SEAT RING | STAINLESS 316 ASTM A276 | | | |
| - | KING | BRONZE ASTM B62 | | | |
| | DIFFERENT | STAINLESS 304 ASTM A276 | | | |
| 3 | DISC SEAT RING | STAINLESS 316 ASTM AZ76 | | | |
| | into / | BRONZE ASTM B62 | | | |
| 4 | DISC | DUCTILE IRON ASTM A536 65-45-12 | | | |
| 5 | WASHER | STEEL ASTM A36 | | | |
| | weeks | STAINLESS ASTM F593 GROUP 1 | | | |
| 6 | HARDWARE | STAINLESS ASTM F593 GROUP 2 | | | |
| | | STEEL ASTM A325 TYPE 1 | | | |
| 7/ | ARM | DUCTILE IRON ASTM A536 65-45-12 | | | |
| 10 | SEAL | EPDM | | | |
| /" | SCAL | BUNA-N (NBR) | | | |
| 9 | COVER | SAME AS BODY (1) | | | |
| | EXTERIOR HARDWARE | STAINLESS ASTM F593 GROUP 1 | | | |
| 10 | | STAINLESS ASTM F593 GROUP 2 | | | |
| | | STEEL ASTM A325 TYPE 1 | | | |
| 11 | BEARING | PTFE | | | |
| 12 | KEY | STEEL ASTM A36 | | | |
| 13 | SHAFT SEAL | EPDM | | | |
| 1.0 | SHAFTSEAL | BUNA-N (NBR) | | | |
| 1.4 | RETAINER: | SAME AS BODY (1) | | | |
| | 10.00 | STAINLESS 304 ASTM A276 | | | |
| 15 | SHAFT | STAINLESS 316 ASTM A276 | | | |
| | | STAINLESS 17-4PH ASTM A693 | | | |
| 16 | ARM* | DUCTILE IRON ASTM A536 65-45-12 | | | |
| 17 | WEIGHT* | DUCTILE IRON ASTM A536 65-45-1 | | | |

^{*} IF EQUIPPED


CAM #25-0539 Exhibit 4 Page 98 of 205


1295 Alpha Drive, Alpharetta, GA 3000A Je 770,740,0800 F: 770,740,8777

E. sales@vs.walerworks.com



MATERIALS OF CONSTRUCTION RUBBER SEATED





| ITEM | DESCRIPTION | MATERIAL OPTIONS | | |
|------|----------------------|---------------------------------|------|--|
| 31= | BODY | DUCTILE IRON ASTM A536 65-45-12 | b" | |
| | 10000-000 | STAINLESS 304 ASTM A276 | | |
| 2 | BODY SEAT RING | STAINLESS 316 ASTM A276 | | |
| | KING | BRONZE ASTM B62 | | |
| | | EPBM | | |
| 3 | DISC SEAT | BUNA-N [NBR] | | |
| | | VITON (FPM) | | |
| 4 | DISC | DUCTILE IRON ASTM A536 65-45-12 | | |
| 5 | WASHER | STEEL ASTM A36 | | |
| | Vindamor 1 | STAINLESS ASTM F593 GROUP I | | |
| 6 | HARDWARE | STAINLESS ASTM F593 GROUP 2 | | |
| | THEOTOMIC | STEEL ASTM A325 TYPE 1 | 1 | |
| 7 | ARM | DUCTILE IRON ASTM AS36 65-45-12 | | |
| a | CEAL | EPDM | | |
| 8 5 | SEAL | BUNA-N (NBR) | | |
| 9 | COVER | SAME AS BODY (1) | | |
| | EXTERIOR HARDWARE | STAINLESS ASTM F593 GROUP 1 | | |
| 10 | | STAINLESS ASTM F593 GROUP 2 | 5531 | |
| | Chargothing | STEEL ASTM A325 TYPE 1 | | |
| 11 | BEARING | PTFE BRONZE | | |
| 12 | KEY | STEEL ASTM A36 | | |
| 13 | SHAFT SEAL | ЕРВМ | | |
| 13 | SHAFT SEAL | BUNA N (NBRI | | |
| 14 | RETAINER | SAME AS BODY ITI | | |
| 15 | | STAINLESS 304 ASTM A276 | | |
| | SHAFT | STAINLESS 316 ASTM A276 | | |
| | | STAINLESS 17-4PH ASTM A693 | | |
| 16 | ARM* | DUCTILE IRON ASTM A586 65-65-12 | | |
| 17 | WEIGHT* | DUCTILE IRON ASTM A536 65-45-12 | | |

* IF EQUIPPED




CAM #25-0539




FLANGED WITH OUTSIDE LEVER AND WEIGHT

| SIZE | A | В | c | D | Ė | F | WEIGHT (LBS) |
|------|-------|------|-------|------|-----------|------|-----------------|
| 2" | 9.00 | 54 | 4.75 | 5.0 | <u> į</u> | 0.75 | 27 |
| 2.5" | 8.50 | 5.8 | 5.5 | 7.0 | 4 | 0.75 | 44 |
| 3" | 9.50 | 4.3 | 4.00 | 7.2 | 4 | 0.75 | 51 |
| 4- | 11.50 | 7.1 | 7.50 | 9.0 | 8 | 0.75 | 79 |
| 52 | 13.00 | 8.0 | 8.50 | 10.0 | 9 | 0,75 | 484 |
| 6" | 14.00 | 8.8 | 9.50 | 11,0 | 8 | 0.88 | 128 |
| 8" | 19.50 | 10,2 | 14.75 | 13.5 | 2 | 0.88 | 238 |
| 10" | 24.50 | 11.4 | 14.25 | 16.0 | 12 | 1.00 | 374 |
| 12" | 27.50 | 128 | 17.00 | 19.0 | 12 | 1.00 | 418 |
| 14" | 31.00 | 16.7 | 18.74 | 21.0 | 12 | 1.13 | 737 |
| 16" | 34.00 | 17.5 | 21.25 | 23.5 | 14 | 1.13 | 948 |
| 18" | 38.00 | 18.9 | 22.75 | 25.0 | 16 | 1.25 | 1500 |
| 20" | 42.00 | 20.0 | 25.00 | 27.5 | 20 | 1.25 | 1400 |
| 24" | 48.00 | 23.9 | 29.50 | 32.0 | 20 | 1,38 | 2600 |
| 30" | 55.00 | 28.6 | 35.00 | 38.8 | 28 | 1.38 | - |
| 36" | 63.00 | 37.9 | 42.75 | 46.0 | 32 | 1.63 | - 1 |
| 75 | 70.00 | 41.0 | 49.50 | 53.0 | 36 | 1.63 | |
| 48" | 76.00 | 49.0 | 56.00 | 49.5 | 44 | 1.63 | - |




CAM #25-0539 Exhibit 4 Page 100 of 205






BONDED SEAT SWING CHECK PART NUMBER MATRIX



EXAMPLE:

CVI08F-DDSB-PS1/0-Q

CAM #25-0539



VSI Waterworks LLC

tel: 1 (770) 740 0800 fax: 1 (770) 740 8777

email: sales@vsiwaterworks.com



As part of a process of on-going product development, VSI reserves the right to amend or change specifications without prior notice. Published data may be subject to change. For the hard website at www.vsiwajexmont/s.com

Page 103 of 205

City of Fort Lauderdale


NE 38th Street 42-Inch FM and NE 19th Avenue 24-Inch FM Replacement.

Submittal Name: SHOP DRAWINGS - PLUG VALVE



| Date of Submission | 12/06/2024 | | | |
|---|---|--|--|--|
| 2, Project Number | P12384 | | | |
| 3, Project Name | NE 38th Street 42-Inch FM and NE 19th Avenue 24-Inch FM Replacement | | | |
| Contractor Identification | 23-FL.GOLF-001 | | | |
| a. Contractor | David Mancini and Sons, Inc | | | |
| b. Supplier | | | | |
| c, Manufacturer | N/A | | | |
| d. Manufacturer or supplier representative | N/A | | | |
| 5. Identification of the Product | EXB-12.0-P12384-20-0 | | | |
| Reference to Contract Drawing | D02 | | | |
| Reference to Specification Section Number, page and paragraphs. | Technical Specifications 2.02 | | | |
| 8. Indication of Contractor's approval. | Approved by DMSI | | | |
| Contractor's Certification Statement. (Refer to paragraph 1.03.F.2) | "By this submittal. I hereby represent that I have determined and verified all field measurements, field construction criteria, materials, dimensions, catalog numbers and similar data and I have checked and coordinated each item with other applicable approved shot drawings and all Contract requirements." | | | |
| 10. Identification of deviations from the Contract, if any. | | | | |
| 11. Reference to previous submittal (for resubmittals). | | | | |











IMPLEMENTATIONS

The Eccentric Plug valve is the industry standard for systems that will experience sludge or large particulate flow. VSI Eccentric Plug Valves are able to achieve an extremely high port area while keeping the operating time much lower than the traditional gate valve.


ECCENTRIC MOVEMENT

The most essential function of a valve is that it must isolate line flow. This action is easy to accomplish, but with traditional designs as pressure and size increase the torque required to close the valve increase exponentially.

To counteract this characteristic all VSI Eccentric Plug Valves incorporate an offset in the valve design. By offsetting the plug and shalt centerline from the valve body and pipe centerline a cam action is achieved. This action allows the plug to contact the valve body only in the last 5-10 degrees of movement. Through the rest of the valve motion the only torque transmitted to the operator will be from the low friction bearings and line force on the plug.

The cam action increases the seat force without increasing operator torque allowing for the use of more durable encapsulation materials that are often harder.





RESILIENT PLUG FACING

All VSI Eccentric Plug Valves are equipped as standard with a fully encapsulated resilient plug. By fully encapsulating the plug the service life of the valve is greatly extended by reducing corrosion of the plug. The resilient nature of the seat allows for driptight shut off. Should small solids become deposited upon the plug face, tight shut off is still guaranteed.



ADJUSTABLE/REPLACEABLE PACKING

The packing of the Series PVIF consists of multiple v-type packing rings and adjustable gland. The open bonnet on above ground valves allows for the adjustment and replacement of packing without removing the gearbox/operator

NUMEROUS ACTUATION OPTIONS

The standard ISO 5211 top mount allows VSI to offer a wide range of electric, pneumatic, hydraulic, failsafe, and other actuation packages

STANDARD LIFTING EYE

The lifting holes at all ends of the PVIF give a secure and easy attachment point that allows the valve to be confidently maneuvered into place on job sites. Equipped as a standard feature on all PVIF valves, making your install that much easier.

FULL PORT DESIGN

The rectangular port is of a "Full Port" type with a flow area equal to the nominal pipe to maintain excellent free flow, high Cv values, and low head loss. Pigging with semi-rigid foam type pigs is possible.

coating can be optioned to

The standard 2-part heavy duty coating can be optioned to a wide variety of coatings as required by the project requirements such as NSF 61 listed coatings, ceramic reinforced resin, or coal-tar epoxy

MULTIPLE COATING OPTIONS

FULLY ENCAPSULATED PLUG

The plug of the Series PVIF is fully encapsulated with resilient rubber covering every surface exposed to the line. Full encapsulation eliminates corrosion and minimizes the possibility of delamination or damage to the seat.

CAM #25-0539

PAGE 3

to AWWA C517



SAMPLE SPECIFICATION

FULL RECTANGULAR PORT PLUG VAVES FOR WATERWORKS SERVICE

- 1.1. This specification covers the design, manufacture, and testing of eccentric plug valves from 14 inch (350 mm) through 72 inch (1800 mm) under service pressure of up to 150 psig [1035 kPa].
- 1.2. Plug valves shall be resilient seated and of the quarter turn, non-lubricated, eccentric type.

GOVERNING STANDARDS

- 2.1. All eccentric plug valves shall be in full conformance with the design, manufacturing, and testing standards set forth by the American Water Works Association (AWWA) in Standard ANSI/AWWA C517.
- 2.2. When requested, manufacturer shall provide an Affidavit of Proof of Design Testing in accordance with AWWA C517.

CONNECTIONS

- 3.1. Flanged valves shall conform to all standards of ANSI B16.1, Class 125.
- 3.2. Mechanical joint valves shall conform to all standards of ANSI/AWWA C111/A21.11.

MARKINGS

- 4.1. Each valve shall be marked with the manufacturer's name, valve size, body material, and pressure rating cast into the body of the valve. Lettering shall be a minimum of 1/2 inch tall and project 1/10 inch from body.
- 4.2. All plug valves, except buried or submerged valves, shall be equipped with a type 304 or 316 stainless steel or Aluminum tag identifying body, plug, resilient seat, and stem material in addition to manufacturer's name, pressure rating, size, date of manufacturer, and date of testing.

DESIGN

- 5.1. Port areas of valves in relation to pipe areas shall not be less than 100%
- Valves shall be equipped with a minimum 95% nickel seat directly bonded to a machined finished surface on valve body.
 Plated or removable seats are not acceptable.
- 5.3. Valve shall be equipped with a set of V-type stem packing with an adjustable gland. Valve stem packing shall be replaceable without removing the cover or bonnet of the valve.
- 5.4. Radial shaft bushings shall be supplied in the upper and lower bearing journals. Thrust bearings shall be supplied between the plug and body in both the upper and lower journal areas.
- 5.5. The valves shall be equipped with a mounting area for operators conforming to Manufacturers Standard Society(MMS).
 101 or International Organization of Standardization(ISO) 52111. There shall be sufficient clearance to directly mount standardized operators with easily accessible fasteners.

6. MATERIALS

- 6.1. The valve body, cover, and bonnet if equipped shall be constructed of ASTM A536 Ductile Iron.
- 6.2. The plug shall be constructed of ASTM A536 Ductile Iron and shall be one piece. The resilient plug encapsulation shall conform to ASTM D429 testing.
- 6.3. Radial and thrust bearings shall be made of permanently lubricated type 316 stainless steel.
- 6.4. All submerged coatings shall conform to AWWA C550, be holiday free, and have a minimum total dry film thickness of 10 mils.
- 6.5. All uncovered, submerged, or buried valves shall have type 304 or 316 stainless steel hardware unless specified.

OPERATORS

- 7.1. All manually operated valves 4 inch and larger shall be equipped with a worm gear actuator with position indicator. Direct 2" operator nut may be used when specified on 6" and under valves.
- 7.2. All actuators shall be permanently sealed and suitable for buried service.
- 7.3. All 2 inch square operating nuts, exposed hardware and shafts shall be made of corrosion resistant stainless steel.
- 7.4. All actuators equipped with handwheels shall have a maximum rim pull of 80lbs.

MANUFACTURER


- 8.1. Eccentric plug valves shall be VSI Series AWWAC517 as manufactured by Valve Solutions, Inc., Alpharetta, GA USA or approved equal.
- 8.2. All valves shall be warranted by manufacturer for a minimum of 12 months.


to AWWA C517





Materials of Construction





| Item | Description | Materials Available | Standard |
|------|----------------------------|-------------------------------|--------------------|
| 1 | Cover | Same as Body | |
| | | Ductile Iron* | ASTM A536 65-45-12 |
| 2 | Darky | Cast Iron | ASTM A126 Class B |
| 2 | Body | Stainless Steel 304 | ASTM A351 CF8 |
| | | Stainless Steel 316 | ASTM A351 CF8M |
| | | Ductile fron* | ASTM A536 65-45-12 |
| 0 | Dive | Cast Iron | ASTM A126 Class B |
| 3 | Plug | Stainless Steel 304 | ASTM A351 CF8 |
| | | Stainless Steel 316 | ASTM A351 CF8M |
| | | Buna-N (NBR)* | |
| | Plug | Chloroprene | |
| 4 | Encapsulation | EPDM | |
| | | Viton (FPM) | |
| 5 | Bonnet | Same as Body | |
| 6 | Gland | Same as Body | |
| 7 | Packing | Same as Plug Encapsulaton | |
| ò | Experience of | Stainless 304* | ASTM F593/594 |
| 8 | Exterior Hardware | Stainless 316 | ASTM F593/594 |
| 9 | Cover Seal | Same as Plug Encapsulation | |
| | | Stainless 316* | |
| 10 | | Stainless 304 | |
| 10 | Bearings | Reinforced PFTE | |
| | | Bronze | |
| 11 | Grit Guard | Nylon | _ |
| 12 | Grit Seal | Same as Plug Encapsulation | |
| 13 | Lower Cover ^[2] | Same as Body | |
| | | Fusion Bonded Epoxy, Black* | |
| NS | Coating/Lining | Two-Part Epoxy | |
| | | Coal-Tar Epoxy | |
| Nic | ₩ | Aluminum* | |
| NS | Tag | Stainless Steel | |
| NS | Assembly Lubricant | ANSI/NSF 61 Listed Silicone L | ubricant |
| NS | Operator | Varies | |

Additional material options available as special order.

*Standard Material

[1] Lower cover integral to body casting on 14"-24"

(2) Lower journal cover standard on 30" and above

CAM #25-0539

Exhibit 4 VSI Waterworks Page 109 of 205 1205 Alpha Drive, Alpharelta, GA 30004 T: 770.740.0800 F: 770,740.8777 E: sales@vsiwaterworks.com



Design Standards



*Standard Option



Resistance Guide

| D | esignation | Common Names | Composition | Min/Max Temperature Range | General Properties | Resistant to: | Attacked by: |
|---|------------|---------------|---|------------------------------|--|---|--|
| | NBR* | NBR, Buna-N | Nitrile-butadiene | -30F/225F | Excellent resistance to petroleum-based fluids. Good physical properties | Many hydrocarbons, fats, oils, greases, hydraulic fluids, chemicals | Ozone, ketones, esters, aldehydes, chlorinated and nitro hydrocarbons |
| | FPM | FPM, Viton® | Hexaflouroproply- ene-vinylidene fluoride | -10F/400F | Excellent oil and air resistances both at low and high tem- peratures. Very good chemical resistance | All aliphatic, aromatic, and halogenated hydrocarbons, acids, animal and vegetable oils | Ketones, low molec- ular weight esters and nitro containing compounds |
| | PTFE | PTFE, Teflon® | Polytetrafluoro-eth- ylene | -100F/450F | Excellent abrasion resistance and chemically inert | Acids, harsh inorganic and organic chemicals, oils, oxidizing agents, and solvents | Molten alkali metals and fluorine at high temperatures |
| | EPDM | ЕРДМ, ЕРМ | Ethylene-propyl- ene-diene Monomer | -40F/250F | Excellent ozone, chemical, and aging resistance. Poor resistance to petroleum-based fluids | Animal and vegetable oils, ozone, strong and oxidizing chemicals. | Mineral oils and solvents, aromatic hydrocarbons |


CAM #25-0539 Exhibit 4 Page 110 of 205

cma

to AWWA C517



Pressure/Temperature Ratings




In determining field pressure ratings for Series PVIF Plug Valves that are constructed of Ductile Iron the above chart should be used. Pressure cast on valve represents maximum seating pressure; maximum hydrostatic pressure is temperature dependent, and may be higher than nominal pressure rating.




Cold Working Pressure Rating


| SIZE | FORWARD CLOSEOFF W/GEAR | REVERSE CLOSEOFF W/ GEAR | FORWARD CLOSEOFF NUT AND/OR LEVER | REVERSE CLOSEOFF NUT AND/OR LEVER |
|------------|-------------------------------|--------------------------------|---|---|
| 14"+ CL125 | 150 PSI | 150 PSI | NA | NA |
| 14"+ MJ | 150 PSI | 150 PSI | NA | NA |
| 14"+ CL250 | 250 PSI | 150 PSI | NA | NA |







Flanged CL125 Barestem Dimensions









| cma l |
|--|
| X server to the total serv |
| |
| |
| |
| 12/0/24 |

| SIZE | A | В | Ċ | D | E | F | G | Hitt | J IZI | R(a) | L141 |
|------|-------|------|-------|-------|------|-------|-------|------|-------|------|------------|
| 14" | 17.00 | 1 38 | 13.11 | 17.00 | 3.35 | 21.00 | 18 75 | 8 | 1/125 | 4 | THUNC |
| 16" | 17.75 | 1.44 | 14.37 | 17.70 | 3.54 | 23.50 | 21.25 | 8 | 1.125 | 8 | 1-8UNC |
| 18" | 21.50 | 1.56 | 15,95 | 19.10 | 3.35 | 25.20 | 12,75 | 8 | 1.25 | 8 | 1.125-7UNC |
| 20" | 23.50 | 1.69 | 16.62 | 20.00 | 3.64 | 28.15 | 25.00 | 12 | 1.25 | 8 | 1.125-7UNC |
| 24 | 42.00 | 1.88 | 20.67 | 23.30 | 4.66 | 32,00 | 29.50 | 20 | 1.375 | 8 | 1.25-7UNC |
| 30" | 51.00 | 2.12 | 26,57 | 30.12 | 4.92 | 38.75 | 36.00 | 20 | 1.375 | 8 | 1.25-7UNC |
| 36 | 60,00 | 2.38 | 30,71 | 34.41 | 5,50 | 46,00 | 42.75 | 24 | 1.625 | 8 | 1.5-AUNC |
| 42" | 72.00 | 2.62 | 37.40 | 43.26 | 7.50 | 53.00 | 49.50 | 32 | 1.625 | 4 | 1.5-6UNC |
| 48- | 84.00 | 2.75 | 42.32 | 47.33 | 7.50 | 59.50 | 56.00 | 40 | 1.625 | 4 | T.5-6UNC |

- [1] "H" represents the total number of through holes, per flange [2] "J" represents the size of the through holes for flange


- (3) "K" represents the total number of tapped holes, per flange (4) "L" represents the size of tapped holes and bolts used for flange


CAM #25-0539 Exhibit 4 Page 112 of 205


E. sales@ys.walerworks.com




Mechanical Joint Barestem Dimensions










| SIZE | A | В | C | D | E | F | G | (Hm) | J(2) |
|------|-------|------|-------|-------|------|-------|-------|------|------|
| 14" | 24.50 | 0,79 | 12.11 | 17,00 | 3,36 | 20,31 | 16,75 | 0.08 | 6 |
| 16" | 27.25 | 0.85 | 14.37 | 17.72 | 3.54 | 22.64 | 21.00 | 0.88 | 8 |
| 18" | 29.25 | 1.00 | 15.95 | 19.10 | 3.85 | 25,00 | 20,25 | 0.88 | 8 |
| 20" | 31.00 | 1.02 | 16.62 | 20.00 | 3.64 | 27.16 | 25.50 | 0.88 | 10 |
| 24" | 42.00 | 1,02 | 20.67 | 23,31 | 4,00 | 31.89 | 30,00 | 0.88 | 12 |
| 30" | 51.00 | 1.31 | 26.57 | 30.12 | 4.92 | 39.12 | 36.88 | 1.13 | 12 |
| 36" | 60.00 | 1.45 | 30.71 | 34.41 | 5.50 | 46.00 | 43.75 | 1 13 | 16 |
| 42" | 72.00 | 1.45 | 37.40 | 43.26 | 7.50 | 53.12 | 50.62 | 1.38 | 20 |
| 48" | 84.00 | 1.45 | 42.32 | 47.33 | 7,50 | 60,00 | 57.50 | 1.38 | 34 |


- (1) "H" represents the size of through holes, bolt size is 1/8" smaller
 Flange's drilling/bolting and bell end/gasket groove dimensions per AWWA C111
 (2) "J" represents the total number through holes, per flange


to AWWA C517




Flanged With Worm Gear & HW









| SIZE | A | В | C | D | E | F | G | Hui | Jim | Kraj | L166 | P |
|------|-------|------|-------|-------|------|-------|-------|-----|-------|------|------------|------|
| 14" | 17.00 | 1.38 | 13.11 | 17.00 | 3.35 | 21.00 | 18.75 | 8 | 1,125 | 4 | 1-8UNC | 24 |
| 16" | 17.75 | 1.44 | 14.37 | 17.70 | 3,54 | 23.50 | 21.25 | 8 | 1.125 | 8 | 1-8UNC | 24 |
| 18" | 21.50 | 1.56 | 15.95 | 19.10 | 3.35 | 25.20 | 22.75 | B | 1.25 | 8 | 1.125-7UNC | 20 |
| 20" | 23.50 | 1.69 | 16.62 | 20.00 | 3.64 | 28.15 | 25.00 | 12 | 1.25 | 8 | 1.125-7UNC | 24 |
| 24" | 42.00 | 1.88 | 20.67 | 23.30 | 4.66 | 32.00 | 29 50 | 20 | 1.375 | -8 | 1.25-7UNE | 24 |
| 30" | 51.00 | 2.12 | 26,57 | 30.12 | 4.92 | 38.75 | 36.00 | 20 | 1.375 | 8 | 1,25-7UNC | 27,5 |
| 36" | 60:00 | 2.38 | 30.71 | 34,41 | 5.50 | 46.00 | 42 75 | 24 | 1.625 | 8 | 1.5-6UNC | 31.5 |
| 42" | 72.00 | 2.62 | 37.40 | 43.26 | 7.50 | 53.00 | 49.50 | 32 | 1.625 | 4 | 1.5-6UNC | 35.5 |
| 48" | 84.00 | 2.75 | 42.32 | 47.33 | 750 | 59.50 | 56.00 | 40 | 1.625 | 4 | 1.5-6UNC | 31.5 |

- (1) "H" represents the total number of through holes, per flange (2) "J" represents the size of the through holes for flange


- (3) "K" represents the lotal number of tapped holes, per flange (4) "L" represents the size of tapped holes and bolts used for flange


CAM #25-0539 Exhibit 4 Page 114 of 205


E. sales@vs.walerworks.com




Mechanical Joint With Worm Gear & 2" Nut Op









| cma |
|---|
| X section and the section is a section of the section in the section in the section is a section in the section in the section in the section is a section in the section in the section in the section is a section in the section in |
| The state is any fire against artifactors with the |
| Contract of present rather for the four least long for one of the state for present for manifest pill for projection of the pile, and it rections. Specially in a could not each of the gamen's included at the first pile. |
| in prices and comment to be about the |
| Annua |


| SIZE | A | В | C | D | E | F | G | Hm | 1121 |
|------|-------|------|-------|-------|------|-------|-------|------|------|
| T4" | 24.50 | 0.79 | 13,11 | 17.00 | 2.00 | 20.25 | 18.75 | 0.88 | 6 |
| 16" | 27.25 | 0.85 | 14.37 | 17.72 | 2.00 | 22.50 | 21.00 | 0.88 | 8 |
| 18" | 29.25 | 1,00 | 15.95 | 19.10 | 3,15 | 24.75 | 23.25 | 0.88 | 8 |
| 20" | 31.00 | 1.02 | 16.62 | 20.00 | 3.55 | 27.00 | 25.50 | 0.88 | 10 |
| 24" | 42:00 | 1.02 | 20.67 | 23.31 | 3.98 | 31,50 | 00.0E | 0.88 | 12 |
| 30" | 51.00 | 1.31 | 26.57 | 30.12 | 5.47 | 39.12 | 36.88 | 1.13 | 12 |
| 36" | 60.00 | 1,45 | 30.71 | 34.41 | 6,61 | 46,00 | 43,75 | 1,13 | 16 |
| 42" | 72.00 | 1.45 | 37.40 | 43.26 | 6.77 | 53.12 | 50.62 | 1.38 | 20 |
| 48" | 84.00 | 1.45 | 42.32 | 47.33 | 7.34 | 60,00 | 57.50 | 1.38 | 24 |


- "H" represents the size of through holes, bolt size is 1/8" smaller
 Flange's drilling/bolting and bell end/gasket groove dimensions per AWWA C111
- (2) "J" represents the total number through holes, per flange



STANDARD OPERATOR TYPES

SINGLE STAGE WORM GEAR WITH SPUR SECONDARY GEAR







2-INCH NUT OP.








CAM #25-0539 Exhibit 4 Page 116 of 205




FLOW CHARACTERISTICS

HEADLOSS VS. FLOW RATE



| SIZE | Cv | Kv |
|------|-------|-------|
| 14" | 6085 | 5257 |
| 16" | 8199 | 7084 |
| 18" | 12168 | 10513 |
| 20" | 15710 | 13573 |
| 24" | 25565 | 22088 |
| 30" | 38315 | 33104 |
| 36" | 58623 | 50650 |








12/9/24





PART NUMBER MATRIX



* Standard Material

1 - May not be available for all configurations/sizes

EXAMPLE:

PVIF14F-DDN-3S1/WC-J

A 14" flanged rectangular full port plug valve with Ductile Iron body and plug, NBR plug encapsulation, SS316 bearings, SS304 hardware, Fusion bonded epoxy, worm gearbox with chainwheel operator.

DOC#:

C517-36-POD

Exh05t/431/2010

AWWA C517-09 Proof of Design Test Certification (36" Resilient Seated Eccentric Plug Valve)

ITEM TESTED:

VSI C517 Series Resilient Seated Eccentric Plug Valve - 36 inch size (150psi)
Ductile Iron Body and Bonnet
95% Nickel Bonded Seat
Ductile Iron Plug encapsulated in NBR

PURPOSE:

To perform the Proof of Design test requirements laid out in American Water Works Association (AWWA) Standard C517, Resilient Seated Cast Iron Eccentric Plug Valves.

RECORD OF TEST:

PLUG STRUCTURE TEST: The test valve was mounted to the test heads, and the valve put into the closed position. A pressure of 300 psi was then applied to the seat side of the plug for 60 seconds. The pressure was then released, and 300 psi was applied to the back side of the plug for 60 seconds. After the test pressure was released, the plug was inspected. There were no signs of deformation nor breakage found.

LIFE CYCLE TEST: The test valve was mounted to the test heads, and put into the closed position. A test pressure of 150 psi was applied to the seat side of the valve, and zero pressure on the back side. The valve was then operated from fully closed to fully open 5,000 times. The test took place over a period of 21 days. Upon completion of the life cycle test, a hydrostatic seat test was performed. A test pressure of 150 psi was applied to the seat side of the valve and held for 60 seconds. The test pressure was then relieved and applied to the back side of the plug for 60 seconds. There were no visible signs of leakage from the stem, seat, or any other pressure constraining joints.

POST TEST INSPECTION: Upon completion of all the tests, the valve was disassembled, and inspected. There were no signs of extensive wear, cracking, or bonding failure on the valves corrosion-resistant seating surfaces.

CERTIFICATION:

PROOF OF DESIGN CERTIFICATION

Based on the above test record, we here by certify that the test valve has successfully met all of the proof of design requirements in AWWA C517 and therefore qualifies similar valves in the Series C517 24 inch through 42 inch product line, with equal or lesser pressure classes to the same standards.

| | (a 1 - A | |
|--|---|------------------|
| TESTED BY:Robert War | Robert wing | DATE: 05/31/2010 |
| CERTIFIED BY: | Michael, fan | DATE: 05/31/2010 |
| Committee of the commit | l Fan, Tianjin Flow Security Valve Co., Ltd | |
| 26" DESILIENT SEATE | D ECCENTRIC BILIC VALVE | € 0530 |

DOC#:

C517-42-POD

AWWA C517-09 Proof of Design Test Certification (42" Resilient Seated Eccentric Plug Valve)

ITEM TESTED:

VSI C517 Series Resilient Seated Eccentric Plug Valve - 42 inch size (150psi)
Ductile Iron Body and Bonnet
95% Nickel Bonded Seat
Ductile Iron Plug encapsulated in NBR

PURPOSE:

To perform the Proof of Design test requirements laid out in American Water Works Association (AWWA) Standard C517, Resilient Seated Cast Iron Eccentric Plug Valves.

RECORD OF TEST:

PLUG STRUCTURE TEST: The test valve was mounted to the test heads, and the valve put into the closed position. A pressure of 300 psi was then applied to the seat side of the plug for 60 seconds. The pressure was then released, and 300 psi was applied to the back side of the plug for 60 seconds. After the test pressure was released, the plug was inspected. There were no signs of deformation nor breakage found.

LIFE CYCLE TEST: The test valve was mounted to the test heads, and put into the closed position. A test pressure of 150 psi was applied to the seat side of the valve, and zero pressure on the back side. The valve was then operated from fully closed to fully open 5,000 times. The test took place over a period of 21 days. Upon completion of the life cycle test, a hydrostatic seat test was performed. A test pressure of 150 psi was applied to the seat side of the valve and held for 60 seconds. The test pressure was then relieved and applied to the back side of the plug for 60 seconds. There were no visible signs of leakage from the stem, seat, or any other pressure constraining joints.

POST TEST INSPECTION: Upon completion of all the tests, the valve was disassembled, and inspected. There were no signs of extensive wear, cracking, or bonding failure on the valves corrosion-resistant seating surfaces.


CERTIFICATION:

Based on the above test record, we here by certify that the test valve has successfully met all of the proof of design requirements in AWWA C517 and therefore qualifies similar valves in the Series C517 24 inch through 42 inch product line, with equal or lesser pressure classes to the same standards.

| TESTED BY: | Robert wang | DATE: 06/07/2010 |
|---------------|---|------------------|
| Robert Wan | g, Valve Solutions, Inc. | |
| CERTIFIED BY: | Michael Fam | DATE: 06/07/2010 |
| Michael | Fan, Tianjin Flow Security Valve Co., Ltd | |

42" RESILIENT SEATED ECCENTRIC PLUG VALVE PROOF OF DESIGN CERTIFICATION

CANT#25-0539 Exhibit/407/2010



VSI Waterworks LLC

tel: 1 (770) 740 0800 fax: 1 (770) 740 8777

email: sales@vsiwaterworks.com



As part of a process of on-going product development, VSI reserves the right to amend or change specifications without prior notice. Published data may be subject to change. For the latest version, visit our website at www.vsiwaexmonlys.com



VSI Waterworks 2" - 72" AWWA C517 ECCENTRIC PLUG VALVES

INSTALLATION, OPERATION AND MAINTENANCE MANUAL





TABLE OF CONTENTS

| SCOPE | 3 |
|----------------------------------|---|
| WARNINGS | 3 |
| GENERAL | 4 |
| UNLOADING | 4 |
| STORAGE | 4 |
| INSPECTION PRIOR TO INSTALLATION | 4 |
| INSTALLATION | 4 |
| TESTING | 6 |
| RECORDS | 7 |
| OPERATION | 7 |
| MAINTENANCE | 7 |
| TROUBLESHOOTING | 9 |



SCOPE:

This installation, operation, and maintenance manual covers the VSI AWWA C517 resilient seated eccentric plug valve and should be read and understood thoroughly by all parties responsible for installation and continued use/maintenance.

WARNINGS:

The critical safety messages within this manual are labeled with an exclamation symbol within a red triangle flag. Care should be taken to thoroughly read and understand these warnings before proceeding to ensure no damage to equipment occurs. Failure to follow all warnings could result in injury or death.



MARNING!

All parties that take part in any installation or continued use/maintenance are cautioned to be vigilant in the possible exposure to media that is contained within the valve and its pipeline. Because of the vast range of media that could be within the valve, protection from pipeline media is not within the scope of this manual. All personnel should be aware of the media within the valve and take appropriate precautions when exposure is possible while installing or servicing the valve.

RECEIVING:

The VSI AWWA C517 Resilient Seated Eccentric Plug Valve is rugged and will be packaged to provide protection during most shipping incidents, however care should be taken to inspect the valve on receipt for any possible shipping damage. Inspection should be performed as soon as practical. Failure to promptly notify VSI of any shipping damage may invalidate any claim for shipping damage. Most shipments from VSI will be made FOB Origin, unless noted on the sales documents, the purchaser will own the freight while in transit, assumes all risk while in transit, and will be responsible for reporting shipping damage promptly to the carrier.

PARTS:

Order parts from your Valve Solutions Inc. sales representative. Please include the serial number, located on the valve tag, when ordering parts.



WARNING!

Read all applicable instructions and directions prior to any maintenance, installation or troubleshooting.



SECTION 1: GENERAL

Plug valves are a significant component of any water distribution system or treatment plant operation. Valve failure due to faulty installation, improper operation, or maintenance in such systems could result in damage, downtime, and costly repairs. In buried or underground installations, problems or malfunctions can result in extensive and costly unearthing operations to correct or eliminate the problem. Many problems with plug valves can be traced to improper installation, operation, or maintenance procedures.

SECTION 2: UNLOADING

Inspect valves on receipt for damage in shipment and conformance with quantity and description on the shipping notice and order. Unload valves carefully to the ground without dropping. On valves larger than 6 in. (150 mm), use forklifts or slings under skids. On smaller valves, do not lift valves with slings or chain around actuator or through waterway. Lift these valves with eyebolts or rods through flange holes or chain hooks at the ends of valve parts.

SECTION 3: STORAGE

If it is not practical to store the valve indoors, protect the valve and actuators from weather and the accumulation of dirt, rocks, and debris. When valves fitted with power actuators and controls are stored, energize electric actuators or otherwise protect electrical-control equipment to prevent corrosion of electrical contacts due to condensation resulting from temperature variation. Do not expose resilient seats to sunlight or ozone for any extended period. Also see the manufacturer's specific storage instructions.

SECTION 4: INSPECTION PRIOR TO INSTALLATION

Make sure valve ends and seats are clean. Check all exposed bolting for loosening in transit and handling and tighten to manufacturer's recommendations. Open and close the valve to make sure it operates properly and that stops or limit switches are correctly set so that the plug seats fully. Close the valve before installing. Check coatings for damage and repair as required.

SECTION 5: INSTALLATION

It is strongly recommended that instruction manuals supplied by the manufacturer be reviewed in detail before installing plug valves. Be sure the inspection, as described in Sec. 4, is carried out at the job site prior to installation.

Sec. 5.1 Handling

Handle valves carefully when positioning, avoiding contact or impact with other equipment or structures.



Sec. 5.2 Service Conditions

Valves are to be installed in accordance with the manufacturer's instructions.

5.2.1 Clean service. Eccentric plug valves used for fluids free of suspended solids may be installed in any orientation. If practical, the valves shall be installed so the pipe line pressure is exerting force on the plug from opposite the seat end of the valve (direct pressure).




Image courtesy of Robert O'Neill

Figure 1. Recommended installation position for suspended solids service

5.2.2 Other service. Eccentric plug valves used for fluids containing suspended solids should be installed as shown in Figure 1. When installed in horizontal pipes, the axis of the plug is to be horizontal, with flow entering the valve body from the seat end. The plug is to rotate counterclockwise to open, keeping the plug in the upper half of the body. When installed in vertical pipes, the seat end shall be oriented as shown in Figure A-1.

Sec. 5.3 Buried Installations

When practical, valves in buried installations should be located in unpaved areas.

Sec. 5.4 Cleaning

Be sure valve interiors, ends, and adjacent piping are cleaned of foreign material prior to making up valve-to-pipe joint connection.



Sec. 5.5 Pipe Ends

Prepare pipe ends and install valves in accordance with the pipe manufacturer's instructions for the joint used. Do not deflect the pipe-valve joint. Do not use a valve as a jack to pull pipe into alignment. In plant piping, the valve shall be installed so as to minimize the bending stresses in the valve end connection with pipe loading.

Sec. 5.6 Installation

For mechanical-joint end valves, lubrication and additional cleaning should be provided by brushing both the gasket and the plain end of the mating pipe with soapy water or pipe lubricant just before slipping the gasket onto the plain end and assembling the joint. When tightening bolts, it is essential that the gland be brought up toward the bell flange evenly, maintaining approximately the same distance between the gland and the face of the flange at all points around the socket. This may be achieved by first partially tightening the bottom bolt, then the top bolt, next the bolts at either side, and finally, the remaining bolts. This process should be repeated until all bolts are fully torqued.

Sec. 5.7 Valve Boxes

Buried valves installed with valve boxes shall be installed so that the valve box does not transmit shock or stress to the valve actuator as a result of shifting soil or traffic load.

Sec. 5.8 Valves Installed in Vaults

When valves are installed in vaults, the vault design shall provide space for removal of the valve-actuator assembly for purposes of repair. Consideration should be given to the possible entry of groundwater or surface water and to the need to provide for disposal thereof. The valve operating nut should be accessible from the top opening of the vault with a tee wrench.

SECTION 6: TESTING

When resilient-seated cast-iron eccentric plug valves are used to isolate sections of a pipeline for testing, it is important to realize that eccentric plug valves are typically factory adjusted to hold pressure only up to the specified shutoff pressure in the direct pressure direction. Prior to any field pressure test under conditions different from above, it is recommended that the valve manufacturer be contacted for approval. Otherwise, test pressures above the valve design pressure may cause leakage, permanent damage, or structural failure to the valve and injury or death to the operator.

Sec. 6.1 Leaks

In order to prevent the loss of time due to searching for leaks, it is recommended, where feasible, that excavations for buried valves not be backfilled until after pressure tests have been completed.

Sec. 6.2 Seat Leakage

Seat leakage can occur from foreign material in the line. If this occurs, open the valve 5° to



10° to obtain high-velocity flushing action, then close. Repeat several times to clear seats for tight shutoff. Do not force valves for a tighter seal. Plug valves are provided with an externally adjustable closed stop on the actuator to provide a tighter seal. See the instruction manual provided by the manufacturer for the correct adjustment procedure.

SECTION 7: RECORDS

On completion of installation, the valve location, size, make, type, date of installation, number of turns to open, direction of opening, and any other information deemed pertinent should be entered on the owner's permanent records.

SECTION 8: OPERATION

Sec. 8.1 Design Pressure

Do not permit the use or operation of any valve at pressures above the rated design pressure of the valve.

Sec. 8.2 Input Torque

Do not exceed 250 ft-lb (339 N·m) input torque on actuators with wrench nuts and do not exceed 200 lb (890 N) rim pull for handwheels or chainwheels. If portable auxiliary actuators are used, size the actuator or use a torque-limiting device to prevent application of torque exceeding 250 ft-lb (339 N·m). If an oversize actuator with no means of limiting torque is used, stop the actuator before the valve is fully opened or closed against stops and complete the operation manually. Be sure to check the actuator directional switch against the direction indicated on the wrench nut, handwheel, or records before applying opening or closing torque.

Sec. A.8.3 Sticking

If a valve is stuck in some intermediate position between open and closed, check first for jamming in the actuator. If nothing is found, the interference is inside the valve. In this case, do not attempt to force the plug open or closed, because excessive torque in this position can severely damage internal parts.

SECTION 9: MAINTENANCE

Maintenance of resilient-seated plug valves by the owner is generally limited to actuators and shaft seals. Unless the owner has skilled personnel and proper equipment, any major internal problem will probably require removal of the valve from the line and return to the manufacturer for repair.

Sec. 9.1 Normal Maintenance

Normal maintenance is in the area of shaft seals and actuators. Seal leakage, broken parts, hard operation, and, in some cases, seat leakage should be corrected by a repair crew as soon as possible after a defect is reported.



Sec. 9.2 Valve Exercising

Each valve should be operated through a full cycle and returned to its normal position on a time schedule that is designed to prevent a buildup of lubrication or other deposits that could render the valve inoperable or prevent a tight shutoff. The interval of time between operations of valves in critical locations or valves subjected to severe operating conditions should be shorter than for other less important installations, but it can be whatever time period is found to be satisfactory based on local experience. For gear operators, the number of turns required to complete the operation cycle should be recorded and compared with permanent installation records to ensure full plug travel.

Sec. 9.3 Field Repairs

If repairs are to be made in the field, repair crews should take a full complement of spare parts to the job site. Be sure to review the valve manufacturer's instructions prior to any repair work. **Sec. 9.4 Isolation**

Provision should be made to stop line flow and isolate the valve from line pressure prior to performing any corrective maintenance.

Sec. 9.5 Repair Testing

After completing repairs, cycle the valve through one complete operating cycle and, after line pressure has been restored, inspect for leakage.

Sec. 9.6 Valve Removal

If major repairs require the removal of the valve for repair, be sure to notify interested parties in the water department and fire department that the valve and line are out of service. On completion of repair and reinstallation, notify the same personnel of the return of the valve and line to service.





SECTION 10: TROUBLESHOOTING

| Problem | Cause | Correction | | | |
|---|---|---|--|--|--|
| The operator or shaft will not turn | Interference between valve box and shaft key | Reposition valve box if necessary | | | |
| | Uneven tightening of gland plate bolts | Loosen then retighten bolts and nuts evenly | | | |
| | Corrosion or debris between the stem and packing | Consult VSI for disassembly procedures and clean stem, stuffing, and stem nut | | | |
| | Debris blocking movement of plug | Consult VSI for disassembly procedures and clean out debris | | | |
| | RARE: Seized worm gear | Inspect and replace if necessary | | | |
| Leakage between the body and cover of valve | Bolts and nuts may be loose or tightened irregularly | Loosen then retighten bolts and nuts evenly | | | |
| | Bonnet o-ring may be damaged | Consult VSI for disassembly procedures and replace o-ring | | | |
| | RARE: Crack in body or bonnet | Inspect and replace if necessary | | | |
| Leakage at the stem | Damaged stuffing | Consult VSI for disassembly procedures and replace damaged parts if needed | | | |
| | Loose packing | Tighten the packing gland nuts until leakage stops or replace packing | | | |
| Valve fails pressure test | Valve is not completely closed | Close valve completely | | | |
| or a leak present in the line | Debris trapped between plug and seat | Throttle valve from fully closed to approximately 25% open several times under line flow to clear debris. If unsuccessful follow instructions for disassembly and remove debris | | | |
| | Rubber plug or metal seat is damaged | Consult VSI for disassembly procedures to inspect for damage. If present replace damaged parts. | | | |

9/5/23, 8:53 PM



Department of State / Division of Corporations / Search Records / Search by Entity Name /

Detail by Entity Name

Florida Profit Corporation
DAVID MANCINI & SONS, INC.

Filing Information

 Document Number
 P10000086044

 FEI/EIN Number
 27-3716806

 Date Filed
 10/20/2010

 Effective Date
 10/20/2010

State FL

Status ACTIVE

Last Event AMENDMENT
Event Date Filed 03/23/2015
Event Effective Date NONE

Principal Address

2601 Wiles Road

Pompano Beach, FL 33073

Changed: 02/03/2020

Mailing Address

2601 WILES ROAD

POMPANO BEACH, FL 33073

Changed: 05/15/2017

Registered Agent Name & Address

MANCINI, DAVID A 2601 WILES ROAD

POMPANO BEACH, FL 33073

Address Changed: 05/15/2017

Officer/Director Detail
Name & Address

Title P

MANCINI, DAVID 1875 N HIBISCUS DRIVE Miami, FL 33181

CAM #25-0539 Exhibit 4 Page 132 of 205 Title SECR

MANCINI, DAVIDA, Jr. 1875 N. HIBISCUS DRIVE MIAMI, FL 33181

Title VP

Mancini, David A, Jr. 1875 N HIBISCUS DRIVE Miami, FL 33181

Title VP

MANCINI, RICHARD 2601 WILES ROAD POMPANO BEACH, FL 33073

Title Vice-President

Angarita, Fabio 2601 Wiles Road Pompano Beach, FL 33073

Annual Reports

| Report Year | Filed Date |
|-------------|------------|
| 2022 | 02/01/2022 |
| 2022 | 02/22/2022 |
| 2023 | 03/01/2023 |

Document Images

| 03/01/2023 ANNUAL REPORT | View image in PDF format |
|----------------------------------|--------------------------|
| 02/22/2022 AMENDED ANNUAL REPORT | View image in PDF format |
| 02/01/2022 ANNUAL REPORT | View image in PDF format |
| 01/29/2021 ANNUAL REPORT | View image in PDF format |
| 02/03/2020 ANNUAL REPORT | View image in PDF format |
| 01/24/2019 ANNUAL REPORT | View image in PDF format |
| 01/16/2018 ANNUAL REPORT | View image in PDF format |
| 05/15/2017 Reg. Agent Change | View image in PDF format |
| 02/02/2017 ANNUAL REPORT | View image in PDF format |
| 01/26/2016 ANNUAL REPORT | View image in PDF format |
| 10/15/2015 AMENDED ANNUAL REPORT | View image in PDF format |
| 03/23/2015 Amendment | View image in PDF format |
| 01/13/2015 ANNUAL REPORT | View image in PDF format |
| 09/30/2014 AMENDED ANNUAL REPORT | View image in PDF format |
| 01/17/2014 ANNUAL REPORT | View image in PDF format |
| 03/13/2013 ANNUAL REPORT | View image in PDF format |

CAM #25-0539 Exhibit 4 Page 133 of 205 02/24/2012 -- ANNUAL REPORT 02/22/2011 -- ANNUAL REPORT 10/20/2010 -- Domestic Profit

View image in PDF format View image in PDF format View image in PDF format

Florida Department of State, Division of Corporations



2601 Wiles Rd Pompano Beach Florida 33073 PH: (954) 977-3556 FAX: (954) 944-2040

CONTRACT: P12384

PROJECT: Coral Ridge Force Main Replacement CONTRACTOR: David Mancini & Sons, Inc. (DMSI)

DATE: 2/4/2025

DESCRIPTION: Additional cost related to Repump B connection with 36-Inch above ground bypass no includeded on the scope of work

on the DCP.

SUMMARY OF DIRECT COSTS

| 1 | TOTAL LABOR | \$ 85,527.96 |
|---|--|------------------|
| 2 | TOTAL EQUIPMENT | \$ 71,374.80 |
| 3 | TOTAL MATERIAL | \$ 420,467.87 |
| 4 | TOTAL SUBCONTRACTORS | \$ 126,980.61 |
| | SUBTOTAL | \$ 704,351.24 |
| 5 | CONTRACTOR'S MARKUP 8.00% | \$ 56,348.10 |
| 7 | GENERAL CONDITIONS [Items (3+4+5)/Construction Cost] 5.35% | \$ 37,682.79 |
| 8 | TAXES | \$ 25,278.07 |
| | Total Direct Cost | \$ 798,382.13 |

SUMMARY OF TIME IMPACT (REQUEST FOR ADDITIONAL TIME)

DMSI reserves the right to claim for additional contract time if the critical path is affected after approval.

Submitted by:

a Suarez 02/04/2025

Alejandra Suarez Assistant Project Manager David Mancini and Sons, Inc

Approved by:

Cyrill Garcia Project Manager City of Fort Lauderdale



LABOR COSTS

| SUMMARY - LABOR COSTS | | |
|-----------------------|-------------|-----------------|
| SUPERVISION | | \$ 20,175.00 |
| CREW | | \$ 28,545.00 |
| LABOR BURDEN (75.55%) | | \$ 36,807.96 |
| | TOTAL LABOR | \$ 85,527.96 |

| LABOR BURDEN MULTIPLIER (LBM) | 58.20% |
|--|--------|
| Social Security Contributions & Excise and Payroll | 6.20% |
| Medicate Rate | 1.45% |
| Unemployment | 5.49% |
| Workmens Compensation | 7.16% |
| Health Benefits | 14.20% |
| Retirement Benefits | 23.70% |
| VACATION MULTIPLIER (VM) | 13.00% |
| Sick Leave (1 week out of 52) | |
| Vacation (2 weeks out of 52) | |
| Holiday Pay (1 week out of 52) | |
| Insurance Schedule | 4.35% |
| General Liability Insurance | 4.35% |

| Total Labor Burden Rate | 75.55% |
|--------------------------|---------|
| Total Labor Burdell Nate | 73.33/0 |

| SUPERVISION | Но | ourly Rate (Salary) | Hourly Overtime Rate | Hours (Salary) | Hours Overtime | Total Cost |
|-------------------|----|---------------------|----------------------|----------------|-----------------------|-----------------|
| Project Manager | \$ | 60.00 | | 30.00 | | \$ 1,800.00 |
| Superintendent | \$ | 55.00 | | 75.00 | | \$ 4,125.00 |
| Crew Foreman | \$ | 47.50 | | 150.00 | | \$ 7,125.00 |
| Crew Foreman | \$ | 47.50 | | 150.00 | | \$ 7,125.00 |
| TOTAL SUPERVISION | | | | | | \$ 20,175.00 |

| MAINLINE CREW - DMSI | Hourly Rate | Hourly Overtime Rate | Hours | Hours Overtime | Total Cost | |
|----------------------|--------------------|-----------------------------|--------|----------------|-------------------|--|
| Excavator Operator | \$ 30.00 | \$ 45.00 | 120.00 | 30.00 | \$ 4,950.00 | |
| Loader Operator | \$ 27.00 | \$ 40.50 | 120.00 | 30.00 | \$ 4,455.00 | |
| Pipe Layer | \$ 28.00 | \$ 42.00 | 120.00 | 30.00 | \$ 4,620.00 | |
| Skilled Laborer | \$ 24.00 | \$ 36.00 | 120.00 | 30.00 | \$ 3,960.00 | |
| Skilled Laborer | \$ 24.00 | \$ 36.00 | 120.00 | 30.00 | \$ 3,960.00 | |
| Laborer | \$ 20.00 | \$ 30.00 | 120.00 | 30.00 | \$ 3,300.00 | |
| Laborer | \$ 20.00 | \$ 30.00 | 120.00 | 30.00 | \$ 3,300.00 | |
| TOTAL CREW | | | | | \$ 28,545.00 | |

| ASSEMBLY CREW - DMSI | | Hourly Rate | Hourly Overtime Rate | Hours | Hours Overtime | Total Cost |
|----------------------|----|--------------------|----------------------|--------|----------------|-----------------|
| Excavator Operator | \$ | 30.00 | \$ 45.00 | 120.00 | 30.00 | \$ 4,950.00 |
| Loader Operator | \$ | 27.00 | \$ 40.50 | 120.00 | 30.00 | \$ 4,455.00 |
| Pipe Layer | \$ | 28.00 | \$ 42.00 | 120.00 | 30.00 | \$ 4,620.00 |
| Skilled Laborer | \$ | 24.00 | \$ 36.00 | 120.00 | 30.00 | \$ 3,960.00 |
| Skilled Laborer | \$ | 24.00 | \$ 36.00 | 120.00 | 30.00 | \$ 3,960.00 |
| Laborer | \$ | 20.00 | \$ 30.00 | 120.00 | 30.00 | \$ 3,300.00 |
| Laborer | \$ | 20.00 | \$ 30.00 | 120.00 | 30.00 | \$ 3,300.00 |
| TOTAL CREW | • | | | | • | \$ 28,545.00 |

EQUIPMENT, MATERIAL & SUBCONTRACTOR COSTS



| EQUIPMENT COSTS - RENTAL RATE BLUE BOOK | | | | | | |
|--|---|--------------|---------------|------------|-----------|--|
| Skid- Steer | | Working Rate | Working Hours | Total Cost | | |
| CAT 272D | Ç | 84.69 | 150.00 | \$ | 12,703.50 | |
| Loaders | | | | | | |
| CAT 938M | Ç | 65.42 | 150.00 | \$ | 9,813.00 | |
| Excavators | | | | | | |
| CAT 308 | Ç | 68.14 | 150.00 | \$ | 10,221.00 | |
| CAT 325 | Ş | 133.24 | 150.00 | \$ | 19,986.00 | |
| Trucks | | | | | | |
| Pick-Up Truck - Chevy Silverado 2500 - Foreman | Ç | 23.39 | 60.00 | \$ | 1,403.40 | |
| Pick-Up Truck - Chevy Silverado 2500 - Foreman | Ş | 23.39 | 60.00 | \$ | 1,403.40 | |
| Miscellaneous Equipment | | | | | | |
| Trash Pump | Ç | 9.83 | 150.00 | \$ | 1,474.50 | |
| Steel Plates - 8'x20' (6 On Site \$60 per plate PER DAY) | Ş | 360.00 | 15.00 | \$ | 5,400.00 | |
| Air Compressor Sullair 375 | Ş | 59.80 | 150.00 | \$ | 8,970.00 | |
| TOTAL EQUIPMENT | | | | \$ | 71,374.80 | |

| MATERIAL COSTS | | | | | |
|----------------------------|-----|------|------------------|----|------------|
| Material Description | QTY | Unit | Unit Cost | 1 | otal Cost |
| 36" FLGXPE DIP 6' | 1 | EA | \$ 9,988.24 | \$ | 9,988.24 |
| 36" FLGXPE DIP 4' | 1 | EA | \$ 7,641.18 | \$ | 7,641.18 |
| 36" FLGXFLG DIP 2' | 2 | EA | \$ 8,089.41 | \$ | 16,178.82 |
| 36" MEGA FLANGE REST ADPT | 1 | EA | \$ 3,708.38 | \$ | 3,708.38 |
| 36" FLG 90 BEND | 2 | EA | \$ 14,002.40 | \$ | 28,004.80 |
| 36" FLG ACC KIT NEOPRENE | 10 | EA | \$ 1,158.83 | \$ | 11,588.30 |
| 36" FLG PLUG VALVE W/GEAR | 1 | EA | \$ 49,916.85 | \$ | 49,916.85 |
| 36" FLG CHECK VALVE | 1 | EA | \$ 48,348.31 | \$ | 48,348.31 |
| 2" BALL CORP | 1 | EA | \$ 315.00 | \$ | 315.00 |
| 2" X 4" SS NIPPLE | 1 | EA | \$ 14.00 | \$ | 14.00 |
| 36"X2" DBL STRP SS | 1 | EA | \$ 720.00 | \$ | 720.00 |
| 2" SEWAGE AIR RELEASE VLV | 1 | EA | \$ 1,040.00 | \$ | 1,040.00 |
| 42" MJ LONG SLEEVE | 1 | EA | \$ 8,338.99 | \$ | 8,338.99 |
| 42" MEGALUG DIP W/ACC | 10 | EA | \$ 2,417.08 | \$ | 24,170.80 |
| 42" MJ 45 BEND | 1 | EA | \$ 11,719.18 | \$ | 11,719.18 |
| 42" X 36" MJ TEE | 1 | EA | \$ 19,636.05 | \$ | 19,636.05 |
| 36" MEGALUG DIP W/ACC | 5 | EA | \$ 1,693.30 | \$ | 8,466.50 |
| 36" MJ 90 BEND | 1 | EA | \$ 9,596.14 | \$ | 9,596.14 |
| 36" MJ PLUG VALVE | 1 | EA | \$ 50,939.33 | \$ | 50,939.33 |
| AR TOU PLUG VALVEY | 1 | EA | \$ 103,264.00 | \$ | 103,264.00 |
| 72" ARV MANHOLE / TOP SLAB | 1 | EA | \$ 2,648.00 | \$ | 2,648.00 |
| 690-AH-M PL R/C | 1 | EA | \$ 4,225.00 | \$ | 4,225.00 |
| SURTAXX人人人人人 | | • | \$ 50.00 | \$ | 50.00 |
| SUBTOTAL | | | | \$ | 420,467.87 |
| TAXES | | | | \$ | 25,278.07 |
| TOTAL MATERIAL | | | | \$ | 445,745.94 |

| SUB | CONTRACTORS COSTS | | | | | |
|-------|--------------------------|-----|------|---------------------|-------|--------------|
| Descr | ption | QTY | Unit | Unit Cost Total Cos | | Total Cost |
| CMA | | 1 | LS | \$ 62,400 | 00 \$ | \$ 62,400.00 |
| A&N | 1 Brothers Concrete | 1 | LS | \$ 7,600 | 00 \$ | 5 7,600.00 |
| SUP | RMIX Flowable Fill 18 CY | 1 | LS | \$ 3,228 | 40 \$ | 3,228.40 |
| Ran | eline (IF NEEDED) | 1 | LS | \$ 50,096 | 00 \$ | \$ 50,096.00 |
| MW | PUMPS (IF NEEDED) | 1 | LS | \$ 3,656 | 21 \$ | 3,656.21 |
| TOT | AL SUBCONTRACTOR | | | | \$ | 126,980.61 |

Where is the ARV and manhole?



P12383 & P12384 – CORAL RIDGE FORCE MAIN REPLACEMENT PROJECT

LABOR BURDEN BREAKDOWN

- A. 6.20 % SOCIAL SECURITY RATE
- B. 1.45 % MEDICARE RATE
- C. 5.49 % UNEMPLOYMENT
- D. 7.16 % WORKERS COMP
- E. 4.35 % GENERAL LIAB
- F. 14.20 % HEALTH INS
- G. 23.70 % RETIREMENT
- H. 13.00 % VAC/HOLIDAY

Burden Rate: 75.55%

DMSI offers our employees the following paid-off time:

- (2) Weeks Paid Vacation
- (3) Weeks Holiday paid, including time between Christmas and New Year
- (1) Week for Sick Time

Based on this, a DMSI employee works 46 weeks a year and gets paid for 52. Therefore, the yearly burden for General Liability, Health Insurance, Retirement, and vacation Holiday Time must be INCREASED based on the calculation below to cover the six non-revenue weeks (for DMSI), whereas DMSI compensates the employee.

Items A-C Above are standard rates through the federal government and the State of Florida.

Item D – Is DMSI's Workman's Comp rate for Sewer when this project was bid and the Contract executed.

Item E – Is DMSI's G/L rate (1.89%) plus 2.46% to cover the non-revenue paid weeks (See Below) (\$21.87x40x6=\$5,248.80x1.89%=\$992.02/\$21.87x40x46 or an additional 2.46%)

Item F – Insurance burden is calculated using the average hourly employee rate multiplied by 40/hrs. per week for 46 weeks worked, dividing this by the average cost of yearly insurance premiums for hourly employees. (Average hourly rate \$21.87x 40 hours x 46 weeks/year divided by the average cost of SGL coverage 476.18/mo. x 12)

Item G - (RETIREMENT 11% + Bonus, which is merely part of the employee's yearly compensation package, of 10% plus the average hourly rate $$21.87 \times 40 \times 6$$ weeks non-working = \$5,248.80, we pay 21% of this income as retirement benefit so we need to add \$1,102.25 to 46 weeks of working to cover these costs or an additional 2.7%)



ITEM H - (6weeks/46weeks of working to cover costs of vacation and holiday)

By signing below, I certify that the information provided is true and correct to the best of my knowledge.

Sincerely,

Fabio Angarita

Vice president


David Mancini and Sons, Inc


Note:


Our financial statement is proprietary and confidential, so we do not wish it to be made public. Our records are available for your appropriate staff to review at our Pompano Beach, FL office.


Please advise us 48 hours in advance.


If you have any questions about our financial information, please call our Financial Controller, Kimberley Weldon, at (954) 977-3556.













www.equipmentwatch.com


All prices shown in US Dollars (\$)

February 6, 2024 Rental Rate Blue Book®

Caterpillar 308E2 CR (disc. 2020)

Crawler Mounted Hydraulic Excavators

Size Class: **6.5 - 8.4 mt** Weight:



Configuration for 308E2 CR (disc. 2020)

Horsepower Power Mode 65.0 hp Operating Weight 18519 lbs Diesel

Blue Book Rates

** FHWA Rate is equal to the monthly ownership cost divided by 176 plus the hourly estimated operating cost.

| | Ownership Costs | | | | Estimated Operating Costs | FHWA Rate** |
|--|-----------------|----------------|--------------|-------------|------------------------------|-------------|
| | Monthly | Weekly | Daily | Hourly | Hourly | Hourly |
| Published Rates | USD \$6,930.00 | USD \$1,940.00 | USD \$485.00 | USD \$73.00 | USD \$28.76 | USD \$68.14 |
| Adjustments | | | | | | |
| Region (100%) | - | - | - | - | | |
| Model Year (2020: 100%) | - | - | - | - 10 | | |
| Adjusted Hourly Ownership Cost (100%) | - | - | - | | | |
| Hourly Operating Cost (100%) | | | | | - | |
| Total: | USD \$6,930.00 | USD \$1,940.00 | USD \$485.00 | USD \$73.00 | USD \$28.76 | USD \$68.14 |

Non-Active Use Rates Hourly Standby Rate USD \$21.66 Idling Rate USD \$46.22

Rate Element Allocation

| Element | Percentage | Value |
|-----------------------------|------------|-------------------|
| Depreciation (ownership) | 30% | USD \$2,079.00/mo |
| Overhaul (ownership) | 45% | USD \$3,118.50/mo |
| CFC (ownership) | 15% | USD \$1,039.50/mo |
| Indirect (ownership) | 10% | USD \$693.00/mo |
| Fuel (operating) @ USD 4.15 | 23.78% | USD \$6.84/hr |

Revised Date: 1st quarter 2024

These are the most accurate rates for the selected Revision Date(s). However, due to more frequent online updates, these rates may not match Rental Rate Blue Book® Print. Visit the Cost Recovery Product Guide on our Help page for more information.

The equipment represented in this report has been exclusively prepared for DAVID MANCINI (dmancinijr@dmsi.co)



All prices shown in US Dollars (\$)

Rental Rate Blue Book® February 6, 2024

Caterpillar 325

Crawler Mounted Hydraulic Excavators

Size Class: 21.5 - 24.4 mt Weight:



Bucket Capacity 1.2 cu yd Horsepower 174 hp
Operating Weight 49604 lbs Power Mode Diesel

Blue Book Rates

** FHWA Rate is equal to the monthly ownership cost divided by 176 plus the hourly estimated operating cost.

| | | Ownership | Costs | | Estimated Operating Costs | FHWA Rate** |
|---------------------------------------|-----------------|----------------|----------------|--------------|------------------------------|--------------|
| | Monthly | Weekly | Daily | Hourly | Hourly | Hourly |
| Published Rates | USD \$14,760.00 | USD \$4,135.00 | USD \$1,035.00 | USD \$155.00 | USD \$49.38 | USD \$133.24 |
| Adjustments | | | | | | |
| Region (100%) | - | - | - | - | | |
| Model Year (2024: 100%) | - | - | - | - 40 | | |
| Adjusted Hourly Ownership Cost (100%) | - | - | - | | | |
| Hourly Operating Cost (100%) | | | | | - | |
| Total: | USD \$14,760.00 | USD \$4,135.00 | USD \$1,035.00 | USD \$155.00 | USD \$49.38 | USD \$133.24 |

Non-Active Use RatesHourlyStandby RateUSD \$46.13Idling RateUSD \$97.70

Rate Element Allocation

| Element | Percentage | Value |
|-----------------------------|------------|-------------------|
| Depreciation (ownership) | 30% | USD \$4,428.00/mo |
| Overhaul (ownership) | 45% | USD \$6,642.00/mo |
| CFC (ownership) | 15% | USD \$2,214.00/mo |
| Indirect (ownership) | 10% | USD \$1,476.00/mo |
| Fuel (operating) @ USD 4.15 | 28.03% | USD \$13.84/hr |

Revised Date: 1st quarter 2024

These are the most accurate rates for the selected Revision Date(s). However, due to more frequent online updates, these rates may not match Rental Rate Blue Book® Print. Visit the Cost Recovery Product Guide on our Help page for more information.



All prices shown in US Dollars (\$)

Rental Rate Blue Book® February 6, 2024

Caterpillar 938M

4-Wd Articulated Wheel Loaders

Size Class: 175 - 199 hp Weight:



Configuration for 938M

Horsepower 168.0 hp Operator Protection ROPS/FOPS

Power Mode Diesel

Blue Book Rates

** FHWA Rate is equal to the monthly ownership cost divided by 176 plus the hourly estimated operating cost.

| | | Ownership C | Costs | | Estimated Operating Costs | FHWA Rate** |
|---------------------------------------|----------------|----------------|--------------|-------------|------------------------------|-------------|
| | Monthly | Weekly | Daily | Hourly | Hourly | Hourly |
| Published Rates | USD \$6,410.00 | USD \$1,795.00 | USD \$450.00 | USD \$68.00 | USD \$29.00 | USD \$65.42 |
| Adjustments | | | | | | |
| Region (100%) | - | - | - | - | N.Y | |
| Model Year (2024: 100%) | - | - | - | | _ | |
| Adjusted Hourly Ownership Cost (100%) | - | - | - | X-O | | |
| Hourly Operating Cost (100%) | | | | | - | |
| Total: | USD \$6,410.00 | USD \$1,795.00 | USD \$450.00 | USD \$68.00 | USD \$29.00 | USD \$65.42 |

Non-Active Use Rates
Standby Rate
USD \$24.77
Idling Rate
USD \$49.38

Rate Element Allocation

| Element | Percentage | Value |
|-----------------------------|------------|-------------------|
| Depreciation (ownership) | 39% | USD \$2,499.90/mo |
| Overhaul (ownership) | 32% | USD \$2,051.20/mo |
| CFC (ownership) | 18% | USD \$1,153.80/mo |
| Indirect (ownership) | 11% | USD \$705.10/mo |
| Fuel (operating) @ USD 4.15 | 44.69% | USD \$12.96/hr |

Revised Date: 1st quarter 2024

These are the most accurate rates for the selected Revision Date(s). However, due to more frequent online updates, these rates may not match Rental Rate Blue Book® Print. Visit the Cost Recovery Product Guide on our Help page for more information.



All prices shown in US Dollars (\$)

Rental Rate Blue Book® February 6, 2024

GMC\CHEVY 2500

On-Highway Light Duty Trucks

Size Class: 300 hp & Over Weight: N/A



Configuration for 2500

Axle Configuration 4.0 x 2.0 Cab Type Crew Horsepower 310.0 hp Power Mode Diesel Ton Rating 3.0 / 4.0

Blue Book Rates

** FHWA Rate is equal to the monthly ownership cost divided by 176 plus the hourly estimated operating cost.

| | | Ownership (| Costs | | Estimated Operating Costs | FHWA Rate** |
|--|--------------|--------------|-------------|----------------------------------|------------------------------|-------------|
| | Monthly | Weekly | Daily | Hourly | Hourly | Hourly |
| Published Rates | USD \$710.00 | USD \$200.00 | USD \$50.00 | USD \$8.00 | USD \$19.36 | USD \$23.39 |
| Adjustments | | | | | _ | |
| Region (100%) | - | - | - | ₩. . () [×] | | |
| Model Year (2024: 100%) | - | - | - | - | | |
| Adjusted Hourly Ownership Cost (100%) | - | - | - | | | |
| Hourly Operating Cost (100%) | | | | | - | |
| Total: | USD \$710.00 | USD \$200.00 | USD \$50.00 | USD \$8.00 | USD \$19.36 | USD \$23.39 |

Non-Active Use Rates
Standby Rate
USD \$2.66
Idling Rate
USD \$19.45

Rate Element Allocation

| Element | Percentage | Value |
|-----------------------------|------------|-----------------|
| Lienient | reicemage | value |
| Depreciation (ownership) | 35% | USD \$248.50/mo |
| Overhaul (ownership) | 34% | USD \$241.40/mo |
| CFC (ownership) | 13% | USD \$92.30/mo |
| Indirect (ownership) | 18% | USD \$127.80/mo |
| Fuel (operating) @ USD 4.15 | 79.65% | USD \$15.42/hr |

Revised Date: 1st quarter 2024

These are the most accurate rates for the selected Revision Date(s). However, due to more frequent online updates, these rates may not match Rental Rate Blue Book® Print. Visit the Cost Recovery Product Guide on our Help page for more information.



All prices shown in US Dollars (\$)

Rental Rate Blue Book® February 6, 2024

Sullair 375HDPQCA

Portable Rotary Screw Air Compressors

Size Class: 250 - 599 cu ft/min Weight: 4150 lbs



Configuration for 375HDPQCA

Air Delivery Rating 375.0 cu ft/min Horsepower 130.0 Power Mode Diesel

Blue Book Rates

** FHWA Rate is equal to the monthly ownership cost divided by 176 plus the hourly estimated operating cost.

| | | Ownership O | Costs | | Estimated Operating Costs | FHWA Rate** |
|---------------------------------------|----------------|----------------|--------------|------------------|------------------------------|-------------|
| | Monthly | Weekly | Daily | Hourly | Hourly | Hourly |
| Published Rates | USD \$4,235.00 | USD \$1,185.00 | USD \$295.00 | USD \$44.00 | USD \$35.74 | USD \$59.80 |
| Adjustments | | | | | | |
| Region (100%) | - | - | - | | · · | |
| Model Year (2024: 100%) | - | - | - | √ - () ` | | |
| Adjusted Hourly Ownership Cost (100%) | - | - | - | | | |
| Hourly Operating Cost (100%) | | | | | - | |
| Total: | USD \$4,235.00 | USD \$1,185.00 | USD \$295.00 | USD \$44.00 | USD \$35.74 | USD \$59.80 |

Non-Active Use RatesHourlyStandby RateUSD \$7.94Idling RateUSD \$43.46

Rate Element Allocation

| Element | Percentage | Value |
|-----------------------------|------------|-------------------|
| Depreciation (ownership) | 15% | USD \$635.25/mo |
| Overhaul (ownership) | 67% | USD \$2,837.45/mo |
| CFC (ownership) | 10% | USD \$423.50/mo |
| Indirect (ownership) | 8% | USD \$338.80/mo |
| Fuel (operating) @ USD 4.15 | 54.28% | USD \$19.40/hr |

Revised Date: 1st quarter 2024

These are the most accurate rates for the selected Revision Date(s). However, due to more frequent online updates, these rates may not match Rental Rate Blue Book® Print. Visit the Cost Recovery Product Guide on our Help page for more information.

All American Precast

1300 NW 4 Street Homestead, FL 33030 US +13054182795 ADMIN@ALLAMERICANPRECAST.COM www.allamericanprecast.com



Estimate

ADDRESS

DAVID MANCINI & SONS INC

2601 Wiles Road

Pompano Beach, FL 33073

SHIP TO

CITY OF FT LAUDERDALE

PROJECT # 12384

NE 38th ST 42-INCH FM MAIN REPLACEMENT

FORT LAUDERDALE FL

ESTIMATE # 12206D1 **DATE** 08/07/2024

P.O. NUMBER FLGOLF-06

SALES REP

ΑI

JOB NAME

PROJ 12384 NE 38th ST

| ACTIVITY | QTY | RATE | AMOUNT |
|---|-----|----------|------------|
| 60" RD ARV MANHOLE 60" RD ARV MANHOLE W/ TOP SLAB & USF # 690-AH-M "CITY OF FT LAUDERDALE ARV SEWER" R/C. | 7 | 6,378.00 | 44,646.00T |
| Castings NAME CHANGE "CITY OF FT LAUDERDALE" ARV SEWER ON LID. | 1 | 2,500.00 | 2,500.00 |
| Castings 60" RD ARV MANHOLE W/ TOP SLAB. Add on 05/09/2024 | 2 | 2,153.00 | 4,306.00T |
| 72" RD ARV MANHOLE 72" RD ARV MANHOLEW/ TOP SLAB. | 3 | 2,648.00 | 7,944.00T |
| Castings TEMP "M" COVERS | 12 | 150.00 | 1,800.00 |
| Castings 690-AH-M PL R/C. | 5 | 4,225.00 | 21,125.00 |
| 02 Delivery included. Any paint / coatings not quoted. Casting lead time 6 to 8 weeks. Ram-nek \$90 per box as needed. | 1 | 0.00 | 0.00 |
| ***Note Note: All American Precast Manufacturing, Corp is a material supplier. We are to be paid per invoice or statement, not per customer's contract draws. | 1 | 0.00 | 0.00 |

1.Proposals are valid for up to 30 calendar days, pricing may be subject to change after 30 days. All American Precast manufacturing, Corp reserves the right to withdraw proposal. Engineering fees if required must be requested.



Date 01/14/25

Customer David Mancini & Sons 2601 Wiles Rd

Deerfield Beach, 33073

Coral Ridge Bypass TBD

Contact Ryan Kaltz Phone Email

Term 4 week

PO: Pending

| Qty | Item | Day | Week | 4 Week | 4 week |
|-----|-----------------------------|---------|---------|----------|------------|
| 100 | 24" Steel Pipe Per Ft | \$1.67 | \$5.00 | \$15.00 | \$1,500.00 |
| 3 | 24" Flange Elbow 90 | \$27.78 | \$83.33 | \$250.00 | \$750.00 |
| 1 | Misc. Nuts, Bolts, Silicone | \$19.44 | \$58.33 | \$175.00 | \$175.00 |

TOTAL RENTAL \$2,425.00

| Services | Item | Price | Total |
|----------|----------|----------|----------|
| 2 | Delivery | \$250.00 | \$500.00 |
| 2 | Pick up | \$250.00 | \$500.00 |

Services Total \$1,000.00

\$3,425.00 Subtotal Env. Fee \$24.25 **Estimated Tax** \$206.96 \$3,656.21 Estimated Total*

*This is an estimate. Actual site conditions can vary which may effect

the final pricing.

Customer Responsibilities:

Point of discharge.

Project

Fueling, unless otherwise noted by contractor.

Power source, materials and labor for electric units.

Heavy equipment for loading , unloading, set up and tear down of equipment $\left(U.O.N\right)$

Discharge Permit and fees.

Monitoring of Dewatering Equipment

Ballast Rock for turbidity control and stability if needed.

Cleaning of sediment tank/s



FEL-POMPANO BEACH WW #125 1950 NW 18TH STREET POMPANO BEACH, FL 33069-1394

Phone: 954-973-8100 Fax: 954-917-3134 Deliver To:

From: Matt Briggle

matt.briggle@ferguson.com

Comments:

Page 1 of 2

22:05:49 OCT 02 2024

FEL-POMPANO BEACH, FL WW #125

Price Quotation
Phone: 954-973-8100
Fax: 954-917-3134

 Bid No:
 B574476
 Cust Phone:
 954-977-3556

 Bid Date:
 10/02/24
 Terms:
 NET 10TH PROX

Quoted By: MB

Customer: DAVID MANCINI & SONS INC Ship To: DAVID MANCINI & SONS INC

2601 WILES ROAD 2601 WILES ROAD

CORAL RIDGE FM REPLACEMENT
POMPANO BEACH, FL 33073

CORAL RIDGE FM REPLACEMENT
POMPANO BEACH, FL 33073

Cust PO#: Job Name: CORAL RIDGE FM REPLACEMEN

| Item | Description | Quantity | Net Price | UM | Total |
|----------------|--------------------------------|----------|------------|----|-------------|
| MJLSP4LA42 | 42 MJ C153 P-401 LONG SLV L/A | 1 | 8338.990 | EA | 8338.99 |
| MJ4P4LA42 | 42 MJ C153 P-401 45 BEND L/A | 1 | 11719.180 | EΑ | 11719.18 |
| D118MJ36 | 36 MJ N/LUBE PLUG VLV L/A | 1 | 50939.330 | EA | 50939.33 |
| SP-MJPLUGVLV42 | 42 MJ PLUG VALVE - SEE SPEC | 2 | 103264.000 | EA | 206528.00 |
| P-MJTLA4236 | 42X36 MJ TEE C153 CL | 1 | 19636.050 | EA | 19636.05 |
| 1J9P4LA36 | 36 MJ C153 P-401 90 BEND L/A | 1 | 9596.140 | EA | 9596.14 |
| PPP436P | 36X4'0 FLGXPE P-401 BT DI SPL | 2 | 7641.180 | EA | 15282.36 |
| FPP436K | 36X2'0 FLGXFLG P-401 BT DI SPL | 2 | 8089.410 | EA | 16178.82 |
| PPP436U | 36X6'0 FLGXPE P-401 BT DI SPL | 1 | 9988.240 | EA | 9988.24 |
| 213600 | 36 MEGAFLANGE FLG ADPT | 2 | 3708.380 | EA | 7416.76 |
| 9P436 | 36 DI 125# FLG P-401 90 BEND | 2 | 14002.400 | EA | 28004.80 |
| P-VF36PV | 36 FLG PLUG VLV | 1 | 49916.850 | EA | 49916.85 |
| P-VFCV36 | 36 FLG CHK VLV | 1 | 48348.310 | EA | 48348.31 |
| SLDE42 | 42 DI MJ WDG RTNR GLAND *ONEL | 10 | 2417.080 | EA | 24170.80 |
| SLDE36 | 36 DI MJ WDG REST GLND *ONELO | 5 | 1693.300 | EA | 8466.50 |
| -SSFAP36 | 36 SS FLG ACC SET | 10 | 1158.830 | EΑ | 11588.30 |
| | | | | | |
| | ARV | | | | |
| FC2023830IP7 | 36X2 IP DBL STRP SS EPOX SDL | 1 | 720.000 | EΑ | 720.00 |
| FB17007NL | LF 2 MIP X FIP BALL CORP | 1 | 315.000 | EΑ | 315.00 |
| 18K | 2 SEWAGE AIR RELEASE VLV | 1 | 1040.000 | EΑ | 1040.00 |
| 46NKP | 2X4 SS S40 316L WLD NIP | 1 | 14.000 | EA | 14.00 |
| | | N | let Total: | | \$528208.43 |

 Net Total:
 \$528208.43

 Tax:
 \$31742.51

 Freight:
 \$0.00

 Total:
 \$559950.94

Page 151 of 205



500 West Cypress Creek Road, Suite 600 Fort Lauderdale, FL 33309

Office: +1 (954) 730-0707



December 12th, 2024

Fabio Angarita David Mancini & Sons, Inc 2601 Wiles Road Pompano Beach, FL 33073

Subject: City of Fort Lauderdale

P12384 Coral Ridge Force Main - Phase 4 RCO #2 - 36-inch Bypass at Repump B

Dear Mr. Angarita,

During the design of the force main in Phase 4 of the City of Fort Lauderdale Force Main Project (P12384), the City of Fort Lauderdale has requested that DMSI replace the existing 36-inch aboveground bypass at Repump B. The work required to install a new bypass necessitates additional design and inspection services from CMA that were not included in the original Design Citeria Package (DCP).

As requested by the City of Fort Lauderdale, CMA will include in our Phase 4 submittal plans a detailed design encompassing all necessary piping, valves, connection points, and pipe supports to meet City standards. This design will also incorporate the above-ground bypass under the same permit. Additionally, CMA will provide restoration design plans for all areas impacted during the construction of the bypass. To support the construction process, CMA will provide an inspector onsite during the installation of the 36-inch above-ground bypass. This request also includes the redesign of the connection location to the existing 42-inch influent line at the Master Repump station as discussed in the field with City staff.

Please note that CMA will not perform any modeling or flow calculations as part of this work. The design plans will incorporate the existing system and be replaced in kind.

This additional scope of work has resulted in unanticipated costs for CMA related to the design and construction inspection of the bypass and new connection locations to the existing force main system. The estimated total cost for these additional services is \$62,400.

Please feel free to contact me if you have any additional questions at +1 (561) 744-8282 or via email at vlocigno@chenmoore.com.

Respectfully submitted,

Vincent Locigno

Chen Moore and Associates Vincent Locigno, PE Project Engineer



Rangeline will provide the following Material:

| Quantity | Description | Unit Price | Total |
|----------|--|------------|------------|
| 1 | Night Work Option for the 42" Double Line stop Service | \$9,545.00 | \$9,545.00 |
| 1 | Night Work Option for the 42" Double Re-Stop Service | \$5,574.00 | \$5,574.00 |

Rangeline Group will perform the following Double Line Stop:

| Quantity | Size | Pipetype | Product | Double Line Stop With Bypass | Total | Line Stop Equipment Overnight charges after 7PM on 5th Day "When Equipment is on the Pipe" |
|----------|------|----------|------------|------------------------------------|-------------|--|
| 1 | 42" | DI | Force Main | \$84,520.00 | \$84,520.00 | \$1,500.00 Per Day, Per Line Stop |

Rangeline Group will perform the following Double Re-Stop:

| Quantity | Size | Pipetype | Product | Double Re- Stop With Bypass | Total | Line Stop Equipment Overnight charges after 7PM on 5th Day "When Equipment is on the Pipe" |
|----------|------|----------|------------|-----------------------------------|-------------|--|
| 1 | 42" | DI | Force Main | \$44,522.00 | \$44,522.00 | \$1,500.00 Per Day, Per Line Stop |

PLEASE NOTE: Rangeline will make every attempt to remove the completion plug and re-insert the line stopper through the existing fitting. If the completion plug cannot be removed, the existing line stop fitting will have to be abandoned and a new line stop fitting and location will be needed in order to shut the system down.

Note: Rangeline cannot guarantee a 100% shutdown due to debris, mineral deposits, solids and/or sediments in the pipe.

Prices are based on the following below:

- Rangeline will provide epoxy coated linestop fittings with stainless steel hardware for the double linestop services, and use existing and serviceable linestop fittings for the double re-stop services.
- If the project is cancelled after NON-AIS(standard) materials are ordered, there will be a restocking fee.
- Rangeline will provide (2) 24" 150# flanged outlets for customer to connect Bypass Piping to the 42" double line stop or double re-stop sets. Customer must provide and install all Bypass Piping and related materials.
- When equipment is placed on the pipeline system, whether the Re-Stop is in the main or not, per day charges will apply.
- Please allow (7 14 days) notice for scheduling after receipt of materials to ensure availability. Projects that require shorter lead times may incur additional charges.
- Contractor must encase each line stop fitting in concrete.
- If the type of pipe changes from what we have quoted above, prices and scheduling may vary. Contractor or Municipality is responsible for verifying the type of pipe and it's O.D.
- Rangeline may require a pre-construction meeting or site visit prior to scheduling any services.
- Normal daytime hours (7:00AM- 7:00 PM EST) Monday through Friday. Technician(s) will have a \$375.00 per hour after hours charge, portal-to-portal. Additional Expenses will be charged at our cost plus 20%.
- Rangeline will allow (3) Mobilizations/De-Mobilizations to the jobsite per double line stop and (2) Mobilizations/De-Mobilizations to the jobsite per double re-stop. Additional trips will be \$750.00 per trip. Mobilization charges are applied when the technician leaves the shop or jobsite to start or after completion of the project.

Rangeline Tapping Services
7256 Westport Place Ste A West Palm Beach, FL 33413



A & M Brothers Concrete Corp.

95 NE 12 Street Homestead Fl, 33030 Phone: (786) 296 5979

a.m.concrete@hotmail.com

CONTRACTOR: DAVID MANCINI & SONS INC.

Attn: Alejandra Suarez Email: ASuarez@dmsi.co PHONE: (786)-284-2268 COUNTY: BROWARD

PROJECT NAME: CORAL RIDGE ABOVE GROUND PIPE SUPPORT

PROPOSAL / CONTRACT
PROPOSAL VALID FOR 90 CALENDAR DAYS
CALENDAR DAYS
Date: FEBRUARY 04, 2025

| Item | Description | Unit | Unit price | Quantity | To | tal Amount |
|---------|--|------------------------------------|--------------------|------------|----|------------|
| 1 | 5' X 18" ABOVE GROUND PIPE SUPPORT WITH #5 REBAR 12" ON CENTER TOP AND BOTTOM EACH WAY | EACH | \$ 3,800.00 | 2 | \$ | 7,600.00 |
| | Note: Final Invoice base on Field measurements | | TOTAL | | \$ | 7,600.00 |
| P | RICE INCLUDES LABOR, MATERIALS, EQUIPMENT A | ND 3,00 | 0 REG OR 2,5 | 00 DOT PSI | | |
| | ffice, Inspections, Concrete Cylinder Test are NOT Included | - | ance of Traffic NC | | | |
| Fill Ma | terials, Grading and Base Preparation are NOT Included | Bond/Layout/As Built NOT Included. | | | | |
| Lime ro | ock Base and Subgrade are NOT Included. | Concrete Pump are NOT Included. | | | | |

PAYMENT TO A & M Brothers Concrete Corp. is due within 30 days of receipt of this invoice. Any payment not received timely, shall be subject to interest at the rate of 1.5 % per month. In the event of legal action is required to enforce this invoice, A & M Brothers Concrete shall be entitled to recover its attorneys' fees and costs.

ACCEPTANCE OF PROPOSAL/CONTRACT:

DAVID MANCINI & SONS

Signature

| The above prices, specifications and conditions are sat specified. Payment will be made as outlined above. | tisfactory and are hereby accepted. You are authorized to do the work as |
|--|--|
| Date | |
| | Name / Title |

CONFIDENTIAL







| Customer Name | David Mancini & Sons - Alejandra Suarez | Phone: 954-977-3556 | | |
|-----------------------|--|---------------------------|--------------------|--|
| Address | 2601 Wiles Road, Pompano Beach, FL 33073 | Fax: | | |
| Project Name | Coral Ridge FM Replacement - Proj 23-FL.GOLF | Cell: 305-775-5 | 340 | |
| Address | NE 50th Court & 15th Ave, Ft Lauderdale, 33334 | asuarez@dmsi.co | | |
| Mix Code | Description | U.O.M. | Price | |
| | * As Requested * | 0.0 | 1 1100 | |
| 06-FF-95 | FDOT FLOWABLE FILL EXCAVATABLE 100 PSI | Cubic Yard | \$173.00 | |
| 0011 00 | I BOTT EOWADEETTEE EXOAVATABLE 100 TO | Ouble Tura | Ψ17 0.00 | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | SERVICE CHARGES | | | |
| | Environmental Load Charge | Load | \$25.00 | |
| Currently | FUEL SURCHARGE - ADJUSTED WEEKLY 1/16/2025 | Load | \$32.20 | |
| 6:00am-12:30pm | Saturday Delivery Charge | Cubic Yard | TBD | |
| 6:00 pm-6:00 am | Plant Opening 4-HR Minimum Monday - Friday | FLAT | TBD | |
| SHORT257 | Minimum Load Charge - Less than 7 CY | Load | \$250.00 | |
| | Return Concrete Handling & Disposal Fee | Cubic Yard | \$35.00 | |
| | Order Cancellation Fee | FLAT | \$1,500.00 | |
| 1/6/2025 | Effective Date | Expiration Date | 3/31/2025 | |
| Escalation | TBD 7/1/2025 | | | |
| • | oust be accepted by written purchase order 30 calendar days from qu | • | · · | |
| Supermix at all times | s reserves the right to increase the quoted prices without notice that | reflect an increase in r | aw material costs, | |
| changes in marke | t conditions, or surcharges incurred by Supermix, and to cancel or d | efer any quote in the e | vent Supermix | |
| becomes delayed | or prevented by shortages or allocations of raw materials. Supermix | shall not be liable to Bu | uyer, any of its | |
| counterparti | es, or any third parties for damages as a result of any such price cha | nge, delay, or cancella | tion. | |
| Supermix | Peter Kaczorowski Office: 954.480.9333 Cell: 95 | 4.214.4937 | | |
| Representative | Account Manager Fax: 954.480.2893 Email: | pete@supermix.co | <u>om</u> | |
| Accorded by | - | Date: | | |

CAM #25-0539 Exhibit 4 Page 155 of 205

City of Fort Lauderdale

NE 38th Street 42-Inch FM and NE 19th Avenue 24-Inch FM Replacement

Submittal Name: SHOP DRAWINGS - CHECK VALVE



| 1. Date of Submission | 12/6/2024 |
|--|---|
| 2. Project Number | P12384 |
| 3. Project Name | NE 38th Street 42-Inch FM and NE 19th Avenue 24-Inch |
| | FM Replacement |
| Contractor Identification | 23-FL.GOLF-001 |
| a. Contractor | David Mancini and Sons, Inc |
| b. Supplier | |
| c. Manufacturer | N/A |
| d. Manufacturer or supplier representative | N/A |
| 5. Identification of the Product | EXB-12.0-P12384-02-1 |
| 6. Reference to Contract Drawing | D02 |
| 7. Reference to Specification Section Number, page and paragraphs. | Technical Specifications 2.03 |
| 8. Indication of Contractor's approval. | Approved by DMSI |
| 9. Contractor's Certification Statement. (Refer to paragraph 1.03.F.2) | "By this submittal, I hereby represent that I have determined and verified all field measurements, field construction criteria, materials, dimensions, catalog numbers and similar data and I have checked and coordinated each item with other applicable approved shop drawings and all Contract requirements." |
| 10. Identification of deviations from the Contract, if any. | |
| 11. Reference to previous submittal (for resubmittals). | |






AWWA C508 Swing Check Valves

<u>Index</u>

| Brochure | 1 |
|--|---|
| Design Standards | 3 |
| Pressure vs Temp Ratings | 4 |
| Technical Drawings | |
| 2"-48" Swing Check Valve AWWA C508 | |
| Standard Material of Construction Rubber Seated | 6 |
| Flanged w/ Outside Lever & Weight CVI Dimensions | 7 |
| 36" Check Valve Drawing with Materials | 8 |







2"-48" CVI BONDED SEAT SWING CHECK

BONDED SEAT SWING CHECK VALVE


VSI offers the simplified bonded seat type check valve for pump and lift stations where a standard duty valve is acceptable and external accessories are not required. It still exemplifies VSI's commitment to providing a quality product.

- Body seats are permanently bonded nonreplaceable, reducing possible leakage paths.
- Disc seats are replaceable by way of replacing the entire disc.
- The shaft extends only to one side, reducing seal friction and possible leakage paths.




SIMPLE INTERNALS

VSI Bonded Seat Swing Check Valves are built with simplicity in mind for use in general duty applications. They feature minimal internal hardware and robust coatings for long service life in many less demanding applications.



REPLACEABLE DISC

VSI Swing Check Valves incorporate a replaceable bonded seat, which can be removed without taking the valve out from the line. Simply remove the sealed cover, and change out the entire disc.



CAM #25-0539

Exhibit 4 VSI Waterworks Page 159 of 205 105 Alpha Drive, Alpharetta, GA 30004 T: 770.740.0800 F: 770.740.8777 E: sales@vsiwaterworks.com



DESIGN STANDARDS

| Size Range | 6"-48" Flanged End |
|-----------------|---------------------------|
| | |
| Construction | AWWA C508 |
| | ASME B16.34 |
| | API 600 |
| Coatings | AWWA C550* |
| Connections | ANSI B16.1 Class 125* |
| | ANSI B16.1 Class 250 |
| | ANSI B16.5 Class 150 |
| | ANSI B16.5 Class 300 |
| Lay Length | AWWA C508 Appendix A Full |
| | ISO 5752 |
| Classifications | 150 PSIG |
| | 175 PSIG |
| | 200 PSIG* |
| | 250 PSIG* |

American Water Works Association

*Standard Option




RESISTANCE GUIDE

| Designation | Common Names | Composition | Min/Max Temperature Range | General Properties | Resistant to: | Attached by: |
|-------------|-----------------------|---|------------------------------|--|---|--|
| EPDM | EPDM , EPM | Ethylene-propyl- ene-diene-Monomer | -4 0F/250F | Excellent ozone, chemical, and aging resistance. Poor resistance to petroleum-based fluids | Animal and vegetable oils, ozone, strong and oxidizing chemicals. | Mineral oils and solvents, aromatic hydrocarbons |
| NBR | NBR, Buna-N | Nitrile-butadiene | -30F/225F | Excellent resistance to petroleum-based fluids. Good physical properties | Many hydrocarbons, fats, oils, greases, hydraulic fluids, chemicals | Ozone, ketones, esters, aldehydes, chlorinated and nitro hydrocarbons |
| FPM | FPM, Viton® | Hexaflouroproply- ene-vinylidene fluoride | -10F/400F | Excellent oil and air resistances both at low-and high temperatures. Very good chemical resistance | All aliphatic, aromatic, and halogenated hydrocarbons, acids, animal and vegetable oils | Ketones, low-molec- ular-weight-esters and nitro containing compounds |
| PTFE | PTFE, Teflon® | Polytetrafluoro-eth- ylene | -100F/450F | Excellent abrasion resistance and chemically inert | Acids, harsh inorganic and organic chemicals, oils, oxidizing agents, and solvents | Molten alkali metals and fluorine at high temperatures |



PRESSURE/TEMPERATURE RATINGS




In determining field pressure ratings for Series CVI Check Valves that are constructed of Ductile Iron the above chart should be used. Pressure cast on valve represents maximum seating pressure; maximum hydrostatic pressure is temperature dependent, and may be higher than nominal pressure rating.



CAM #25-0539 Exhibit 4 Page 161 of 205 to AWWA C508



MATERIALS OF CONSTRUCTION METAL SEATED VALVES



| ITEM | DESCRIPTION | MATERIAL OPTIONS | | | |
|----------------|----------------------|---------------------------------|--|--|--|
| | | | | | |
| 1 | BODY | DUCTILE IRON ASTM A536 65-45-12 | | | |
| | BODY SEAT RING | STAINLESS 304 ASTM A276 | | | |
| 2 | | STAINLES 316 ASTM A276 | | | |
| | KIIVO | BRONZE ASTM B62 | | | |
| | DICCCEAT | STAMLESS 304 ASTM A276 | | | |
| 3 | DISC SEAT RING | STAINLESS 316 ASTM A276 | | | |
| | / | BRONZE ASTM B62 | | | |
| 4 | DISC | DUCTILE IRON ASTM A536 65-45-12 | | | |
| 5 | WASHER | STEEL ASTM A36 | | | |
| | WETTED | STAINLESS ASTM F593 GROUP 1 | | | |
| 6 | WETTED HARDWARE | STAINLESS ASTM F593 GROUP 2 | | | |
| | MAKE | STEEL ASTM A325 TYPE 1 | | | |
| 7 / | ARM | DUCTILE IRON ASTM A536 65-45-12 | | | |
| 8 | SEAL | EPDM | | | |
| /° | | BUNA-N (NBR) | | | |
| 9 | COVER | SAME AS BODY (1) | | | |
| | EXTERIOR HARDWARE | STAINLESS ASTM F593 GROUP 1 | | | |
| 10 | | STAINLESS ASTM F593 GROUP 2 | | | |
| | | STEEL ASTM A325 TYPE 1 | | | |
| 11 | BEARING | PTFE | | | |
| 12 | KEY | STEEL ASTM A36 | | | |
| 10 | CHAFTCEAL | EPDM | | | |
| 13 | SHAFT SEAL | BUNA-N (NBR) | | | |
| 14 | RETAINER | SAME AS BODY (1) | | | |
| | | STAINLESS 304 ASTM A276 | | | |
| 15 | SHAFT | STAINLESS 316 ASTM A276 | | | |
| | | STAINLESS 17-4PH ASTM A693 | | | |
| 16 | ARM* | DUCTILE IRON ASTM A536 65-45-12 | | | |
| 17 | WEIGHT* | DUCTILE IRON ASTM A536 65-45-12 | | | |
| * IE ENLIIDDEN | | | | | |


^{*} IF EQUIPPED


CAM #25-0539 Exhibit 4 Page 162 of 205

NOTE: VSI offers two versions of the series CVI. All features are not applicable to all valves. Consult with VSI for more information.



MATERIALS OF CONSTRUCTION RUBBER SEATED





| ITEM | DESCRIPTION | MATERIAL OPTIONS | | | | |
|------|----------------------|--------------------------------------|-------|--|--|--|
| 1 | BODY | BODY DUCTILE IRON ASTM A536 65-45-12 | | | | |
| | | STAINLESS 304 ASTM A276 | | | | |
| 2 | BODY SEAT RING | STAINLESS 316 ASTM A276 | | | | |
| | KING | BRONZE ASTM B62 | | | | |
| | | EPDM | | | | |
| 3 | DISC SEAT | BUNA-N (NBR) | | | | |
| | | VITON (FPM) | | | | |
| 4 | DISC | DUCTILE IRON ASTM A536 65-45-12 | | | | |
| 5 | WASHER | STEEL ASTM A36 | | | | |
| | WETTER | STAINLESS ASTM F593 GROUP 1 | | | | |
| 6 | WETTED HARDWARE | STAINLESS ASTM F593 GROUP 2 | SS316 | | | |
| | | STEEL ASTM A325 TYPE 1 | | | | |
| 7 | ARM | DUCTILE IRON ASTM A536 65-45-12 | | | | |
| 8 | SEAL | EPDM | | | | |
| 0 | JEAL | BUNA-N (NBR) | | | | |
| 9 | COVER | SAME AS BODY (1) | | | | |
| | EVTEDIOD | STAINLESS ASTM F593 GROUP 1 | | | | |
| 10 | EXTERIOR HARDWARE | STAINLESS ASTM F593 GROUP 2 | SS316 | | | |
| | | STEEL ASTM A325 TYPE 1 | | | | |
| 11 | BEARING | PTFE BRONZE | | | | |
| 12 | KEY | STEEL ASTM A36 | | | | |
| 13 | SHAFT SEAL | EPDM | | | | |
| 13 | SHAFT SEAL | BUNA-N (NBR) | | | | |
| 14 | RETAINER | SAME AS BODY (1) | | | | |
| | | STAINLESS 304 ASTM A276 | | | | |
| 15 | SHAFT | STAINLESS 316 ASTM A276 | | | | |
| | | STAINLESS 17-4PH ASTM A693 | | | | |
| 16 | ARM* | DUCTILE IRON ASTM A536 65-45-12 | | | | |
| 17 | WEIGHT* | DUCTILE IRON ASTM A536 65-45-12 | | | | |

* IF EQUIPPED




CAM #25-0539


Exhibit 4 VSI Waterworks Page 163 of 205 105 Alpha Drive, Alpharetta, GA 30004 T: 770.740.0800 F: 770.740.8777 E: sales@vsiwaterworks.com




FLANGED WITH OUTSIDE LEVER AND WEIGHT

| SIZE | A | В | С | D | E | F | WEIGHT (LBS) |
|-----------------|------------------|-----------------|------------------|-----------------|---------------|-----------------|-----------------|
| 2" | 8.00 | 5.4 | 4.75 | 6.0 | 4 | 0.75 | 37 |
| 2.5" | 8.50 | 5.8 | 5.5 | 7.0 | 4 | 0.75 | 44 |
| 3" | 9.50 | 6.3 | 6.00 | 7.2 | 4 | 0.75 | 51 |
| 4" | 11.50 | 7.1 | 7.50 | 9.0 | 8 | 0.75 | 79 |
| 5" | 13.00 | 8.0 | 8.50 | 10.0 | 8 | 0.75 | 101 |
| 6" | 14.00 | 8.8 | 9.50 | 11.0 | 8 | 0.88 | 128 |
| 8" | 19.50 | 10.2 | 11.75 | 13.5 | 8 | 0.88 | 238 |
| 10" | 24.50 | 11.4 | 14.25 | 16.0 | 12 | 1.00 | 374 |
| 12" | 27.50 | 12.8 | 17.00 | 19.0 | 12 | 1.00 | 418 |
| 14" | 31.00 | 16.7 | 18.74 | 21.0 | 12 | 1.13 | 737 |
| 16" | 36.00 | 17.5 | 21.25 | 23.5 | 16 | 1.13 | 968 |
| 18" | 38.00 | 18.9 | 22.75 | 25.0 | 16 | 1.25 | 1500 |
| 20" | 42.00 | 20.7 | 25.00 | 27.5 | 20 | 1.25 | 1600 |
| 24" | 48.00 | 23.9 | 29.50 | 32.0 | 20 | 1.38 | 2600 |
| 30" | 56.00 | 28.6 | 36.00 | 38.8 | 28 | 1.38 | _ |
| 36" | 63.00 | 37.9 | 42.75 | 46.0 | 32 | 1.63 | - |
| 42" | 70.00 | 41.0 | 49.50 | 53.0 | 36 | 1.63 | - |
| 48" | 76.00 | 49.0 | 56.00 | 49.5 | 44 | 1.63 | _ |






CAM #25-0539 Exhibit 4 Page 164 of 205






BONDED SEAT SWING CHECK PART NUMBER MATRIX



EXAMPLE:

CVI08F-DDSB-PS1/0-Q

A 8" flanged Check valve with Ductile Iron body and disc, SS304 shaft, Bronze body seat, B. Vocettoga FE DE 12/9/24 NBR seals, PTFE bearings, SS304 hardware, AWWA C550 2-part epoxy coatings with outside lever & weight.



VSI Waterworks LLC

tel: 1 (770) 740 0800 fax: 1 (770) 740 8777

email: sales@vsiwaterworks.com



As part of a process of on-going product development, VSI reserves the right to amend or change specifications without prior notice. Published data may be subject to change. For the latest specific our website at www.vsiwatexmonke.com

Page 167 of 205

City of Fort Lauderdale

NE 38th Street 42-Inch FM and NE 19th Avenue 24-Inch FM Replacement


Submittal Name: SHOP DRAWINGS - PLUG VALVE




| 1. Date of Submission | 12/06/2024 |
|--|---|
| 2. Project Number | P12384 |
| 3. Project Name | NE 38th Street 42-Inch FM and NE 19th Avenue 24-Inch |
| | FM Replacement |
| Contractor Identification | 23-FL.GOLF-001 |
| a. Contractor | David Mancini and Sons, Inc |
| b. Supplier | |
| c. Manufacturer | N/A |
| d. Manufacturer or supplier representative | N/A |
| 5. Identification of the Product | EXB-12.0-P12384-20-0 |
| Reference to Contract Drawing | D02 |
| 7. Reference to Specification Section Number, page and paragraphs. | Technical Specifications 2.02 |
| 8. Indication of Contractor's approval. | Approved by DMSI |
| 9. Contractor's Certification Statement. (Refer to paragraph 1.03.F.2) | "By this submittal, I hereby represent that I have determined and verified all field measurements, field construction criteria, materials, dimensions, catalog numbers and similar data and I have checked and coordinated each item with other applicable approved shop drawings and all Contract requirements." |
| 10. Identification of deviations from the Contract, if any. | |
| 11. Reference to previous submittal (for resubmittals). | |



BY Vincent Locigno, PE DATE 12/9/24





to AWWA C517







IMPLEMENTATIONS

The Eccentric Plug valve is the industry standard for systems that will experience sludge or large particulate flow. VSI Eccentric Plug Valves are able to achieve an extremely high port area while keeping the operating time much lower than the traditional gate valve.

ECCENTRIC MOVEMENT

The most essential function of a valve is that it must isolate line flow. This action is easy to accomplish, but with traditional designs as pressure and size increase the torque required to close the valve increase exponentially.

To counteract this characteristic all VSI Eccentric Plug Valves incorporate an offset in the valve design. By offsetting the plug and shaft centerline from the valve body and pipe centerline a cam action is achieved. This action allows the plug to contact the valve body only in the last 5-10 degrees of movement. Through the rest of the valve motion the only torque transmitted to the operator will be from the low friction bearings and line force on the plug.

The cam action increases the seat force without increasing operator torque allowing for the use of more durable encapsulation materials that are often harder.



Offset

RESILIENT PLUG FACING

All VSI Eccentric Plug Valves are equipped as standard with a fully encapsulated resilient plug. By fully encapsulating the plug the service life of the valve is greatly extended by reducing corrosion of the plug. The resilient nature of the seat allows for driptight shut off. Should small solids become deposited upon the plug face, tight shut off is still guaranteed.



ADJUSTABLE/REPLACEABLE PACKING

The packing of the Series PVIF consists of multiple v-type packing rings and adjustable gland. The open bonnet on above ground valves allows for the adjustment and replacement of packing without removing the gearbox/operator

NUMEROUS ACTUATION OPTIONS

The standard ISO 5211 top mount allows VSI to offer a wide range of electric, pneumatic, hydraulic, failsafe, and other actuation packages

STANDARD LIFTING EYE

The lifting holes at all ends of the PVIF give a secure and easy attachment point that allows the valve to be confidently maneuvered into place on job sites. Equipped as a standard feature on all PVIF valves, making your install that much easier.

PAGE

FULL PORT DESIGN

The rectangular port is of a "Full Port" type with a flow area equal to the nominal pipe to maintain excellent free flow, high Cv values, and low head loss. Pigging with semi-rigid foam type pigs is possible.

MULTIPLE COATING OPTIONS

The standard 2-part heavy duty coating can be optioned to a wide variety of coatings as required by the project requirements such as NSF 61 listed coatings, ceramic reinforced resin, or coal-tar epoxy

FULLY ENCAPSULATED PLUG

The plug of the Series PVIF is fully encapsulated with resilient rubber covering every surface exposed to the line. Full encapsulation eliminates corrosion and minimizes the possibility of delamination or damage to the seat.



SAMPLE SPECIFICATION

1. FULL RECTANGULAR PORT PLUG VAVES FOR WATERWORKS SERVICE

- 1.1. This specification covers the design, manufacture, and testing of eccentric plug valves from 14 inch (350 mm) through 72 inch (1800 mm) under service pressure of up to 150 psig (1035 kPa).
- 1.2. Plug valves shall be resilient seated and of the quarter turn, non-lubricated, eccentric type.

2. <u>GOVERNING STANDARDS</u>

- 2.1. All eccentric plug valves shall be in full conformance with the design, manufacturing, and testing standards set forth by the American Water Works Association (AWWA) in Standard ANSI/AWWA C517.
- 2.2. When requested, manufacturer shall provide an Affidavit of Proof of Design Testing in accordance with AWWA C517.

CONNECTIONS

- 3.1. Flanged valves shall conform to all standards of ANSI B16.1, Class 125.
- 3.2. Mechanical joint valves shall conform to all standards of ANSI/AWWA C111/A21.11.

MARKINGS

- 4.1. Each valve shall be marked with the manufacturer's name, valve size, body material, and pressure rating cast into the body of the valve. Lettering shall be a minimum of 1/2 inch tall and project 1/10 inch from body.
- 4.2. All plug valves, except buried or submerged valves, shall be equipped with a type 304 or 316 stainless steel or Aluminum tag identifying body, plug, resilient seat, and stem material in addition to manufacturer's name, pressure rating, size, date of manufacturer, and date of testing.

5. DESIGN

- 5.1. Port areas of valves in relation to pipe areas shall not be less than 100%
- 5.2. Valves shall be equipped with a minimum 95% nickel seat directly bonded to a machined finished surface on valve body. Plated or removable seats are not acceptable.
- 5.3. Valve shall be equipped with a set of V-type stem packing with an adjustable gland. Valve stem packing shall be replaceable without removing the cover or bonnet of the valve.
- 5.4. Radial shaft bushings shall be supplied in the upper and lower bearing journals. Thrust bearings shall be supplied between the plug and body in both the upper and lower journal areas.
- 5.5. The valves shall be equipped with a mounting area for operators conforming to Manufacturers Standard Society(MMS) 101 or International Organization of Standardization(ISO) 52111. There shall be sufficient clearance to directly mount standardized operators with easily accessible fasteners.

6. MATERIALS

- 6.1. The valve body, cover, and bonnet if equipped shall be constructed of ASTM A536 Ductile Iron.
- 6.2. The plug shall be constructed of ASTM A536 Ductile Iron and shall be one piece. The resilient plug encapsulation shall conform to ASTM D429 testing.
- 6.3. Radial and thrust bearings shall be made of permanently lubricated type 316 stainless steel.
- 6.4. All submerged coatings shall conform to AWWA C550, be holiday free, and have a minimum total dry film thickness of 10 mils
- 6.5. All uncovered, submerged, or buried valves shall have type 304 or 316 stainless steel hardware unless specified.

7. OPERATORS

- 7.1. All manually operated valves 4 inch and larger shall be equipped with a worm gear actuator with position indicator. Direct 2" operator nut may be used when specified on 6" and under valves.
- 7.2. All actuators shall be permanently sealed and suitable for buried service.
- 7.3. All 2 inch square operating nuts, exposed hardware and shafts shall be made of corrosion resistant stainless steel.
- 7.4. All actuators equipped with handwheels shall have a maximum rim pull of 80lbs.

8. MANUFACTURER


- 8.1. Eccentric plug valves shall be VSI Series AWWAC517 as manufactured by Valve Solutions, Inc., Alpharetta, GA USA or approved equal.
- 8.2. All valves shall be warranted by manufacturer for a minimum of 12 months.


CAM #25-0539 Exhibit 4 Page 172 of 205





Materials of Construction





| Item | Description | Materials Available | Standard |
|------|----------------------------|-------------------------------|--------------------|
| 1 | Cover | Same as Body | |
| 2 | | Ductile Iron* | ASTM A536 65-45-12 |
| 2 | Body | Cast Iron | ASTM A126 Class B |
| _ | Dody | Stainless Steel 304 | ASTM A351 CF8 |
| | | Stainless Steel 316 | ASTM A351 CF8M |
| | | Ductile Iron* | ASTM A536 65-45-12 |
| 3 | Plug | Cast Iron | ASTM A126 Class B |
| J | Plug | Stainless Steel 304 | ASTM A351 CF8 |
| | | Stainless Steel 316 | ASTM A351 CF8M |
| | | Buna-N (NBR)* | |
| 4 | Plug Encapsulation | Chloroprene | |
| 4 | | EPDM | |
| | | Viton (FPM) | |
| 5 | Bonnet | Same as Body | |
| 6 | Gland | Same as Body | |
| 7 | Packing | Same as Plug Encapsulaton | |
| 8 | Exterior Hardware | Stainless 304* | ASTM F593/594 |
| | Exterior naruware | Stainless 316 | ASTM F593/594 S |
| 9 | Cover Seal | Same as Plug Encapsulation | |
| | | Stainless 316* | |
| 10 | Bearings | Stainless 304 | |
| 10 | bearings | Reinforced PFTE | |
| | | Bronze | |
| 11 | Grit Guard | Nylon | |
| 12 | Grit Seal | Same as Plug Encapsulation | |
| 13 | Lower Cover ^[2] | Same as Body | |
| | | Fusion Bonded Epoxy, Black* | |
| NS | Coating/Lining | Two-Part Epoxy | |
| | | Coal-Tar Epoxy | |
| NS | Tag | Aluminum* | |
| | | Stainless Steel | |
| NS | Assembly Lubricant | ANSI/NSF 61 Listed Silicone L | ubricant |
| NS | Operator | Varies | |

Additional material options available as special order.

- *Standard Material
- (1) Lower cover integral to body casting on 14"-24"
- (2) Lower journal cover standard on 30" and above


CAM #25-0539

Exhibit 4 VSI Waterworks
Page 173 of 205
1205 Alpha Drive, Alpharetta, GA 30004
T: 770.740.0800 F: 770.740.8777
E: sales@vsiwaterworks.com

Full Port Plug Valves to AWWA C517



Design Standards



*Standard Option



Resistance Guide


| Designation | Common Names | Composition | Min/Max Temperature Range | General Properties | Resistant to: | Attacked by: |
|-------------|---------------|---|------------------------------|---|---|--|
| NBR* | NBR, Buna-N | Nitrile-butadiene | -30F/225F | Excellent resistance to petroleum-based fluids. Good physical properties | Many hydrocarbons, fats, oils, greases, hydraulic fluids, chemicals | Ozone, ketones, esters, aldehydes, chlorinated and nitro hydrocarbons |
| FPM | FPM, Viton® | Hexaflouroproply- ene-vinylidene fluoride | -10F/400F | Excellent oil and air resistances both at low and high temperatures. Very good chemical resistance | All aliphatic, aromatic, and halogenated hydrocarbons, acids, animal and vegetable oils | Ketones, low molec- ular weight esters and nitro containing compounds |
| PTFE | PTFE, Teflon® | Polytetrafluoro-eth- ylene | -100F/450F | Excellent abrasion resistance and chemically inert | Acids, harsh inorganic and organic chemicals, oils, oxidizing agents, and solvents | Molten alkali metals and fluorine at high temperatures |
| EPDM | ЕРДМ, ЕРМ | Ethylene-propyl- ene-diene Monomer | -40F/250F | Excellent ozone, chemical, and aging resistance. Poor resistance to petroleum-based fluids | Animal and vegetable oils, ozone, strong and oxidizing chemicals. | Mineral oils and solvents, aromatic hydrocarbons |

CAM #25-0539 Exhibit 4 Page 174 of 205

E: sales@vsiwaterworks.com



Pressure/Temperature Ratings



In determining field pressure ratings for Series PVIF Plug Valves that are constructed of Ductile Iron the above chart should be used. Pressure cast on valve represents maximum seating pressure; maximum hydrostatic pressure is temperature dependent, and may be higher than nominal pressure rating.





Cold Working Pressure Rating


| SIZE | FORWARD CLOSEOFF W/GEAR | REVERSE CLOSEOFF W/ GEAR | FORWARD CLOSEOFF NUT AND/OR LEVER | REVERSE CLOSEOFF NUT AND/OR LEVER |
|------------|-------------------------------|--------------------------------|---|---|
| 14"+ CL125 | 150 PSI | 150 PSI | NA | NA |
| 14"+ MJ | 150 PSI | 150 PSI | NA | NA |
| 14"+ CL250 | 250 PSI | 150 PSI | NA | NA |




Flanged CL125 Barestem Dimensions









Vincent Locigno, PE DATE 12/9/24

| SIZE | A | В | C | D | E | F | G | H ⁽¹⁾ | J ⁽²⁾ | K ⁽³⁾ | L ⁽⁴⁾ |
|------|-------|------|-------|-------|------|-------|-------|------------------|-------------------------|------------------|------------------|
| 14" | 17.00 | 1.38 | 13.11 | 17.00 | 3.35 | 21.00 | 18.75 | 8 | 1.125 | 4 | 1-8UNC |
| 16" | 17.75 | 1.44 | 14.37 | 17.70 | 3.54 | 23.50 | 21.25 | 8 | 1.125 | 8 | 1-8UNC |
| 18" | 21.50 | 1.56 | 15.95 | 19.10 | 3.35 | 25.20 | 22.75 | 8 | 1.25 | 8 | 1.125-7UNC |
| 20" | 23.50 | 1.69 | 16.62 | 20.00 | 3.64 | 28.15 | 25.00 | 12 | 1.25 | 8 | 1.125-7UNC |
| 24" | 42.00 | 1.88 | 20.67 | 23.30 | 4.66 | 32.00 | 29.50 | 20 | 1.375 | 8 | 1.25-7UNC |
| 30" | 51.00 | 2.12 | 26,57 | 30.12 | 4.92 | 38.75 | 36.00 | 20 | 1.375 | 8 | 1.25-7UNC |
| 36" | 60.00 | 2.38 | 30.71 | 34.41 | 5.50 | 46.00 | 42.75 | 24 | 1.625 | 8 | 1.5-6UNC |
| 42" | 72.00 | 2.62 | 37.40 | 43.26 | 7.50 | 53.00 | 49.50 | 32 | 1.625 | 4 | 1.5-6UNC |
| 48" | 84.00 | 2.75 | 42.32 | 47.33 | 7.50 | 59.50 | 56.00 | 40 | 1.625 | 4 | 1.5-6UNC |


- (1) "H" represents the total number of through holes, per flange (2) "J" represents the size of the through holes for flange


- (3) "K" represents the total number of tapped holes, per flange (4) "L" represents the size of tapped holes and bolts used for flange


CAM #25-0539 Exhibit 4 Page 176 of 205




Mechanical Joint Barestem Dimensions











| SIZE | Α | В | C | D | E | F | G | H ⁽¹⁾ | J ⁽²⁾ |
|------|-------|------|-------|-------|------|-------|-------|------------------|-------------------------|
| 14" | 24.50 | 0.79 | 13.11 | 17.00 | 3.35 | 20.31 | 18.75 | 0.88 | 6 |
| 16" | 27.25 | 0.85 | 14.37 | 17.72 | 3.54 | 22.64 | 21.00 | 0.88 | 8 |
| 18" | 29.25 | 1.00 | 15.95 | 19.10 | 3.35 | 25.00 | 23.25 | 0.88 | 8 |
| 20" | 31.00 | 1.02 | 16.62 | 20.00 | 3.64 | 27.16 | 25.50 | 0.88 | 10 |
| 24" | 42.00 | 1.02 | 20.67 | 23.31 | 4.66 | 31.89 | 30.00 | 0.88 | 12 |
| 30" | 51.00 | 1.31 | 26.57 | 30.12 | 4.92 | 39.12 | 36.88 | 1.13 | 12 |
| 36" | 60.00 | 1.45 | 30.71 | 34.41 | 5.50 | 46.00 | 43.75 | 1.13 | 16 |
| 42" | 72.00 | 1.45 | 37.40 | 43.26 | 7.50 | 53.12 | 50.62 | 1.38 | 20 |
| 48" | 84.00 | 1.45 | 42.32 | 47.33 | 7.50 | 60.00 | 57.50 | 1.38 | 24 |


- (1) "H" represents the size of through holes, bolt size is 1/8" smaller
 Flange's drilling/bolting and bell end/gasket groove dimensions per AWWA C111
- (2) "J" represents the total number through holes, per flange




Flanged With Worm Gear & HW









| SIZE | A | В | С | D | E | F | G | H ⁽¹⁾ | J ⁽²⁾ | K ⁽³⁾ | L ⁽⁴⁾ | Р |
|------|-------|------|-------|-------|------|-------|-------|------------------|------------------|-------------------------|------------------|------|
| 14" | 17.00 | 1.38 | 13.11 | 17.00 | 3.35 | 21.00 | 18.75 | 8 | 1.125 | 4 | 1-8UNC | 24 |
| 16" | 17.75 | 1.44 | 14.37 | 17.70 | 3.54 | 23.50 | 21.25 | 8 | 1.125 | 8 | 1-8UNC | 24 |
| 18" | 21.50 | 1.56 | 15.95 | 19.10 | 3.35 | 25.20 | 22.75 | 8 | 1.25 | 8 | 1.125-7UNC | 20 |
| 20" | 23.50 | 1.69 | 16.62 | 20.00 | 3.64 | 28.15 | 25.00 | 12 | 1.25 | 8 | 1.125-7UNC | 24 |
| 24" | 42.00 | 1.88 | 20.67 | 23.30 | 4.66 | 32.00 | 29.50 | 20 | 1.375 | 8 | 1.25-7UNC | 24 |
| 30" | 51.00 | 2.12 | 26,57 | 30.12 | 4.92 | 38.75 | 36.00 | 20 | 1.375 | 8 | 1.25-7UNC | 27.5 |
| 36"√ | 60.00 | 2.38 | 30.71 | 34.41 | 5.50 | 46.00 | 42.75 | 24 | 1.625 | 8 | 1.5-6UNC | 31.5 |
| 42" | 72.00 | 2.62 | 37.40 | 43.26 | 7.50 | 53.00 | 49.50 | 32 | 1.625 | 4 | 1.5-6UNC | 35.5 |
| 48" | 84.00 | 2.75 | 42.32 | 47.33 | 7.50 | 59.50 | 56.00 | 40 | 1.625 | 4 | 1.5-6UNC | 31.5 |

- (1) "H" represents the total number of through holes, per flange (2) "J" represents the size of the through holes for flange (3) "K" represents the total number of tapped holes, per flange


- (4) "L" represents the size of tapped holes and bolts used for flange


CAM #25-0539 Exhibit 4 Page 178 of 205


E: sales@vsiwaterworks.com




Mechanical Joint With Worm Gear & 2" Nut Op









| | chen moor | re and associates |
|--|---|---|
| | TONS TAKEN RESUBMIT | FURNISH WITH CHANG NOTED REJECTED |
| design conce with the info Corrections of during this in compliance of specifications | pt of the primation give r comments eview do no ith the required. Approval | general conformance wit roject and general comp an in the Contract Docum is made on the shop dra dot relieve the contractor uiroments of the plans ar for a specific item sha |
| component. 6 be confirmed that pertains the means, procedures of trades; and satisfactory in | contractor is and correla solely to the methods, f construction performing anner. | assembly of which the ites some process and at the jobsite; inform he fabrication processes techniques, sequences, ion; coordination of work g all work in a safe |


| SIZE | Α | В | С | D | E | F | G | H ⁽¹⁾ | J ⁽²⁾ |
|------|-------|------|-------|-------|------|-------|-------|------------------|-------------------------|
| 14" | 24.50 | 0.79 | 13.11 | 17.00 | 2.00 | 20.25 | 18.75 | 0.88 | 6 |
| 16" | 27.25 | 0.85 | 14.37 | 17.72 | 2.00 | 22.50 | 21.00 | 0.88 | 8 |
| 18" | 29.25 | 1.00 | 15.95 | 19.10 | 3.15 | 24.75 | 23.25 | 0.88 | 8 |
| 20" | 31.00 | 1.02 | 16.62 | 20.00 | 3.55 | 27.00 | 25.50 | 0.88 | 10 |
| 24" | 42.00 | 1.02 | 20.67 | 23.31 | 3.98 | 31.50 | 30.00 | 0.88 | 12 |
| 30" | 51.00 | 1.31 | 26.57 | 30.12 | 5.47 | 39.12 | 36.88 | 1.13 | 12 |
| 36" | 60.00 | 1.45 | 30.71 | 34.41 | 6.61 | 46.00 | 43.75 | 1.13 | 16 |
| 42" | 72.00 | 1.45 | 37.40 | 43.26 | 6.77 | 53.12 | 50.62 | 1.38 | 20 |
| 48" | 84.00 | 1.45 | 42.32 | 47.33 | 7.36 | 60.00 | 57.50 | 1.38 | 24 |

- (1) "H" represents the size of through holes, bolt size is 1/8" smaller
 - Flange's drilling/bolting and bell end/gasket groove dimensions per AWWA C111
- (2) "J" represents the total number through holes, per flange



STANDARD OPERATOR TYPES

SINGLE STAGE WORM GEAR WITH SPUR SECONDARY GEAR





Vincent Lociono, PE DATE 12/9/24


HANDWHEEL 🗸



2-INCH NUT OP.




CHAINWHEEL




CAM #25-0539 Exhibit 4 Page 180 of 205



FLOW CHARACTERISTICS



| SIZE | Cv | Kv |
|------|-------|-------|
| 14" | 6085 | 5257 |
| 16" | 8199 | 7084 |
| 18" | 12168 | 10513 |
| 20" | 15710 | 13573 |
| 24" | 25565 | 22088 |
| 30" | 38315 | 33104 |
| 36" | 58623 | 50650 |







BY Vincent Locigno, PE DATE 12/9/24

VSI Waterworks


1205 Alpha Drive, Alpharetta, GA 30004 T: 770.740.0800 F: 770.740.8777

E: sales@vsiwaterworks.com





PART NUMBER MATRIX



- * Standard Material
- 1 May not be available for all configurations/sizes

EXAMPLE:

PVIF14F-DDN-3S1/WC-J

A 14" flanged rectangular full port plug valve with Ductile Iron body and plug, NBR plug encapsulation, SS316 bearings, SS304 hardware, Fusion bonded epoxy, worm gearbox with chainwheel operator.

DOC#:

C517-36-POD

AWWA C517-09 Proof of Design Test Certification (36" Resilient Seated Eccentric Plug Valve)

ITEM TESTED:

VSI C517 Series Resilient Seated Eccentric Plug Valve - 36 inch size (150psi) **Ductile Iron Body and Bonnet** 95% Nickel Bonded Seat Ductile Iron Plug encapsulated in NBR

PURPOSE:

To perform the Proof of Design test requirements laid out in American Water Works Association (AWWA) Standard C517, Resilient Seated Cast Iron Eccentric Plug Valves.

RECORD OF TEST:

PLUG STRUCTURE TEST: The test valve was mounted to the test heads, and the valve put into the closed position. A pressure of 300 psi was then applied to the seat side of the plug for 60 seconds. The pressure was then released, and 300 psi was applied to the back side of the plug for 60 seconds. After the test pressure was released, the plug was inspected. There were no signs of deformation nor breakage found.

LIFE CYCLE TEST: The test valve was mounted to the test heads, and put into the closed position. A test pressure of 150 psi was applied to the seat side of the valve, and zero pressure on the back side. The valve was then operated from fully closed to fully open 5,000 times. The test took place over a period of 21 days. Upon completion of the life cycle test, a hydrostatic seat test was performed. A test pressure of 150 psi was applied to the seat side of the valve and held for 60 seconds. The test pressure was then relieved and applied to the back side of the plug for 60 seconds. There were no visible signs of leakage from the stem, seat, or any other pressure constraining joints.

POST TEST INSPECTION: Upon completion of all the tests, the valve was disassembled, and inspected. There were no signs of extensive wear, cracking, or bonding failure on the valves corrosionresistant seating surfaces.

CERTIFICATION:

Based on the above test record, we here by certify that the test valve has successfully met all of the proof of design requirements in AWWA C517 and therefore qualifies similar valves in the Series C517 24 inch through 42 inch product line, with equal or lesser pressure classes to the same standards.

| TESTED BY: Robert Wan | g, Valve Solutions, Inc. | DATE: <u>05/31/2010</u> |
|--------------------------|--|-------------------------|
| CERTIFIED BY: Michael | Michael, fan Fan, Tianjin Flow Security Valve Co., Ltd | DATE: <u>05/31/2010</u> |
| 36" RESILIENT SEATE | D ECCENTRIC PLUG VALVE | € 25-0539 |

PROOF OF DESIGN CERTIFICATION

Ex10151/31/2010

DOC#:

C517-42-POD

AWWA C517-09 Proof of Design Test Certification (42" Resilient Seated Eccentric Plug Valve)

ITEM TESTED:

VSI C517 Series Resilient Seated Eccentric Plug Valve - 42 inch size (150psi) Ductile Iron Body and Bonnet 95% Nickel Bonded Seat Ductile Iron Plug encapsulated in NBR

PURPOSE:

To perform the Proof of Design test requirements laid out in American Water Works Association (AWWA) Standard C517, Resilient Seated Cast Iron Eccentric Plug Valves.

RECORD OF TEST:

PLUG STRUCTURE TEST: The test valve was mounted to the test heads, and the valve put into the closed position. A pressure of 300 psi was then applied to the seat side of the plug for 60 seconds. The pressure was then released, and 300 psi was applied to the back side of the plug for 60 seconds. After the test pressure was released, the plug was inspected. There were no signs of deformation nor breakage found.

LIFE CYCLE TEST: The test valve was mounted to the test heads, and put into the closed position. A test pressure of 150 psi was applied to the seat side of the valve, and zero pressure on the back side. The valve was then operated from fully closed to fully open 5,000 times. The test took place over a period of 21 days. Upon completion of the life cycle test, a hydrostatic seat test was performed. A test pressure of 150 psi was applied to the seat side of the valve and held for 60 seconds. The test pressure was then relieved and applied to the back side of the plug for 60 seconds. There were no visible signs of leakage from the stem, seat, or any other pressure constraining joints.


POST TEST INSPECTION: Upon completion of all the tests, the valve was disassembled, and inspected. There were no signs of extensive wear, cracking, or bonding failure on the valves corrosion-resistant seating surfaces.

CERTIFICATION:

PROOF OF DESIGN CERTIFICATION

Based on the above test record, we here by certify that the test valve has successfully met all of the proof of design requirements in AWWA C517 and therefore qualifies similar valves in the Series C517 24 inch through 42 inch product line, with equal or lesser pressure classes to the same standards.

| TESTED BY: Robert Wa | Robert wang ng, Valve Solutions, Inc. | DATE: <u>06/07/2010</u> |
|-------------------------|---|---|
| CERTIFIED BY: Michae | Michael fan el Fan, Tianjin Flow Security Valve Co., Ltd | DATE: <u>06/07/2010</u> |
| 42" RESILIENT SEAT | ED ECCENTRIC PLUG VALVE | ©%%\₹25-0539 Ex \06\/07/201 0 |



VSI Waterworks LLC

tel: 1 (770) 740 0800 fax: 1 (770) 740 8777

email: sales@vsiwaterworks.com



As part of a process of on-going product development, VSI reserves the right to amend or change specifications without prior notice. Published data may be subject to change. For the latest specific our website at www.vsiwatexmonke.com



VSI Waterworks 2" - 72" AWWA C517 ECCENTRIC PLUG VALVES

INSTALLATION, OPERATION AND MAINTENANCE MANUAL





INSTALLATION, OPERATION AND MAINTENANCE VSI AWWA C517 ECCENTRIC PLUG VALVES

TABLE OF CONTENTS

| SCOPE | 3 |
|----------------------------------|---|
| WARNINGS | 3 |
| GENERAL | 4 |
| UNLOADING | 4 |
| STORAGE | 4 |
| INSPECTION PRIOR TO INSTALLATION | 4 |
| INSTALLATION | 4 |
| TESTING | 6 |
| RECORDS | 7 |
| OPERATION | 7 |
| MAINTENANCE | 7 |
| TROUBLESHOOTING | 9 |

INSTALLATION, OPERATION AND MAINTENANCE VSI AWWA C517 ECCENTRIC PLUG VALVES



SCOPE:

This installation, operation, and maintenance manual covers the VSI AWWA C517 resilient seated eccentric plug valve and should be read and understood thoroughly by all parties responsible for installation and continued use/maintenance.

WARNINGS:

The critical safety messages within this manual are labeled with an exclamation symbol within a red triangle flag. Care should be taken to thoroughly read and understand these warnings before proceeding to ensure no damage to equipment occurs. Failure to follow all warnings could result in injury or death.



WARNING!

All parties that take part in any installation or continued use/maintenance are cautioned to be vigilant in the possible exposure to media that is contained within the valve and its pipeline. Because of the vast range of media that could be within the valve, protection from pipeline media is not within the scope of this manual. All personnel should be aware of the media within the valve and take appropriate precautions when exposure is possible while installing or servicing the valve.

RECEIVING:

The VSI AWWA C517 Resilient Seated Eccentric Plug Valve is rugged and will be packaged to provide protection during most shipping incidents, however care should be taken to inspect the valve on receipt for any possible shipping damage. Inspection should be performed as soon as practical. Failure to promptly notify VSI of any shipping damage may invalidate any claim for shipping damage. Most shipments from VSI will be made FOB Origin, unless noted on the sales documents, the purchaser will own the freight while in transit, assumes all risk while in transit, and will be responsible for reporting shipping damage promptly to the carrier.

PARTS:

Order parts from your Valve Solutions Inc. sales representative. Please include the serial number, located on the valve tag, when ordering parts.



WARNING!

Read all applicable instructions and directions prior to any maintenance, installation or troubleshooting.



INSTALLATION, OPERATION AND MAINTENANCE **VSI AWWA C517 ECCENTRIC PLUG VALVES**

SECTION 1: GENERAL

Plug valves are a significant component of any water distribution system or treatment plant operation. Valve failure due to faulty installation, improper operation, or maintenance in such systems could result in damage, downtime, and costly repairs. In buried or underground installations, problems or malfunctions can result in extensive and costly unearthing operations to correct or eliminate the problem. Many problems with plug valves can be traced to improper installation, operation, or maintenance procedures.

SECTION 2: UNLOADING

Inspect valves on receipt for damage in shipment and conformance with quantity and description on the shipping notice and order. Unload valves carefully to the ground without dropping. On valves larger than 6 in. (150 mm), use forklifts or slings under skids. On smaller valves, do not lift valves with slings or chain around actuator or through waterway. Lift these valves with eyebolts or rods through flange holes or chain hooks at the ends of valve parts.

SECTION 3: STORAGE

If it is not practical to store the valve indoors, protect the valve and actuators from weather and the accumulation of dirt, rocks, and debris. When valves fitted with power actuators and controls are stored, energize electric actuators or otherwise protect electrical-control equipment to prevent corrosion of electrical contacts due to condensation resulting from temperature variation. Do not expose resilient seats to sunlight or ozone for any extended period. Also see the manufacturer's specific storage instructions.

SECTION 4: INSPECTION PRIOR TO INSTALLATION

Make sure valve ends and seats are clean. Check all exposed bolting for loosening in transit and handling and tighten to manufacturer's recommendations. Open and close the valve to make sure it operates properly and that stops or limit switches are correctly set so that the plug seats fully. Close the valve before installing. Check coatings for damage and repair as required.

SECTION 5: INSTALLATION

It is strongly recommended that instruction manuals supplied by the manufacturer be reviewed in detail before installing plug valves. Be sure the inspection, as described in Sec. 4, is carried out at the job site prior to installation.

Sec. 5.1 Handling

Handle valves carefully when positioning, avoiding contact or impact with other equipment or structures.

4

INSTALLATION, OPERATION AND MAINTENANCE VSI AWWA C517 ECCENTRIC PLUG VALVES



Sec. 5.2 Service Conditions

Valves are to be installed in accordance with the manufacturer's instructions.

5.2.1 Clean service. Eccentric plug valves used for fluids free of suspended solids may be installed in any orientation. If practical, the valves shall be installed so the pipe line pressure is exerting force on the plug from opposite the seat end of the valve (direct pressure).




Image courtesy of Robert O'Neill

Figure 1. Recommended installation position for suspended solids service

5.2.2 Other service. Eccentric plug valves used for fluids containing suspended solids should be installed as shown in Figure 1. When installed in horizontal pipes, the axis of the plug is to be horizontal, with flow entering the valve body from the seat end. The plug is to rotate counterclockwise to open, keeping the plug in the upper half of the body. When installed in vertical pipes, the seat end shall be oriented as shown in Figure A-1.

Sec. 5.3 Buried Installations

When practical, valves in buried installations should be located in unpaved areas.

Sec. 5.4 Cleaning

Be sure valve interiors, ends, and adjacent piping are cleaned of foreign material prior to making up valve-to-pipe joint connection.



INSTALLATION, OPERATION AND MAINTENANCE **VSI AWWA C517 ECCENTRIC PLUG VALVES**

Sec. 5.5 Pipe Ends

Prepare pipe ends and install valves in accordance with the pipe manufacturer's instructions for the joint used. Do not deflect the pipe-valve joint. Do not use a valve as a jack to pull pipe into alignment. In plant piping, the valve shall be installed so as to minimize the bending stresses in the valve end connection with pipe loading.

Sec. 5.6 Installation

For mechanical-joint end valves, lubrication and additional cleaning should be provided by brushing both the gasket and the plain end of the mating pipe with soapy water or pipe lubricant just before slipping the gasket onto the plain end and assembling the joint. When tightening bolts, it is essential that the gland be brought up toward the bell flange evenly, maintaining approximately the same distance between the gland and the face of the flange at all points around the socket. This may be achieved by first partially tightening the bottom bolt, then the top bolt, next the bolts at either side, and finally, the remaining bolts. This process should be repeated until all bolts are fully torqued.

Sec. 5.7 Valve Boxes

Buried valves installed with valve boxes shall be installed so that the valve box does not transmit shock or stress to the valve actuator as a result of shifting soil or traffic load.

Sec. 5.8 Valves Installed in Vaults

When valves are installed in vaults, the vault design shall provide space for removal of the valve-actuator assembly for purposes of repair. Consideration should be given to the possible entry of groundwater or surface water and to the need to provide for disposal thereof. The valve operating nut should be accessible from the top opening of the vault with a tee wrench.

SECTION 6: TESTING

When resilient-seated cast-iron eccentric plug valves are used to isolate sections of a pipeline for testing, it is important to realize that eccentric plug valves are typically factory adjusted to hold pressure only up to the specified shutoff pressure in the direct pressure direction. Prior to any field pressure test under conditions different from above, it is recommended that the valve manufacturer be contacted for approval. Otherwise, test pressures above the valve design pressure may cause leakage, permanent damage, or structural failure to the valve and injury or death to the operator.

Sec. 6.1 Leaks

In order to prevent the loss of time due to searching for leaks, it is recommended, where feasible, that excavations for buried valves not be backfilled until after pressure tests have been completed.

Sec. 6.2 Seat Leakage

Seat leakage can occur from foreign material in the line. If this occurs, open the valve 5° to

INSTALLATION, OPERATION AND MAINTENANCE VSI AWWA C517 ECCENTRIC PLUG VALVES



10° to obtain high-velocity flushing action, then close. Repeat several times to clear seats for tight shutoff. Do not force valves for a tighter seal. Plug valves are provided with an externally adjustable closed stop on the actuator to provide a tighter seal. See the instruction manual provided by the manufacturer for the correct adjustment procedure.

SECTION 7: RECORDS

On completion of installation, the valve location, size, make, type, date of installation, number of turns to open, direction of opening, and any other information deemed pertinent should be entered on the owner's permanent records.

SECTION 8: OPERATION

Sec. 8.1 Design Pressure

Do not permit the use or operation of any valve at pressures above the rated design pressure of the valve.

Sec. 8.2 Input Torque

Do not exceed 250 ft-lb (339 N·m) input torque on actuators with wrench nuts and do not exceed 200 lb (890 N) rim pull for handwheels or chainwheels. If portable auxiliary actuators are used, size the actuator or use a torque-limiting device to prevent application of torque exceeding 250 ft-lb (339 N·m). If an oversize actuator with no means of limiting torque is used, stop the actuator before the valve is fully opened or closed against stops and complete the operation manually. Be sure to check the actuator directional switch against the direction indicated on the wrench nut, handwheel, or records before applying opening or closing torque.

Sec. A.8.3 Sticking

If a valve is stuck in some intermediate position between open and closed, check first for jamming in the actuator. If nothing is found, the interference is inside the valve. In this case, do not attempt to force the plug open or closed, because excessive torque in this position can severely damage internal parts.

SECTION 9: MAINTENANCE

Maintenance of resilient-seated plug valves by the owner is generally limited to actuators and shaft seals. Unless the owner has skilled personnel and proper equipment, any major internal problem will probably require removal of the valve from the line and return to the manufacturer for repair.

Sec. 9.1 Normal Maintenance

Normal maintenance is in the area of shaft seals and actuators. Seal leakage, broken parts, hard operation, and, in some cases, seat leakage should be corrected by a repair crew as soon as possible after a defect is reported.



INSTALLATION, OPERATION AND MAINTENANCE VSI AWWA C517 ECCENTRIC PLUG VALVES

Sec. 9.2 Valve Exercising

Each valve should be operated through a full cycle and returned to its normal position on a time schedule that is designed to prevent a buildup of lubrication or other deposits that could render the valve inoperable or prevent a tight shutoff. The interval of time between operations of valves in critical locations or valves subjected to severe operating conditions should be shorter than for other less important installations, but it can be whatever time period is found to be satisfactory based on local experience. For gear operators, the number of turns required to complete the operation cycle should be recorded and compared with permanent installation records to ensure full plug travel.

Sec. 9.3 Field Repairs

If repairs are to be made in the field, repair crews should take a full complement of spare parts to the job site. Be sure to review the valve manufacturer's instructions prior to any repair work.

Sec. 9.4 Isolation

Provision should be made to stop line flow and isolate the valve from line pressure prior to performing any corrective maintenance.

Sec. 9.5 Repair Testing

After completing repairs, cycle the valve through one complete operating cycle and, after line pressure has been restored, inspect for leakage.

Sec. 9.6 Valve Removal

If major repairs require the removal of the valve for repair, be sure to notify interested parties in the water department and fire department that the valve and line are out of service. On completion of repair and reinstallation, notify the same personnel of the return of the valve and line to service.





SECTION 10: TROUBLESHOOTING

| Problem | Cause | Correction |
|---|--|---|
| The operator or shaft will not turn | Interference between valve box and shaft key | Reposition valve box if necessary |
| | Uneven tightening of gland plate bolts | Loosen then retighten bolts and nuts evenly |
| | Corrosion or debris between the stem and packing | Consult VSI for disassembly procedures and clean stem, stuffing, and stem nut |
| | Debris blocking movement of plug | Consult VSI for disassembly procedures and clean out debris |
| | RARE: Seized worm gear | Inspect and replace if necessary |
| Leakage between the body and cover of valve | Bolts and nuts may be loose or tightened irregularly | Loosen then retighten bolts and nuts evenly |
| | Bonnet o-ring may be damaged | Consult VSI for disassembly procedures and replace o-ring |
| | RARE: Crack in body or bonnet | Inspect and replace if necessary |
| Leakage at the stem | Damaged stuffing | Consult VSI for disassembly procedures and replace damaged parts if needed |
| | Loose packing | Tighten the packing gland nuts until leakage stops or replace packing |
| Valve fails pressure test | Valve is not completely closed | Close valve completely |
| or a leak present in the line | Debris trapped between plug and seat | Throttle valve from fully closed to approximately 25% open several times under line flow to clear debris. If unsuccessful follow instructions for disassembly and remove debris |
| | Rubber plug or metal seat is damaged | Consult VSI for disassembly procedures to inspect for damage. If present replace damaged parts. |

Original Proposal with Comments

Mark-ups are based on

total amounts that

include taxes



2601 Wiles Rd Pompano Beach Florida 33073 PH: (954) 977-3556 FAX: (954) 944-2040

CONTRACT: P12384

PROJECT: Coral Ridge Force Main Replacement CONTRACTOR: David Mancini & Sons, Inc. (DMSI)

DATE: 1/23/2025

DESCRIPTION: Additional cost related to Repump B connection with 36Inch above ground bypass no includeded on the scope of work

on the DCP.

Submitted by:

SUMMARY OF DIRECT COSTS

| 30111111 | ART OF DIRECT COSTS | | | |
|----------|--|-------|----|--------------------|
| 1 | TOTAL LABOR | | \$ | 85/327.96 |
| 2 | TOTAL EQUIPMENT | | \$ | 10 7,829.75 |
| 3 | TOTAL MATERIAL | | \$ | 445,745.94 |
| 4 | TOTAL SUBCONTRACTORS | | \$ | 126,980.61 |
| | SUBTOTAL | 1 | \$ | 766,084.26 |
| 5 | CONTRACTOR'S MARKUP | 8.00% | Ş | 61,286.74 |
| 7 | GENERAL CONDITIONS [Items (3+4+5)/Construction Cost] | 5.35% | \$ | 40,985.51 |
| | Total Direct Cost | | \$ | 868,356.51 |

SUMMARY OF TIME IMPACT (REQUEST FOR ADDITIONAL TIME)

| | DAYS | 0 |
|---------------------------------------|------|----|
| ADDITIONAL TIME FOR NEW SCOPE OF WORK | 15 | 15 |
| ADDITIONAL TIME REQUESTED | | 15 |

| - | Alejandra Suarez | |
|--------------|-----------------------------|--|
| | Assistant Project Manager | |
| | David Mancini and Sons, Inc | |
| Approved by: | | |
| | Cyrill Garcia | |
| | Project Manager | |
| | City of Fort Lauderdale | |

GENERAL COMMENTS

1. Provide layout/sketch of the new work (including material) clearly showing the difference from the original scope. Layout and location of proposed works needs to be approved by the City.

2. Provide a description of the work included in this proposal.



LABOR COSTS

| SUMMARY - LABOR COSTS | | |
|-----------------------|------------|-----------|
| SUPERVISION | \$ | 20,175.00 |
| CREW | \$ | 28,545.00 |
| LABOR BURDEN (75.55%) | \$ | 36,807.96 |
| TOTA | L LABOR \$ | 85,527.96 |

| LABOR BURDEN MULTIPLIER (LBM) | 58.20% |
|--|--------|
| Social Security Contributions & Excise and Payroll | 6.20% |
| Medicate Rate | 1.45% |
| Unemployment | 5.49% |
| Workmens Compensation | 7.16% |
| Health Benefits | 14.20% |
| Retirement Benefits | 23.70% |
| VACATION MULTIPLIER (VM) | 13.00% |
| Sick Leave (1 week out of 52) | |
| Vacation (2 weeks out of 52) | |
| Holiday Pay (1 week out of 52) | |
| Insurance Schedule | 4.35% |
| General Liability Insurance | 4.35% |

| Г | Total Labor Burden Rate | 75.55% |
|---|--------------------------|---------|
| | Total Easter Burden Hate | 75.5570 |

| SUPERVISION | Но | ourly Rate (Salary) | Hourly Overtime Rate | Hours (Salary) | Hours Overtime | Total Cost |
|-------------------|----|---------------------|----------------------|----------------|----------------|-----------------|
| Project Manager | \$ | 60.00 | | 30.00 | | \$ 1,800.00 |
| Superintendent | \$ | 55.00 | | 75.00 | | \$ 4,125.00 |
| Crew Foreman | \$ | 47.50 | | 150.00 | | \$ 7,125.00 |
| Crew Foreman | \$ | 47.50 | | 150.00 | | \$ 7,125.00 |
| TOTAL SUPERVISION | | | | | | \$ 20,175.00 |

| MAINLINE CREW - DMSI | Hourly Rate | Н | ourly Overtime Rate | Hours | Hours Overtime | Total Cost |
|----------------------|-------------|----|---------------------|--------|----------------|-----------------|
| Excavator Operator | \$ 30.00 | \$ | 45.00 | 120.00 | 30.00 | \$ 4,950.00 |
| Loader Operator | \$ 27.00 | \$ | 40.50 | 120.00 | 30.00 | \$ 4,455.00 |
| Pipe Layer | \$ 28.00 | \$ | 42.00 | 120.00 | 30.00 | \$ 4,620.00 |
| Skilled Laborer | \$ 24.00 | \$ | 36.00 | 120.00 | 30.00 | \$ 3,960.00 |
| Skilled Laborer | \$ 24.00 | \$ | 36.00 | 120.00 | 30.00 | \$ 3,960.00 |
| Laborer | \$ 20.00 | \$ | 30.00 | 120.00 | 30.00 | \$ 3,300.00 |
| Laborer | \$ 20.00 | \$ | 30.00 | 120.00 | 30.00 | \$ 3,300.00 |
| TOTAL CREW | | | | | | \$ 28,545.00 |

What role will the support crew provide?

| | | | | | | _ | |
|---------------------|-------------|--------|---------------|--------|----------------|----|------------|
| SUPPORT CREW - DMSI | Hourly Rate | Hourly | Overtime Rate | Hours | Hours Overtime | | Total Cost |
| Excavator Operator | \$ 30.00 | \$ | 45.00 | 120.00 | 30.00 | \$ | 4,950.00 |
| Loader Operator | \$ 27.00 | \$ | 40.50 | 120.00 | 30.00 | \$ | 4,455.00 |
| Pipe Layer | \$ 28.00 | \$ | 42.00 | 120.00 | 30.00 | \$ | 4,620.00 |
| Skilled Laborer | \$ 24.00 | \$ | 36.00 | 120.00 | 30.00 | \$ | 3,960.00 |
| Skilled Laborer | \$ 24.00 | \$ | 36.00 | 120.00 | 30.00 | \$ | 3,960.00 |
| Laborer | \$ 20.00 | \$ | 30.00 | 120.00 | 30.00 | \$ | 3,300.00 |
| Laborer | \$ 20.00 | \$ | 30.00 | 120.00 | 30.00 | \$ | 3,300.00 |
| TOTAL CREW | | | | | | \$ | 28,545.00 |

Please provide an expected schedule that details expected overtime.

Why are hourly rates used for two weeks of work with overtime? Provide weekly or monthly rate for comparison

Provide justification for this equipment

EQUIPMENT, MATERIAL & SUBCONTRACTOR COSTS

| EQUIPMENT, MATERIAL & SUBCONTRACTOR COSTS | | | DMSI | Г | DAVID M | ANCINI |
|--|------------|-------------|---------------|---------------|------------|---------|
| EQUIPMENT COSTS - RENTAL RATE BLUE BOOK | | 5 | | S | SONS, INC | ANCINI |
| Skid- Steer | W | orking Rate | Working Hours | \mathcal{J} | Total Cost | / |
| CAT 272D | \$ | 137.96 | 150.00 | \$ | 20,694.00 | / |
| Loaders | | | | | | / |
| CAT 938M | \$ | 85.19 | 150.00 | \$ | 12,778.50 | / |
| Excavators | | | | | | / |
| CAT 308 | \$ | 103.43 | 150.00 | \$ | 15,514.50 | / |
| CAT 325 | \$ | 153.18 | 150.00 | \$ | 22,977.00 | / |
| Tyacky Y Y Y Y Y Y Y Y Y Y Y Y Y Y Y Y Y Y Y | \searrow | \sim | \sim | Y | \sim | \prec |
| Pick-Up Truck - Chevy Silverado 2500 - Foreman | \$ | 61.63 | 150.00 | \$ | 9,244.50 | 人 |
| Pick-Up Truck - Chevy Silverado 2500 - Foreman | \$ | 61.63 | 150.00 | \$ | 9,244.50 |) |
| Pick-Up Truck - Chevy Silverado 2500 - Superindendant | \$ | 61.63 | 75.00 | \$ | 4,622.25 |) |
| Miscellaneous Equipment | | | | | | |
| Water Pump | \$ | 9.83 | 150.00 | \$ | 1,474.50 | |
| Steel Plates - 8'x20' (6 On Site \$60 per plate PER DAY) | \$ | 360.00 | 15.00 | \$ | 5,400.00 | |
| Air Compressor Sullair 375 | \$ | 392.00 | 15.00 | \$ | 5,880.00 | Drovido |
| TOTAL EQUIPMENT | | • | | \$ | 107,829.75 | Provide |

Provide back up for material cost

| MATERIAL COSTS | | | | | | |
|----------------------------|-----|------|----------------|------------|----|------------|
| Material Description | QTY | Unit | Unit Unit Cost | | | Total Cost |
| 36" FLGXPE DIP 6' | 1 | EA | \$ | 9,988.24 | \$ | 9,988.24 |
| 36" FLGXPE DIP 4' | 1 | EA | \$ | 7,641.18 | \$ | 7,641.18 |
| 36" FLGXFLG DIP 2' | 2 | EA | \$ | 8,089.41 | \$ | 16,178.82 |
| 36" MEGA FLANGE REST ADPT | 1 | EA | \$ | 3,708.38 | \$ | 3,708.38 |
| 36" FLG 90 BEND | 2 | EA | \$ | 14,002.40 | \$ | 28,004.80 |
| 36" FLG ACC KIT NEOPRENE | 10 | EA | \$ | 1,158.83 | \$ | 11,588.30 |
| 36" FLG PLUG VALVE W/GEAR | 1 | EA | \$ | 49,916.85 | \$ | 49,916.85 |
| 36" FLG CHECK VALVE | 1 | EA | \$ | 48,348.31 | \$ | 48,348.31 |
| 2" BALL CORP | 1 | EA | \$ | 315.00 | \$ | 315.00 |
| 2" X 4" SS NIPPLE | 1 | EA | \$ | 14.00 | \$ | 14.00 |
| 36"X2" DBL STRP SS | 1 | EA | \$ | 720.00 | \$ | 720.00 |
| 2" SEWAGE AIR RELEASE VLV | 1 | EA | \$ | 1,040.00 | \$ | 1,040.00 |
| 42" MJ LONG SLEEVE | 1 | EA | \$ | 8,338.99 | \$ | 8,338.99 |
| 42" MEGALUG DIP W/ACC | 10 | EA | \$ | 2,417.08 | \$ | 24,170.80 |
| 42" MJ 45 BEND | 1 | EA | \$ | 11,719.18 | \$ | 11,719.18 |
| 42" X 36" MJ TEE | 1 | EA | \$ | 19,636.05 | \$ | 19,636.05 |
| 36" MEGALUG DIP W/ACC | 5 | EA | \$ | 1,693.30 | \$ | 8,466.50 |
| 36" MJ 90 BEND | 1 | EA | \$ | 9,596.14 | \$ | 9,596.14 |
| 36" MJ PLUG VALVE | 1 | EA | \$ | 50,939.33 | \$ | 50,939.33 |
| 42" MJ PLUG VALVE | 1 | EA | \$ | 103,264.00 | \$ | 103,264.00 |
| 72" ARV MANHOLE / TOP SLAB | 1 | EA | \$ | 2,648.00 | \$ | 2,648.00 |
| 690-AH-M PL R/C | 1 | EA | \$ | 4,225.00 | \$ | 4,225.00 |
| SURTAX | | | \$ | 50.00 | \$ | 50.00 |
| SUBTOTAL | | | | | \$ | 420,467.87 |
| TAXES | | | | | \$ | 25,278.07 |
| TOTAL MATERIAL | | | | | \$ | 445,745.94 |

| CURCONTRACTORS COSTS | | | Provide back up for subs | | | | |
|------------------------------|-----|--------------------|--------------------------|-------------|----|------------|--|
| SUBCONTRACTORS COSTS | | | | | | | |
| Description | QTY | QTY Unit Unit Cost | | Total Cost | | | |
| CMA | 1 | LS | 9 | 62,400.00 | \$ | 62,400.00 | |
| A&M Brothers Concrete | 1 | LS | , | 5 7,600.00 | \$ | 7,600.00 | |
| SUPERMIX Flowable Fill 18 CY | 1 | LS | , | \$ 3,228.40 | \$ | 3,228.40 | |
| Rangeline (IF NEEDED) | 1 | LS | , | 50,096.00 | \$ | 50,096.00 | |
| MWI PUMPS (IF NEEDED) | 1 | LS | , | \$ 3,656.21 | \$ | 3,656.21 | |
| TOTAL SUBCONTRACTOR | | | | | \$ | 126.980.61 | |




Hazen and Sawyer 498 Seventh Avenue, 11th Floor New York, New York 10018 Phone: (212) 539-7011 Project: 43194-023/024 - P12383 & 12384, Design Build Services for NE 25th Avenue 24-Inch Force Main Replacement, and NE 38th Street 42-Inch FM and NE 19th Avenue 24-Inch FM Replacement 4000 NE 25 AVE

Fort Lauderdale, Florida 33308

| RFI #5 - Repump Station B Connection | | | | | | | |
|---------------------------------------|-----------------------------|--|--|--|--|--|--|
| DATE INITIATED: | 08/21/ 2024 | STATUS: | Closed on 09/20/24 | | | | |
| LOCATION: | | DUE DATE: | 08/30/2024 | | | | |
| COST CODE: | | REFERENCE: | | | | | |
| COST IMPACT: | | SCHEDULE IMPACT: | | | | | |
| DRAWING NUMBER: SPEC SECTION: | | | | | | | |
| LINKED DRAWINGS | : | | | | | | |
| RECEIVED FROM: | Vincent Locigno (Chen Moore | & Associates) | | | | | |
| • | d Sawyer - Hollywood) | (Hazon and Ganjo | - Coral Gables), Criztol Lopez (WSP), Enrique | | | | |
| Question | | | | | | | |
| Received on 8/16/202 See attached. | 23 | | | | | | |
| Attachments: P12384 - RFI Repum | p B Conenction.pdf | | | | | | |
| _ | | onded on Friday, September 20th, 2024 at 3: tember 13, 2024, please provide a quote for the | ne additional work related to the installing a new | | | | |

BY DATE COPIES TO CAM #25-0539 Exhibit 4

Page 200 of 205 Printed On: 02/25/2025 05:05 PM



500 West Cypress Creek Road, Suite 600 Fort Lauderdale, FL 33309

Office: +1 (954) 730-0707



August 16th, 2024

Cyrill Garcia
Project Manager II
City of Fort Lauderdale
Public Works – Engineering
101 NE 3rd Ave, Suite 2100
Fort Lauderdale, Florida 33301

Re: P12384 Phase 4 – Request for Information for Connections

To Mr. Garcia,

David Mancini and Sons, Inc. (DMSI) began exploratory efforts at the City of Fort Lauderdale Repump B pump station to locate existing utilities and plan for the proposed connection to the existing 42-inch force main, as shown in the Design Criteria Package (DCP). During the field investigation, a valve (shown in Image 1 and labeled as valve 1 on PDF markup) was located on the south side of the manifold system and this valve appears to be currently closed. On the east side of the manifold system, there is a similar valve configuration (shown in image 2 and labeled as valve 2 on PDF markup), which was found to be open during the investigation.

Chen Moore and Associates (CMA) believes this valve configuration allows for the flow at Repump B station to be diverted in case of emergency or maintenance by simply operating these two valves. Therefore, valve 1 on the south side should remain closed at all times and only be operated when necessary to bypass the station by closing valve 2. The DCP shows the proposed connection on the south side of valve 1. If the connection were performed at this location, the flow from the new 42-inch main would not pump through the repump station but would instead divert the new 42-inch flow directly into the existing 36-inch/42-inch effluent main leading out to GTL.

The above scenario is based off field investigation and CMA would like clarification on where the connection should be made and weather the goal of this project is to route the flow from the proposed 42-inch FM through repump B. Also, please clarify the end result of this project and weather it is to completely isolate and place out of service the existing 42-inch FM, if so a cap/plug/or permanent separation needs to be performed near the proposed connection point.

Should you have any questions, please do not hesitate to contact me at my cell phone at +1 (561) 926-2596 or send me an electronic message at vlocigno@chenmoore.com.

Respectfully submitted,

Vincent Locigno

Vincent Locigno, PE Project Engineer Office: +1 (954) 730-0707






Figure 1: Existing Valve on south side of manifold appears to be in closed position. Labeled as valve 1 in PDF markup.

Office: +1 (954) 730-0707






Figure 2: Existing valve on east side of manifold system and open in normal operating conditions letting flow into Repump B. Labeled as valve 2 in PDF markup.



AUDERDALE **VICINITY MAP**

BCTED 231205061



DAMAGE OR DISRUPTIONS TO ANY EXISTING UTILITIES. ALL LOCATIONS ARE APPROXIMATE AND SHALL BE FIELD VERIFIED BEFORE STARTING CONSTRUCTION. CONSTRUCTION SHALL FOUND TO BE IN DISCREPANCY WITH THE PLANS, THE CONTRACTOR SHALL NOTIFY THE ENGINEER OF RECORD, IN

A HORIZONTAL SEPARATION OF 6' MINIMUM SHALL ALWAYS BE ENFORCED WHENEVER THE FORCEMAIN IS LESS THAN 18"

ALL DIP TO BE RESTRAINED MINIMUM PIPE COVER IS 36" FOR PVC AND 30" FOR DIP.

HDPE PIPE THICKNESS (DR) AND CALCULATIONS PROVIDED BY OTHERS.

9. ALL HDDS TO HAVE WATER BALLAST PRIOR TO INSTALL/PULL.

VACUUM TEST HOLE DATA TABLE TH# GRND EL COVER ELEV TOP DIRECTION

| | | 3012.1 | | | 22001411 11014 |
|----|------|--------|-------|---------|---------------------------------------|
| 61 | 5.47 | 5.83 | -0.36 | NW - SE | 12" SAN FM (UNABLE TO OBTAIN SIZE) |
| 62 | 5.38 | 8.12 | -2.74 | NW - SE | UNABLE TO OBTAIN SIZE |
| 63 | 6.77 | 1.49 | 5.28 | NE - SW | 42" STEEL FORCE MAIN |
| 64 | 6.88 | 1.11 | 5.77 | W - E | 42" STEEL FORCE MAIN |
| 65 | 6.95 | 1.58 | 5.37 | N - S | 42" STEEL FORCE MAIN |
| 66 | 6.98 | 5.41 | 1.57 | N - S | CONCRETE ELECTRIC |
| 67 | 7.18 | 1.75 | 5.43 | NW - SE | 42" STEEL FM |

Sunshine Call 811 or visit sunshine811.com two full business days before digging to have buried facilities located and marked.



500 West Cypress Creek Road, Suite 600 Ft. Lauderdale, FL 33309 954.730.0707 www.chenmoore.com

DESIGN-BUILDER & SONS, INC.

CUC 044220

DAVID MANCINI Pompano Office: 2601 Wiles Road Pompano Beach, FL 33073 954.977.3556

PROGRE %

90

E MAIN FORCE

12384-MULTI-PLPR-38 DRAWINGAMF####D5860.