## **Ballistic Panel Replacement**

Unit	2016 CLASS	DEPARTMENT	Year	Make	Model	Ballistic Panel Replacement Cost
V9585	02	POL020401-D - STAFF SUPPORT	2009	FORDX	CROWN VICTORIA	\$2,764
V9383	02	POL020401-D - STAFF SUPPORT			CROWN VICTORIA	\$2,764
V6472	02	POL020401-D - STAFF SUPPORT			CROWN VICTORIA	\$2,764
V6473	02	POL020401-D - STAFF SUPPORT			CROWN VICTORIA	\$2,764
V6474	02	POL020401-D - STAFF SUPPORT			CROWN VICTORIA	\$2,764
V6475	02	POL020401-D - STAFF SUPPORT	2010		CROWN VICTORIA	\$2,764
V6480	14	POL020401-D - STAFF SUPPORT	2010		CROWN VICTORIA	\$2,764
V6480 V6481	02	POL020401-D - STAFF SUPPORT	2010		CROWN VICTORIA	\$2,764
V6481	02	POL020401-D - STAFF SUPPORT	2010		CROWN VICTORIA	\$2,764
V6482	02	POL020401-D - STAFF SUPPORT	2010		CROWN VICTORIA	\$2,764
V6485	02	POL020401-D - STAFF SUPPORT	2010		CROWN VICTORIA	\$2,764
V6485	02	POL020401-D - STAFF SUPPORT	2010		CROWN VICTORIA	\$2,764
	02	POL020401-D - STAFF SUPPORT	2010		CROWN VICTORIA	\$2,764
V6487 V6488	02	POL020401-D - STAFF SUPPORT			CROWN VICTORIA	\$2,764
	02	POL020401-D - STAFF SUPPORT			CROWN VICTORIA	\$2,764
V6489	02	POL020401-D - STAFF SUPPORT	2010		CROWN VICTORIA	\$2,764
V6498	02	POL020401-D - STAFF SUPPORT	2011		CROWN VICTORIA	\$2,764
V6499	14	POL020401-D - STAFF SUPPORT			CROWN VICTORIA	\$2,764
V6500		POL020401-D - STAFF SUPPORT	2011		CROWN VICTORIA	\$2,764
V6511	02	POL020401-D - STAFF SUPPORT	2011		CROWN VICTORIA	\$2,764
V6535	02	POL020401-D - STAFF SUPPORT	2011		CROWN VICTORIA	\$2,764
V6550	02	POL020401-D - STAFF SUPPORT	2011		CROWN VICTORIA	\$2,764
V6551	02	POL020401-D - STAFF SUPPORT	2011		CROWN VICTORIA	\$2,764
V6552	02	POL020401-D - STAFF SUPPORT	2011		CROWN VICTORIA	\$2,764
V6553	02		2011		CROWN VICTORIA	\$2,764
V6554	02	POL020401-D - STAFF SUPPORT POL020401-D - STAFF SUPPORT			CROWN VICTORIA	\$2,764
V6555	02		2011		CROWN VICTORIA	\$2,764
V6556	02	POL020401-D - STAFF SUPPORT	2011		CROWN VICTORIA	\$2,764
V6557	02	POL020401-D - STAFF SUPPORT	2011		CROWN VICTORIA	\$2,764
V6558	02	POL020401-D - STAFF SUPPORT	2011		CROWN VICTORIA	\$2,764
V6559	02	POL020401-D - STAFF SUPPORT	2011		CROWN VICTORIA	\$2,764
V6560	02	POL020401-D - STAFF SUPPORT			CROWN VICTORIA	\$2,764
V6561	02	POL020401-D - STAFF SUPPORT	2011		CROWN VICTORIA	\$2,764
V6562	02	POL020401-D - STAFF SUPPORT			CROWN VICTORIA	\$2,764
V6563	02	POL020401-D - STAFF SUPPORT			CROWN VICTORIA	\$2,764
V6564	02	POL020401-D - STAFF SUPPORT				\$2,764
V6566	02	POL020401-D - STAFF SUPPORT			CROWN VICTORIA	\$2,764
V6567	14	POL020401-D - STAFF SUPPORT			CROWN VICTORIA	\$2,764
V6568	14	POL020401-D - STAFF SUPPORT			CROWN VICTORIA	\$2,764
V6569	14	POL020401-D - STAFF SUPPORT				
V6570	14	POL020401-D - STAFF SUPPORT			CROWN VICTORIA	\$2,764
V6571	02	POL020401-D - STAFF SUPPORT			CROWN VICTORIA	\$2,764
V6572	02	POL020401-D - STAFF SUPPORT				\$2,764
V6586	02	POL020401-D - STAFF SUPPORT				\$2,764
V9448	02A	POL020401-D - STAFF SUPPORT			CROWN VICTORIA	\$2,764
<u>V9450</u>	02A	POL020401-D - STAFF SUPPORT			CROWN VICTORIA	\$2,764
V9455	02A	POL020401-D - STAFF SUPPORT			CROWN VICTORIA	\$2,764
V94 <u>56</u>	02A	POL020401-D - STAFF SUPPORT			CROWN VICTORIA	\$2,764
V9459	02A	POL020401-D - STAFF SUPPORT			CROWN VICTORIA	\$2,764
V9476	08A	POL020401-D - STAFF SUPPORT	2007	IFORDX	CROWN VICTORIA	\$2,764

## **Ballistic Panel Replacement**

Unit	2016 CLASS	DEPARTMENT	Year	Make	Model	Ballistic Panel Replacement Cost
V9478	02A	POL020401-D - STAFF SUPPORT	2007	FORDX	CROWN VICTORIA	\$2,764
V9480	02A	POL020401-D - STAFF SUPPORT	2007	FORDX	CROWN VICTORIA	\$ <u>2,</u> 764
V9498	02A	POL020401-D - STAFF SUPPORT	2007	FORDX	CROWN VICTORIA	\$2,764
V9499	02A	POL020401-D - STAFF SUPPORT	2008	FORDX	CROWN VICTORIA	\$2,764
V9507	02A	POL020401-D - STAFF SUPPORT	2008	FORDX	CROWN VICTORIA	\$2,764
V9509	02A	POL020401-D - STAFF SUPPORT	2008	FORDX	CROWN VICTORIA	\$2,764
V9510	02A	POL020401-D - STAFF SUPPORT	2008	FORDX	CROWN VICTORIA	\$2,764
V9512	02A	POL020401-D - STAFF SUPPORT	2008	FORDX	CROWN VICTORIA	\$2,764
V9516	02A	POL020401-D - STAFF SUPPORT	2008	FORDX	CROWN VICTORIA	\$2,764
V9518	08A	POL020401-D - STAFF SUPPORT	2008	FORDX	CROWN VICTORIA	\$2,764
V9519	02A	POL020401-D - STAFF SUPPORT	2008	FORDX	CROWN VICTORIA	\$2,764
V9521	02A	POL020401-D - STAFF SUPPORT	2008	FORDX	CROWN VICTORIA	\$2,764
V9522	02A	POL020401-D - STAFF SUPPORT	2008		CROWN VICTORIA	\$2,764
V9523	02A	POL020401-D - STAFF SUPPORT	2008	FORDX	CROWN VICTORIA	\$2,764
V9524	02A	POL020401-D - STAFF SUPPORT	2008	FORDX	CROWN VICTORIA	\$2,764
V9525	02A	POL020401-D - STAFF SUPPORT			CROWN VICTORIA	\$2,764
V9527	02A	POL020401-D - STAFF SUPPORT			CROWN VICTORIA	\$2,764
V9534	02A	POL020401-D - STAFF SUPPORT	2008		CROWN VICTORIA	\$2,764
V9540	02A	POL020401-D - STAFF SUPPORT			CROWN VICTORIA	\$2,764
V9541	02A	POL020401-D - STAFF SUPPORT		FORDX	CROWN VICTORIA	\$2,764
V9543	02A	POL020401-D - STAFF SUPPORT			CROWN VICTORIA	\$2,764
V9547	02A	POL020401-D - STAFF SUPPORT	2008		CROWN VICTORIA	\$2,764
V9552	02A	POL020401-D - STAFF SUPPORT	2008		CROWN VICTORIA	\$2,764
V9554	02	POL020401-D - STAFF SUPPORT	2009	FORDX	CROWN VICTORIA	\$2,764
V9556	02A	POL020401-D - STAFF SUPPORT		FORDX	CROWN VICTORIA	\$2,764
V9558	02A	POL020401-D - STAFF SUPPORT			CROWN VICTORIA	\$2,764
V9560	02	POL020401-D - STAFF SUPPORT			CROWN VICTORIA	\$2,764
V9561	02	POL020401-D - STAFF SUPPORT	2009	FORDX	CROWN VICTORIA	\$2,764
V9564	02	POL020401-D - STAFF SUPPORT	2009		CROWN VICTORIA	\$2,764
V9569	02	POL020401-D - STAFF SUPPORT	2009		CROWN VICTORIA	\$2,764
V9570	02	POL020401-D - STAFF SUPPORT	2009	FORDX	CROWN VICTORIA	\$2,764
V9571	02	POL020401-D - STAFF SUPPORT	2009	FORDX	CROWN VICTORIA	\$2,764
V9572	02	POL020401-D - STAFF SUPPORT		FORDX	CROWN VICTORIA	\$2,764
V9574	08	POL020401-D - STAFF SUPPORT	2009	FORDX	CROWN VICTORIA	\$2,764
V9578	02	POL020401-D - STAFF SUPPORT	2009	FORDX	CROWN VICTORIA	\$2,764
V9579	02	POL020401-D - STAFF SUPPORT			CROWN VICTORIA	\$2,764
V9583	02	POL020401-D - STAFF SUPPORT	2009	FORDX	CROWN VICTORIA	\$2,764
V9584	02	POL020401-D - STAFF SUPPORT			CROWN VICTORIA	\$2,764
V9587	02	POL020401-D - STAFF SUPPORT			CROWN VICTORIA	\$2,764
V9588	02	POL020401-D - STAFF SUPPORT			CROWN VICTORIA	\$2,764
V9589	02	POL020401-D - STAFF SUPPORT			CROWN VICTORIA	\$2,764
V9590	02	POL020401-D - STAFF SUPPORT			CROWN VICTORIA	\$2,764
V9593	14A	POL020401-D - STAFF SUPPORT			CROWN VICTORIA	\$2,764
V9594	02	POL020401-D - STAFF SUPPORT			CROWN VICTORIA	\$2,764
V9595	02	POL020401-D - STAFF SUPPORT			CROWN VICTORIA	\$2,764
V9596	02	POL020401-D - STAFF SUPPORT			CROWN VICTORIA	\$2,764
V9599	02	POL020401-D - STAFF SUPPORT				\$2,764
V9600	02	POL020401-D - STAFF SUPPORT			CROWN VICTORIA	\$2,764
V9604	02	POL020401-D - STAFF SUPPORT			CROWN VICTORIA	\$2,764

	Ba	Ilistic Panel	Re	epla	acemen	t
Unit	2016 CLASS	DEPARTMENT	Year	Make	Model	Ballistic Panel Replacement Cost
V9606	02	POL020401-D - STAFF SUPPORT	2009	FORDX	CROWN VICTORIA	\$2,764
V9607	02	POL020401-D - STAFF SUPPORT	2009	FORDX	CROWN VICTORIA	\$2,764
V9608	02	POL020401-D - STAFF SUPPORT	2009	FORDX	CROWN VICTORIA	\$2,764
V9610	02	POL020401-D - STAFF SUPPORT	2009	FORDX	CROWN VICTORIA	\$2,764
V9611	02	POL020401-D - STAFF SUPPORT	2009	FORDX	CROWN VICTORIA	\$2,764
V9612	02	POL020401-D - STAFF SUPPORT	2009	FORDX	CROWN VICTORIA	\$2,764
V9613	02	POL020401-D - STAFF SUPPORT	2009	FORDX	CROWN VICTORIA	\$2,764
V9615	02	POL020401-D - STAFF SUPPORT	2009	FORDX	CROWN VICTORIA	\$2,764
V9617	02	POL020401-D - STAFF SUPPORT	2009	FORDX	CROWN VICTORIA	\$2,764
V9618	02	POL020401-D - STAFF SUPPORT	2009	FORDX	CROWN VICTORIA	\$2,764
V9620	02	POL020401-D - STAFF SUPPORT	2009	FORDX	CROWN VICTORIA	\$2,764
V9621	02	POL020401-D - STAFF SUPPORT	2009	FORDX	CROWN VICTORIA	\$2,764
V9623	02	POL020401-D - STAFF SUPPORT	2009	FORDX	CROWN VICTORIA	\$2,764
V9624	02	POL020401-D - STAFF SUPPORT	2009	FORDX	CROWN VICTORIA	\$2,764
V9627	02	POL020401-D - STAFF SUPPORT	2009	FORDX	CROWN VICTORIA	\$2,764

CAM #15-0976 Exhibit 2 Page 3 of 3