FIRST AMENDMENT AND CHANGE ORDER NO.1 TO CONSTRUCTION AGREEMENT FOR COOLEY'S LANDING MARINA PARK ADMINISTRATION BUILDING IMPROVEMENTS

THIS FIRST AMENDMEN	T AND CHANGE OF	DER NO.1 to (Construction	Agreemen	it for
Cooley's Landing Marina P	ark Administration Bu	ilding Improver	ments are ma	de this	
day of	_, 2025, by and betwe	en the CITY O	F FORT LAU	JDERDAL	E , a
Florida municipality, ("CITY	'"), with its principal ac	Idress located a	at 101 NE 3rd	Avenue, S	Suite
2100, Fort Lauderdale, Fl	orida 33301, and El	NCOP, INC., a	Florida prof	fit corpora	tion,
("CONTRACTOR"), with	its principal address	located at 78	3rd SW 3rd	Street, N	lorth
Lauderdale, Florida 33068	(collectively, "Parties	").			

WHEREAS, on December 19, 2023, the City Commission approved a construction agreement (CAM #23-1060) between the City and Contractor for Cooley's Landing Marina Park Administration Building Improvements, pursuant to Invitation to Bid ("ITB") Number 178-1 for Project Number 12753 ("Agreement"); and

WHEREAS, on January 26, 2024, the City executed the Agreement with Contractor and issued a Notice to Proceed on January 17, 2025, to complete the work in accordance with the terms and conditions therein; and

WHEREAS, the City and Contractor mutually desire to enter into a First Amendment to the Agreement by amending Section 5.2 of the contract to increase the substantial work completion time from 90 days to 150 days and Section 5.3 to increase the final work completion time from 60 days to 180 days, consistent with the contract time listed in ITB No. 178-1 for Project No. 12753, and subject to and conditioned upon the remaining terms, conditions, and specifications contained in the Agreement including any subsequent renewal terms that are mutually agreed to in a writing and executed by both Parties ("First Amendment"); and

WHEREAS, pursuant to the terms and conditions outlined in Section 14.2 of the Agreement, the City received a written request with supporting documents from Contractor to increase the contract price by a total amount of One Hundred Fifty-Eight Thousand Six Hundred Ninety-Four Dollars (\$158,694) in order to structurally comply with the City's flooding and the Federal Emergency Management Agency (FEMA) requirements to waterproof the existing administration building at Cooley's Landing Park ("Change Order No.1"); and

WHEREAS, the City desires to approve Change Order No. 1 and thereby increasing the contract price from \$376,341 to a total amount of \$535,035;

NOW THEREFORE, for and in consideration of the mutual promises and covenants set forth herein and other good and valuable considerations, the receipt and sufficiency of which is hereby acknowledged, the Parties covenant and agree as follows:

- I. **RECITALS:** The foregoing recitals are true and correct in all respects and are incorporated herein by reference.
- II. **DEFINITIONS:** For purposes of this First Amendment, capitalized terms used

but not defined herein have the meanings assigned to them in the Agreement.

- III. **AMENDMENTS**: The Agreement is amended as follows, subject to and conditioned upon the remaining terms, conditions, and specifications contained in the Agreement, including any subsequent renewal terms that are mutually agreed to in a writing and executed by both Parties:
 - A. Section 5.2 is deleted in its entirety and replaced with the following:
 - 5.2 The work shall be Substanially Completed within 150 calendar days after the date when the Contract Time Commences to run as provided in the Notice to Proceed.
 - B. Section 5.3 is deleted in its entirety and replaced with the following:
 - 5.3 The Work shall be finally completed on the Final Completion Date and ready for the final payment in accordance with this Agreement within 180 calendar days after the date when the Contract Time commences to run as provided in the Notice of Proceed.
- IV. <u>CHANGE ORDER NO. 1</u> Pursuant to Section 14.2 of the Agreement, the City hereby approves Change Order No.1 to increase the contract price by a total amount not to exceed One Hundred Fifty-Eight Thousand Six Hundred Ninety-Four Dollars (\$158,694), thereby increasing the contract price to a total amount of Five Hundred Thirty-Five Thousand Thirty-Five Dollars (\$535,035), and more specifically described in attached **Exhibit A** which is incorporated herein as if fully stated in this First Amendment. The purpose of the Change Order is to structurally comply with the City's flooding and FEMA requirements to waterproof the existing administration building at Cooley's Landing Park.
- V. <u>COUNTERPARTS</u>: This First Amendment and Change Order No. 1 may be executed in one (1) or more counterparts, each of which together shall be deemed and original, but all of which together shall constitute one and the same instrument. In the event that any signature is delivered by facsimile transmission or by e- mail delivery of a .PDF format data file, such signature shall create a valid and binding obligation of the party executing (or on whose behalf such signature is executed) with the same force and effect as if such facsimile or .PDF signature page were an original thereof.
- VI. <u>HEADINGS</u>: Headings herein are for the convenience of reference only and shall not be considered in any interpretation of this First Amendment, Change Order No. 1, or both, or the Agreement.
- VII. **NO OTHER CHANGES:** Except as modified by this First Amendment, Change Order No. 1, or both, all terms, covenants, obligations and provisions of the Agreement, Change Order No. 1, or both, shall remain unaltered, shall continue in full force and effect, and are hereby ratified, approved and

confirmed by the parties in every respect. If the terms and conditions set forth in this First Amendment, Change Order No. 1, or both, directly conflict with any provision contained in the Agreement, then this First Amendment shall control.

[REMAINDER OF THIS PAGE IS INTENTIONALLY LEFT BLANK]

IN WITNESS WHEREOF, the City and the Contractor execute this FIRST AMENDMENT as follows:

	CITY
ATTEST:	CITY OF FORT LAUDERDALE , a Florida Municipality.
David R. Soloman, City Clerk	By: Rickelle Williams, City Manager
	Date:
	Approved as to form and correctness: D'Wayne M. Spence, Interim City Attorney
	By: Patricia SaintVil-Joseph Assistant City Attorney

CONTRACTOR

WITNESSES:	ENCOP, INC., a Florida profit corporation.
	By:
Signature	By: Wolmer De Oliveira, President
Print Name	
Signature	
Print Name	
	[CORPORATE SEAL]
STATE OF:	
COUNTY OF:	
The foregoing instrument was acknown online notarization, this day of President, for ENCOP , INC ., a Floridate	wledged before me by means of □ physical presence or of, 2025, by Wolmer De Oliveira a profit corporation.
[NOTARY SEAL]	
	(Signature of Notary Public - State of Florida)
	(Print, Type, or Stamp Commissioned Name of Notary Public)
Personally Known OR Productory Type of Identification Produced:	ced Identification

Exhibit A



Parks and Recreation Department Route Form

Commission Approval Required

Part 1:	Part 1:									
Master Blanket PO Number: 12621 Master Agreement Number: N/A										
Check One:										
☐ Task Order ☐ Change Order ☐ Quick Quote ☐ Bid Packet ☐ General Routing										
Originator:	Originator: Alex Torres Phone #: 954-828-6231									
Document Title/	Change Or	dor No	1 (مامر	de La	adin	a Mari	กว		
Description Info:	Change Of	uei ivo). I - CC	ole	/ S Lai	lulli	giviaii	Па		
Vendor Name:	Encop, Inc.									
,	P12753	Contract N		N/A			Number o	f Originals:		1 - Digital
CAM Number:	N/A	Task Order	r Number:	N/A			Invoice or	Pay Numb	er:	N/A
Part 2:										
Capital Investment /			-		-					
least \$50,000, and sh	· ·						•			
useful life, including r	najor repairs such	as root rep	lacement, e	tc. The	term "Re	eal Prop	erty" inclu	ides: land,	real	estate,
realty, or real.										
CIP Funded:			×Yes			□No		□N/A (A	aver	tising)
Amount Required:	J		\$158,694	0.60.65	00 04 275	2.4				
Index/Sub-Object Cod	ie:	-	10-129-930	16			1	I		
Parks & Recreation Fi	nance Approval Si	gnature:	Vedasha Roopnarine		Digitally signed by Roopnarine Date: 2025.03.31		Date:			
		73	rtoophanne	- 11	20101 2020.00701					
Part 3: Approval Path	1									
. а. о от търго са. т са.		Approv	ed Retu	ırned	Signa	ature	D	ate	No	t Applicable
Marc Isaac				_	Marc	Digitally signed				
Project Manager II		×	l l		Isaac	Marc Isaac Date. 2025.03.3 11:48:11 -04'00				
Alex Torres				_	Julio Alexis	Digitally signed Julio Alexis Tor				
Senior Project Manag	ger	×	l l	_	Torres	Date: 2025.03.3 12:56:14 -04'00	31			
Enrique Sanchez				7	Enrique	Digitally signed Enrique Sanche	by ez			
Deputy Director - Par	ks and Recreation	×		_	Sanchez					
Carl Williams		×		7	Carl	Digitally signed Carl Williams				
Director - Parks and R	Recreation		L		Williams	Date: 2025.04.0 13:12:16 -04'00	01			
Fill here			٦							
Click here to enter tit			_							
Fill here			١							
Click here to enter title.										
Part 4: External Rout	Part 4: External Routing									
		Signature		Date		Return	ed By:	Date		
Procurement/Finance	9									□N/A
City Manager or Design	gnee									×N/A
City Attorney or Desig	nee									×N/A
2.17 / (2.2.110) 01 50318	55								_	
										□N/A

Please return executed documents to Marc Isaac, extension 5230, Second Floor, Southside Cultural Arts Center.

REV.01.PKR Revision Date: 04/05/2023





To: Rickelle Williams, City Manager

From: Ben Rogers, Acting Assistant City Manager

Date: June 3, 2025

Re: Change Order No. #1 for Project #P12753 Cooley's Landing Marina Admin Building

Job Description: Project P12753, Cooley's Landing Marina

Contractor: Encop, Inc.

Amount: Total amount of Change Order No. 1, \$158,694.00 plus 90 additional days

Funding: 10-129-60-6599-9300-P12753A

The purpose of this Change Order is:

To structurally comply with city flooding and FEMA requirements of waterproofing the existing administration building at Cooley's Land Park. This change order also includes the removal and installation of ceiling and wall insulation, drywall and others due to discovered roof/wall water leaks and mold at the time areas were opened, additional P-traps for proposed laundry and gas piping disposal. Other areas may require additional corrective actions.

NEW AND EXISTING CONTRACT ITEMS ARE UTILIZED – TOTAL CREDIT (\$0,000)

NEW CONTRACT ITEMS ARE UTILIZED – TOTAL ADDITIVE COST \$158,694.00

Item No .26 Ceiling Insulation

1 LS

Remove, haul away existing ceiling insulation and replace with new insulation

ADD \$14,465.00

Item No. 27 Floodproofing Logs

1 LS

Provide and install new dry floodproofing log per approved floodproofing plan

ADD \$43,111.00



Item No.28 **Concrete Columns**

1 LS

Provide solid concreate column or concrete filled cell for hollow block per revised structural sheet and approved floodproofing plan. Pavers at the area to be removed and new concrete surface provided.

ADD \$20,919.00

Item No. 29 Slab Reinforcement

1 LS

Provide concrete slab reinforcement per revised structural sheet and approved floodproofing plan

ADD \$24,095.00

Item No. 30 **Laundry Water and Sewer**

1 LS

Install 3 washing machine outlet boxes and 3 P-traps by revised plans

ADD \$1,860.00

Item No. 31 **Gas Piping**

1 LS

Remove and properly dispose of existing laundry gas supply and reconnect it to the water heater supply line

ADD \$1,950.00

Item No. 32 **Chimenea Air Intake Louver Windows**

1 LS

Remove existing 3 louvers, opening to be infilled and louver to be reinstalled as is

ADD \$1,550.00

Item No. 33 **Exterior Paint**

1 LS

All building's exterior walls shall receive 2 coats of paint over primer

ADD \$19,700.00

PrinCAM #25c0496 er. Exhibit 5

Page 3 of 16

Page 2 of 7

PARKS AND RECREATION DEPARTMENT



Item No. 34 Insulation and Drywall

1 LS

Remove and replace mold affected insulation and drywall in office room and

female restroom

ADD \$8,532.00

Item No. 35 Remove/Reinstall Partial Metal Stair Rails

1 LS

Partial removal and reinstallation of metal stair rails at the electrical room

entrance to allow for flood barrier installation

ADD \$1,270.00

Item No. 36 Exterior Stucco Removal and Replacement Before Applying Elastomeric Paint per

Flooding Requirements

1 LS

Use of appropriate repair methods for the substrate to repair pitting, spalls, cracks,

peeling, blistering, delamination, water damage, or other defects that may exist.

ADD \$13,000.00

Item No. 37 Patch Roof

1 LS

Pat roof flashing at the existing leak position.

ADD \$750.00

Item No. 38 Exhaust Fans Replacement

1 LS

(2) units of Panasonic FV40VQ4-380CFM quiet exhaust fans replacements with

existing duct work.

ADD \$3,970.00

Item No. 39 Kitchen Partition

1 LS

New kitchen partition in lieu of modular office partition by others.

ADD \$3,522.00

PARKS AND RECREATION DEPARTMENT

Page 3 of 7



NET AMOUNT OF THIS CHANGE ORDER \$158,694.00

ADDITIONAL CONTRACT TIME BEING REQUESTED NINETY (90) CALENDAR DAYS

THE TOTAL AMOUNT OF THIS CHANGE ORDER \$158,694.00

PARKS AND RECREATION DEPARTMENT



This Change Order provides for all costs and schedule adjustments associated with completing the work, including materials, labor, equipment, bond, insurance, overhead, profit, impacts, and any and all related items or associated costs incurred or resulting from the items listed above, and is provided in accordance with Article 13 – Changes in the Work of the Contract.

IN WITNESS OF THE FOREGOING, the parties have set their hands and seals the day and year first written below.

Encop, Inc.

Approved: 5/22/2025

Wolmer F. Oliveira, President



IN WITNESS OF THE FOREGOING, the Parties have set their hands and seals the day and year first written above.

<u>CITY</u>

CITY OF FORT LAUDERDALE, a Florida municipa corporation.
By:RICKELLE WILLIAMS
City Manager
Date:
ATTEST:
By: DAVID R. SOLOMAN
City Clerk
Approved as to Legal Form and Correctness: D'Wayne M. Spence, Interim City Attorney
Ву:
PATRICIA SAINTVIL-JOSEPH
Assistant City Attorney

REV.21.COM Revision Date: 10/03/2024 Approved by: Alan Dodd

TELEPHONE (954) 828-6250

WWW.FORTLAUDERDALE.GOV

Page 6 of 7

CHANGE ORDER SUMMARY SHEET

ORIGINAL CONTRACT AMOUNT \$376,341.00

COST OF CHANGE ORDERS TO DATE \$0.00

COST OF THIS CHANGE ORDER \$158,694.00

TOTAL: \$535,035.00

ORIGINAL CONTRACT TIME 180 calendar days

TIME ADDED TO DATE 0 calendar days

TIME ADDED TO THIS CHANGE ORDER 90 calendar days

TOTAL: 270 calendar days

SCHEDULE OF CHANGE ORDERS TO DATE

AMOUNT OF COST OR C.O.# DATE DESCRIPTION CREDIT

PARKS AND RECREATION DEPARTMENT

Proposal

Date of submission: 5/19/2025

7858 SW 3RD ST - North Lauderdale FI 33068 Tel 754 367 2115 encopinc@hotmail.com

Submitted by: Vendor 15730

ENCOP, INC. Wolmer Oliveira

Submitted to: City of Fort Lauderdale
Alex Torres – Project Manager

Project name: Event 178 - Cooley's Landing

Renovations

P.O Number: 7132

Job address: 450 SW 7th Avenue, Fort Lauderdale FL, 33312

We hereby submit estimates to provide material and Labor for:

Miscellaneous Services.

Scope of work: This proposal outlines the scope of work and estimated costs for additional Miscellaneous Services as described below.

Item	No .1 Ceiling Insulation	
	1 LS	
	Remove, haul away existing ceiling insulation and	
	replace with new insulation	
Item		Total Cost
-	Open cell spray 8" R30 open cell spray foam in roof rafters, ridge to wall. Includes spraying 3" R11 open cell in masonry gable walls - 1500Sqft	\$8,643.00
	Removal & disposal of existing fiberglass insulation 1,400 Sqft	\$2,500.00
-	Install blocker at perimeter soffit to spray against and complete thermal envelope - 50Lft	\$3,322.00
Total		\$14,465.00

Item N	No.2 Flood Proofing Logs	
	1 LS Provide and install new dry floodproofing log per approved floodproofing plan	
Item		Total Cost
- 1	Floodproofing logs - 3 doors by plans	\$17,334.28
- :	Installation labor and material	\$25,776.72
Total		\$43,111.00

Item No.3	Concrete Columns	
	1 LS Provide solid concreate column or concrete filled cell for hollow block per revised structural sheet and approved floodproofing plan. Pavers at the area to be removed and new concrete surface provided, to allow for new flood proofing logs installation.	
Item		Total Cost
_	all removal, replacement, finish and painting, concrete block removal to allow for 6 new mns.	\$3,000.00
- Six n	new concrete column installations	\$9,000.00
- New c	concrete slab surface	\$7,000.00
- Paver	removal & disposal to allow for a new concrete	\$1,919.00
Total		\$20,919.00

Item	No. 4 Slab Reinforcement	
	1 LS Provide concrete slab reinforcement per revised structural sheet and approved floodproofing plan. 1,400 Sqft	
Item		Total Cost
-	Cut new 50 trenches, 3"wx3"d at slab mid span spaced as per plan.	\$6,000.00
-	Clean out dust, roughen up, and add bonding agent to 50 trenches.	\$2,400.00
-	Place #5 horizontal rebar by drill and dowel beyond 5" deep using epoxy.	\$10,695.00
-	Fill 122 linear feet of trenches with 5,000 psi non shrinking grout and finish to allow to receive new flooring.	\$5,000.00
Total		\$24,095.00

Item	No. 5 Laundry Water and Sewer 1 LS Install 3 washing machine outlet boxes and 3 P-traps by revised plans	
Item		Total Cost
-	Outlet boxes - 3 units	\$240.00
-	P-traps - 3 units	\$150.00
-	Plumbing installation - 32 Lft	\$1,470.00
Total		\$1,860.00

Item	No. 6 Gas Piping	
	1 LS Remove and properly dispose of existing laundry gas supply and reconnect it to the water heater supply line	
Item		Total Cost
-	New gas line	\$400.00
-	Fittings & connectors	\$300.00
-	Labor	\$1,250.00
Total		\$1,950.00

Item No. 7 Chimenea Air Intake Louver Windows	
1 LS Remove existing 3 louvers, opening to be infilled and louver to be reinstalled as is	
Item	Total Cost
- Louver removal & reinstallation	\$1,250.00
- Opening infill materials	\$300.00
Total	\$1,550.00

Item No. 8 Exterior Elastomeric Paint for Floodproofing	
1 LS All building's exterior walls and soffits shall receive 2 coats of paint over primer - 4,570 Sqft	
Item	Total Cost
- Excavate to open ground around building (12" from walls x 18" deep)	\$2,400.00
- Pressure clean exterior walls and soffits	\$2,230.00
- Prime all exterior walls with elastocolor primer WB	\$5,700.00
- Mapei elastocolor 2 coats	\$8,320.00
- Caulk around all exterior windows	\$1,050.00
Total	\$19,700.00

Item	No. 9	Insulation and Drywall	
		1 LS Remove and replace 440 Sqft of mold affected insulation and drywall in office room and female restroom	
Item			Total Cost
-	Remove	and replace insulation and drywall	\$8,532.00
Total			\$8,532.00

Item No. 10	Remove/Reinstall Partial Metal Stair Rails	
	1 LS Partial removal and reinstallation of metal stair rails at the electrical room entrance to allow for flood barrier installation	
Item Total		Total Cost \$1,270.00

Item No	. 11 Exterior Stucco Removal and Replacement Before Applying Elastomeric Paint per Flooding Requirements	
	1 LS Use of appropriate repair methods for the substrate to repair pitting, spalls, cracks, peeling, blistering, delamination, water damage, or other defects that may exist. Approximated 800 Sqft	
Item		Total Cost
pe ot	tucco removal to repair pitting, spalls, cracks, eeling, blistering, delamination, water damage, or ther defects that could allow water to enter ne building, for new stucco application.	\$13,000.00
Total		\$13,000.00

Item	No. 12 Patch Roof Leak Repair	
	1 LS Pat roof flashing at the existing leak position. 60 Sqft	
Item		Total Cost
-	Flashing repair materials	\$100.00
-	Labor	\$650.00
Total		\$750.00

Item	No. 13 Exhaust Fans Replacement	
	1 LS (2) units of Panasonic FV40VQ4-380CFM quiet exhaust fans replacement with existing duct work.	
Item		Total Cost
-	Panasonic fv40vq4-380cfm fans and accessories	\$1,700.00
-	Installation materials	\$500.00
-	Labor	\$1,770.00
Total		\$3,970.00

Item No.	14 Kitchen Wall Partition	
	1 LS	
	New kitchen partition in lieu of modular office	
	partition by others. 70 Sqft	
Item		Total Cost
- Me	tal studs 2-1/2" (20 gauge)	\$360.00
- Tr	ack for metal studs	\$100.00
- Mo	isture-resistant drywall 1/2"	\$210.00
- Dr	ywall screws	\$20.00
- Jo	int compound & tape	\$40.00
- Pr	imer & paint for finishing	\$80.00
- Ca	ulk for sealing edges	\$24.00
- Fr	aming installation (metal studs & track)	\$680.00
- Dr	ywall installation	\$630.00
- Ta	oing & finishing	\$450.00
- Pr	iming & painting	\$538.00
- Se	aling (caulking & final touches)	\$390.00
Total		\$3,522.00

<u>Encop, Inc.</u> proposes to furnish the aforementioned material and labor in accordance with the above conditions for the sum of \$158,694.00 (One Hundred Fifty-eight thousand, six hundred ninety-four Dollars).

This proposal does not include:

Any job not related to above specifications and/or plans. Architectural and/or engineering plans, City permit fees, additional services required by the city. Services and any material not related to the above scope of work described.

Encop, Inc. Signed By: Wolmer F. Oliveira	Date: 5/19/2025
President	
This is your authorization to complete and reverse sides of this proposal.	the work as outlined above according to conditions on the front
Acceptance Signed By:	Date:
When both parties sign this proposal	this instrument constitutes a legal and hiding contract hetween

When both parties sign this proposal, this instrument constitutes a legal and biding contract between the parties.

This proposal may be withdrawn if not accepted within fifteen (15) days from date of submission.



INSULATION AT UNDERSIDE OF ROOF DECK	City of Fort Lauderdale - Cooley's Landing Restroom Renovations Statement of Probable Cost				5/21/202
A Remove all existing eciling insulation	tem Description	Qty.	Unit	Unit Cost	Co
A Remove all existing eciling insulation	1 INSULATION AT UNDERSIDE OF BOOK DECV				
b		1.506	C II	¢1.50	\$2.250.0
Installation of barrier at perimeter of work area					
Property					\$2,550.0
A					
b					
Commonstrate Section					\$1,920.0
Installation of Concrete base to receive logs 48 SF \$150.00 \$7,200					\$45,000.0
Installation of required finishes, gyp bd, paint, etc.					\$9,000.0
Slab Preparation					
a Slab Preparation	e Installation of required finishes, gyp bd, paint, etc.	- 6	ΕA	\$500,00	\$3,000.0
Description of the property of the project of the	3 SLAB REINFORCEMENT				
4 MISCELLANEOUS LAUNDRY WORK a Outlet boxes, P traps 6 EA \$100.00 \$6000 30 LF \$50.00 \$1,500 5 GAS SUPPLY LINE a Installation of gas line to water heater, fittings, etc. 1 LS \$2,100 6 TOWER LOUVER WORK a Remove louvers, block opening, reinstall louver 3 EA \$550.00 \$1,650 7 WATERPROOFING EXTERIOR WALL COATING a Prepare walls, apply coating, catulk, etc. 4,500 SF \$4.50 \$20,250 8 DRYWALL AND INSULATION REPLACEMENT a Remove and install gyp bd & insulation at area affected by water infiltration 440 SF \$35.00 \$15,400 9 EXTERIOR STAIR HANDRAIL REPAIR a Remove, cut to fit new flood log system, and reinstall handrail 1 LS \$1,300 10 EXTERIOR STUCCO REPAIR a Removal of hollow, delaminated stucco. 800 SF \$18.00 \$14,400 11 ROOF LEAK REPAIR a Roof leak repair at valley 60 SF \$25.00 \$1,000 12 EXHAUST FAN REPLACEMENT a Install thin 3-1/2" wide partition with 2-1/2" studs and 1/2" gyp. bd. Finish, etc. 70 SF \$45.00 \$3,150 13 BREAKROOM PARTITION a Install thin 3-1/2" wide partition with 2-1/2" studs and 1/2" gyp. bd. Finish, etc. 70 SF \$45.00 \$3,150 Overhead and Profit (15%) \$25,818	a Slab Preparation	1,394	SF	\$9.00	\$12,546.0
Outlet boxes, P traps	b Place rebar and concrete fill trenches	1,394	SF	\$11.00	\$15,334.0
Outlet boxes, P traps					
5 GAS SUPPLY LINE a Installation of gas line to water heater, fittings, etc. 6 TOWER LOUVER WORK a Remove louvers, block opening, reinstall louver 7 WATERPROOFING EXTERIOR WALL COATING a Prepare walls, apply coating, caulk, etc. 4,500 SF \$4.50 S20,250 BOYWALL AND INSULATION REPLACEMENT a Remove and install gyp bd & insulation at area affected by water infiltration 440 SF \$35.00 S15,400 BOYWALL AND INSULATION REPLACEMENT a Remove and install gyp bd & insulation at area affected by water infiltration 440 SF \$35.00 S15,400 SIT, 400 EXTERIOR STAIR HANDRAIL REPAIR a Remove, cut to fit new flood log system, and reinstall handrail 1 LS S1,300 EXTERIOR STUCCO REPAIR a Removal of hollow, delaminated stucco. 800 SF \$18.00 S14,400 II ROOF LEAK REPAIR a Roof leak repair at valley 60 SF \$25.00 S1,000 12 EXHAUST FAN REPLACEMENT a Install an exhaust fan per restroom 2 EA S1,800.00 S3,600 13 BREAKROOM PARTITION a Install thin 3-1/2" wide partition with 2-1/2" studs and 1/2" gyp. bd. Finish, etc. 70 SF \$45.00 S3,150 S25,818 Overhead and Profit (15%) S25,818 Diverhead and Profit (15%) S25,818		6	EA	\$100.00	\$600.0
5 GAS SUPPLY LINE a Installation of gas line to water heater, fittings, etc. 6 TOWER LOUVER WORK a Remove louvers, block opening, reinstall louver 7 WATERPROOFING EXTERIOR WALL COATING a Prepare walls, apply ceating, caulk, etc. 4,500 SF \$4.50 S20,250 8 DRYWALL AND INSULATION REPLACEMENT a Remove and install gyp bd & insulation at area affected by water infiltration 440 SF \$35.00 S15,400 9 EXTERIOR STAIR HANDRAIL REPAIR a Remove, cut to fit new flood log system, and reinstall handrail 1 LS S1,300 EXTERIOR STUCCO REPAIR a Removal of hollow, delaminated stucco. 800 SF \$18.00 S14,400 11 ROOF LEAK REPAIR a Roof leak repair at valley 60 SF \$25.00 S1,000 12 EXHAUST FAN REPLACEMENT a Install an exhaust fan per restroom 2 EA \$1,800,00 \$3,600 13 BREAKROOM PARTITION a Install thin 3-1/2" wide partition with 2-1/2" studs and 1/2" gyp. bd. Finish, etc. 70 SF \$45.00 S3,150 13 BREAKROOM PARTITION a Install thin 3-1/2" wide partition with 2-1/2" studs and 1/2" gyp. bd. Finish, etc. 70 SF \$45.00 S3,150 15 Subtotal S172,123 16 Students does not include asbestes abstenest for floorfeeding removal. This "rotable Construction Cust Estimate is based on the specific existing conditions for the project. Costs are based Mader. 2025 pricing and should be adjusted to accountly for market conditions and inflation as the project moves waved. Overhead and Profit (15%) S25,818 Overhead and Profit (15%) S25,818	a Ounet boxes, F traps	45 45 5		The second secon	
a Installation of gas line to water heater, fittings, etc. f TOWER LOUVER WORK a Remove louvers, block opening, reinstall louver a Remove louvers, block opening, reinstall louver b VATERPROOFING EXTERIOR WALL COATING a Prepare walls, apply coating, caulk, etc. b Prepare walls, apply coating, caulk, etc. c Prepare walls, apply coating, caulk, etc. b Prepare walls, apply coating, caulk, etc. c Prepare walls, apply coating, caulk, etc. d 4,500 SF \$4.50 S20,250 c SE \$4.50 S20,250 c SE \$4.50 SE0,250 c SE \$35,00 S15,400 c SE \$35,00 S15,400 c SE \$35,00 S15,400 c SE \$18,00 S14,400 c SE \$18,00 S14,400 c SE \$18,00 S14,400 c SE \$18,00 S14,400 c SE \$25,00 S10,000 c SE \$25,00 S10,000 c SE \$25,00 S10,000 c SE \$25,00 S10,000 c SE \$325,00 S10,000 c SE \$4.50 SE0,000 S3,600 c SE0,000 S5,600 c SE \$4.50 SE0,000 S3,600 c SE0,000 S5,600 c SE		50	2.1	\$20.00	ψ1,500.t
6 TOWER LOUVER WORK a Remove louvers, block opening, reinstall louver 7 WATERPROOFING EXTERIOR WALL COATING a Prepare walls, apply coating, eaulk, etc. 4,500 SF \$4,50 \$20,250 8 DRYWALL AND INSULATION REPLACEMENT a Remove and install gyp bd & insulation at area affected by water infiltration 440 SF \$35,00 \$15,400 9 EXTERIOR STAIR HANDRAIL REPAIR a Remove, cut to fit new flood log system, and reinstall handrail 1 LS \$1,300 10 EXTERIOR STUCCO REPAIR a Removal of hollow, delaminated stucco. 800 SF \$18,00 \$14,400 11 ROOF LEAK REPAIR a Roof leak repair at valley 60 SF \$25,00 \$1,000 12 EXHAUST FAN REPLACEMENT a Install an exhaust fun per restroom 2 EA \$1,800,00 \$3,600 13 BREAKROOM PARTITION a Install thin 3-1/2" wide partition with 2-1/2" studs and 1/2" gyp, bd. Finish, etc. 70 SF \$45,00 \$3,150 Overhead and Profit (15%) \$25,818 Overhead and Profit (15%) \$25,818 Does to fectors such as tariffs on imported items and general babor shortages construction costs may vary considerably.	5 GAS SUPPLY LINE				
a Remove louvers, block opening, reinstall louver 7 WATERPROOFING EXTERIOR WALL COATING a Prepare walls, apply coating, caulk, etc. 4,500 SF \$4.50 S20,250 8 DRYWALL AND INSULATION REPLACEMENT a Remove and install gyp bd & insulation at area affected by water infiltration 440 SF \$35,00 S15,400 9 EXTERIOR STAIR HANDRAIL REPAIR a Remove, cut to fit new flood log system, and reinstall handrail 1 LS S1,300 10 EXTERIOR STUCCO REPAIR a Removal of hollow, delaminated stucco. 800 SF \$18.00 S14,400 11 ROOF LEAK REPAIR a Roof leak repair at valley 60 SF \$25.00 S1,000 12 EXHAUST FAN REPLACEMENT a Install an exhaust fan per restroom 2 EA S1,800,00 S3,600 13 BREAKROOM PARTITION a Install thin 3-1/2" wide partition with 2-1/2" studs and 1/2" gyp. bd. Finish, etc. 70 SF \$45.00 S3,150 13 BREAKROOM PARTITION a Install thin 3-1/2" wide partition with 2-1/2" studs and 1/2" gyp. bd. Finish, etc. 70 SF \$45.00 S3,150 15 Subtotal S172,123 16 Subtotal S172,123 17 Subtotal S172,123 18 Subtotal S172,123 18 Subtotal S172,123 18 Subtotal S172,123 18 Subtotal S172,123	a Installation of gas line to water heater, fittings, etc.	1	LS		\$2,100.0
a Remove louvers, block opening, reinstall louver 7 WATERPROOFING EXTERIOR WALL COATING a Prepare walls, apply coating, caulk, etc. 4,500 SF \$4.50 S20,250 8 DRYWALL AND INSULATION REPLACEMENT a Remove and install gyp bd & insulation at area affected by water infiltration 440 SF \$35,00 S15,400 9 EXTERIOR STAIR HANDRAIL REPAIR a Remove, cut to fit new flood log system, and reinstall handrail 1 LS S1,300 10 EXTERIOR STUCCO REPAIR a Removal of hollow, delaminated stucco. 800 SF \$18.00 S14,400 11 ROOF LEAK REPAIR a Roof leak repair at valley 60 SF \$25.00 S1,000 12 EXHAUST FAN REPLACEMENT a Install an exhaust fan per restroom 2 EA S1,800,00 S3,600 13 BREAKROOM PARTITION a Install thin 3-1/2" wide partition with 2-1/2" studs and 1/2" gyp. bd. Finish, etc. 70 SF \$45.00 S3,150 13 BREAKROOM PARTITION a Install thin 3-1/2" wide partition with 2-1/2" studs and 1/2" gyp. bd. Finish, etc. 70 SF \$45.00 S3,150 15 Subtotal S172,123 16 Subtotal S172,123 17 Subtotal S172,123 18 Subtotal S172,123 18 Subtotal S172,123 18 Subtotal S172,123 18 Subtotal S172,123	Z TOWNS LOWER WORK				
7 WATERPROOFING EXTERIOR WALL COATING a Prepare walls, apply coating, eaulk, etc. 4,500 SF \$4.50 S20,250 8 DRYWALL AND INSULATION REPLACEMENT a Remove and install gyp bd & insulation at area affected by water infiltration 440 SF \$35.00 \$15,400 9 EXTERIOR STAIR HANDRAIL REPAIR a Remove, cut to fit new flood log system, and reinstall handrail 1 LS \$1,300 10 EXTERIOR STUCCO REPAIR a Removal of hollow, delaminated stucco. 800 SF \$18.00 \$14,400 11 ROOF LEAK REPAIR a Roof leak repair at valley 60 SF \$25.00 \$1,000 12 EXHAUST FAN REPLACEMENT a Install an exhaust fan per restroom 2 EA \$1,800.00 \$3,600 13 BREAKROOM PARTITION a Install thin 3-1/2" wide partition with 2-1/2" studs and 1/2" gyp. bd. Finish, etc. 70 SF \$45.00 \$3,150 11 Probable Construction Cust Estimate is based on the specific existing conditions for the project. Costs are based March 2015 pricing, and should be adjusted in account for market conditions and inflation as the project moves reward. 11 Due to factors such as tariffs on impurted tiems and general labor shortages construction costs may vary considerably.		2	EA	9550.00	\$1.650.1
a Prepare walls, apply coating, eaulk, etc. 8 DRYWALL AND INSULATION REPLACEMENT a Remove and install gyp bd & insulation at area affected by water infiltration 440 SF \$35,00 S15,400 9 EXTERIOR STAIR HANDRAIL REPAIR a Remove, cut to fit new flood log system, and reinstall handrail 1 LS S1,300 10 EXTERIOR STUCCO REPAIR a Removal of hollow, delaminated stucco. 800 SF \$18.00 S14,400 11 ROOF LEAK REPAIR a Roof leak repair at valley 60 SF \$25.00 S1,000 12 EXHAUST FAN REPLACEMENT a Install an exhaust fan per restroom 2 EA \$1,800.00 \$3,600 13 BREAKROOM PARTITION a Install thin 3-1/2" wide partition with 2-1/2" studs and 1/2" gyp. bd. Finish, etc. 70 SF \$45.00 S3,150 21 Subtotal S172,123 22 Extinuite does not include subsesso abatement for floor/sciling removal. This Probable Construction Cost Estimate is based on the specific existing conditions for the project. Costs are based of March 2025 pricing, and should be adjusted to account for market conditions and inflation as the project moves revard. Due to factors such as tariffs on impured items and general labor shortages construction costs may vary considerably.	a Remove touvers, block opening, reinstan touver	3	EA	\$330.00	51,050.
8 DRYWALL AND INSULATION REPLACEMENT a Remove and install gyp bd & insulation at area affected by water infiltration 440 SF \$35,00 \$15,400 9 EXTERIOR STAIR HANDRAIL REPAIR a Remove, cut to fit new flood log system, and reinstall handrail 1 LS \$1,300 10 EXTERIOR STUCCO REPAIR a Removal of hollow, delaminated stucco. 800 SF \$18.00 \$14,400 11 ROOF LEAK REPAIR a Roof leak repair at valley 60 SF \$25.00 \$1,000 12 EXHAUST FAN REPLACEMENT a Install an exhaust finn per restroom 2 EA \$1,800.00 \$3,600 13 BREAKROOM PARTITION a Install thin 3-1/2" wide partition with 2-1/2" studs and 1/2" gyp. bd. Finish, etc. 70 SF \$45.00 \$3,150 13 BREAKROOM PARTITION a Install thin 3-1/2" wide partition with 2-1/2" studs and 1/2" gyp. bd. Finish, etc. 70 SF \$45.00 \$3,150 15 Subtotal \$172,123	7 WATERPROOFING EXTERIOR WALL COATING				
Remove and install gyp bd & insulation at area affected by water infiltration 440 SF \$35,00 S15,400 PEXTERIOR STAIR HANDRAIL REPAIR Remove, cut to fit new flood log system, and reinstall handrail 1 LS \$1,300 EXTERIOR STUCCO REPAIR Removal of hollow, delaminated stucco. 800 SF \$18.00 S14,400 11 ROOF LEAK REPAIR Removal of hollow, delaminated stucco. 800 SF \$25.00 S1,000 12 EXHAUST FAN REPLACEMENT Install an exhaust fun per restroom 2 EA \$1,800.00 \$3,600 13 BREAKROOM PARTITION Install thin 3-1/2" wide partition with 2-1/2" studs and 1/2" gyp. bd. Finish, etc. 15 Subtotal 16 SIF \$45.00 S3,150 17 SIF \$45.00 S3,150 18 Subtotal S172,123 18 Subtotal S172,123 18 Subtotal S172,123 This Probable Construction Cost Estimate is based on the specific existing conditions for the project. Costs are based to March 2025 pricing, and should be adjusted to account for market conditions and inflation as the project moves revent. The to factors such as tariffs on imported items and general labor shortages construction costs may vary considerably.	a Prepare walls, apply coating, caulk, etc.	4,500	SF	\$4.50	\$20,250.0
Remove and install gyp bd & insulation at area affected by water infiltration 440 SF \$35,00 S15,400 PEXTERIOR STAIR HANDRAIL REPAIR Remove, cut to fit new flood log system, and reinstall handrail 1 LS \$1,300 EXTERIOR STUCCO REPAIR Removal of hollow, delaminated stucco. 800 SF \$18.00 S14,400 11 ROOF LEAK REPAIR Removal of hollow, delaminated stucco. 800 SF \$25.00 S1,000 12 EXHAUST FAN REPLACEMENT Install an exhaust fun per restroom 2 EA \$1,800.00 \$3,600 13 BREAKROOM PARTITION Install thin 3-1/2" wide partition with 2-1/2" studs and 1/2" gyp. bd. Finish, etc. 15 Subtotal 16 SIF \$45.00 S3,150 17 SIF \$45.00 S3,150 18 Subtotal S172,123 18 Subtotal S172,123 18 Subtotal S172,123 This Probable Construction Cost Estimate is based on the specific existing conditions for the project. Costs are based to March 2025 pricing, and should be adjusted to account for market conditions and inflation as the project moves revent. The to factors such as tariffs on imported items and general labor shortages construction costs may vary considerably.					
9 EXTERIOR STAIR HANDRAIL REPAIR a Remove, cut to fit new flood log system, and reinstall handrail 1 LS \$1,300 10 EXTERIOR STUCCO REPAIR a Removal of hollow, delaminated stuceo. 800 SF \$18.00 \$14,400 11 ROOF LEAK REPAIR a Roof leak repair at valley 60 SF \$25.00 \$1,000 12 EXHAUST FAN REPLACEMENT a Install an exhaust fan per restroom 2 EX S1,800,00 \$3,600 13 BREAKROOM PARTITION a Install thin 3-1/2" wide partition with 2-1/2" studs and 1/2" gyp. bd. Finish, etc. 70 SF \$45.00 \$3,150 13 Install thin 3-1/2" wide partition with 2-1/2" studs and 1/2" gyp. bd. Finish, etc. 70 SF \$45.00 \$3,150 15 Probable Construction Cost Estimate is based on the specific existing conditions for the project. Costs are based of March 2025 pricing, and should be adjusted to account for market conditions and inflation as the project moves reward. This Probable Construction Cost Estimate is based on the specific existing conditions for the project. Costs are based of March 2025 pricing, and should be adjusted to account for market conditions and inflation as the project moves reward. Due to factors such as tariffs on imported items and general labor shortages construction costs may vary considerably.				****	
a Remove, cut to fit new flood log system, and reinstall handrail 1 LS \$1,300 10 EXTERIOR STUCCO REPAIR a Removal of hollow, delaminated stucco. 800 SF \$18.00 S14,400 11 ROOF LEAK REPAIR a Roof leak repair at valley 60 SF \$25.00 \$1,000 12 EXHAUST FAN REPLACEMENT a Install an exhaust fan per restroom 1 Install an exhaust fan per restroom 2 EA \$1,800.00 \$3,600 13 BREAKROOM PARTITION a Install thin 3-1/2" wide partition with 2-1/2" studs and 1/2" gyp. bd. Finish, etc. 15 SF \$45.00 \$3,150 26 SF \$45.00 \$3,150 27 SF \$45.00 \$3,150 28 Subtotal \$172,123 29 SE \$45.00 \$3,150 20 SE \$100 \$100 \$100 \$100 \$100 \$100 \$100 \$10	a Remove and install gyp od & insulation at area affected by water infiltration	440	SF	\$35.00	\$15,400.
a Remove, cut to fit new flood log system, and reinstall handrail 1 LS \$1,300 10 EXTERIOR STUCCO REPAIR a Removal of hollow, delaminated stucco. 800 SF \$18.00 S14,400 11 ROOF LEAK REPAIR a Roof leak repair at valley 60 SF \$25.00 \$1,000 12 EXHAUST FAN REPLACEMENT a Install an exhaust fan per restroom 1 Install an exhaust fan per restroom 2 EA \$1,800.00 \$3,600 13 BREAKROOM PARTITION a Install thin 3-1/2" wide partition with 2-1/2" studs and 1/2" gyp. bd. Finish, etc. 15 SF \$45.00 \$3,150 26 SF \$45.00 \$3,150 27 SF \$45.00 \$3,150 28 Subtotal \$172,123 29 SE \$45.00 \$3,150 20 SE \$100 \$100 \$100 \$100 \$100 \$100 \$100 \$10	9 EXTERIOR STAIR HANDRAIL REPAIR				
10 EXTERIOR STUCCO REPAIR a Removal of hollow, delaminated stucco. 11 ROOF LEAK REPAIR a Roof leak repair at valley 12 EXHAUST FAN REPLACEMENT a Install an exhaust fan per restroom 13 BREAKROOM PARTITION a Install thin 3-1/2" wide partition with 2-1/2" studs and 1/2" gyp. bd. Finish, etc. 14 Install thin 3-1/2" wide partition with 2-1/2" studs and 1/2" gyp. bd. Finish, etc. 15 Estimate does not include asbestos abatement for floor/ceiling removal. This Probable Construction Cost Estimate is based on the specific existing conditions for the project. Costs are based where the project costs are based on the specific existing conditions and inflation as the project moves reward. The floor of factors such as tariffs on imported items and general labor shortages construction costs may vary considerably.		1	LS		\$1,300.
A Removal of hollow, delaminated stucco. 11 ROOF LEAK REPAIR a Roof leak repair at valley 12 EXHAUST FAN REPLACEMENT a Install an exhaust fan per restroom 13 BREAKROOM PARTITION a Install thin 3-1/2" wide partition with 2-1/2" studs and 1/2" gyp. bd. Finish, etc. 14 Install thin 3-1/2" wide partition with 2-1/2" studs and 1/2" gyp. bd. Finish, etc. 15 Install thin 3-1/2" wide partition with 2-1/2" studs and 1/2" gyp. bd. Finish, etc. 16 Install thin 3-1/2" wide partition with 2-1/2" studs and 1/2" gyp. bd. Finish, etc. 17 Install thin 3-1/2" wide partition with 2-1/2" studs and 1/2" gyp. bd. Finish, etc. 18 Install thin 3-1/2" wide partition with 2-1/2" studs and 1/2" gyp. bd. Finish, etc. 29 Install thin 3-1/2" wide partition with 2-1/2" studs and 1/2" gyp. bd. Finish, etc. 30 Install thin 3-1/2" wide partition with 2-1/2" studs and 1/2" gyp. bd. Finish, etc. 40 Install thin 3-1/2" wide partition with 2-1/2" studs and 1/2" gyp. bd. Finish, etc. 50 Install thin 3-1/2" wide partition with 2-1/2" studs and 1/2" gyp. bd. Finish, etc. 50 Install thin 3-1/2" wide partition with 2-1/2" studs and 1/2" gyp. bd. Finish, etc. 50 Install thin 3-1/2" wide partition with 2-1/2" studs and 1/2" gyp. bd. Finish, etc. 50 Install thin 3-1/2" wide partition with 2-1/2" studs and 1/2" gyp. bd. Finish, etc. 50 Install thin 3-1/2" wide partition with 2-1/2" studs and 1/2" gyp. bd. Finish, etc. 50 Install thin 3-1/2" wide partition with 2-1/2" studs and 1/2" gyp. bd. Finish, etc. 50 Install thin 3-1/2" wide partition with 2-1/2" studs and 1/2" gyp. bd. Finish, etc. 50 Install thin 3-1/2" wide partition with 2-1/2" studs and 1/2" gyp. bd. Finish, etc. 50 Install thin 3-1/2" wide partition with 2-1/2" studs and 1/2" gyp. bd. Finish, etc. 51 Install thin 3-1/2" wide partition with 2-1/2" studs and 1/2" gyp. bd. Finish, etc. 51 Install thin 3-1/2" wide partition with 2-1/2" studs and 1/2" gyp. bd. Finish, etc. 51 Install thin 3-1/2" wide partition with 2-1/2" studs and 1/2" gyp. bd. Finish, etc. 52 Install thin					
11 ROOF LEAK REPAIR a Roof leak repair at valley 60 SF \$25.00 \$1,000 12 EXHAUST FAN REPLACEMENT a Install an exhaust fan per restroom 2 EA \$1,800.00 \$3,600 13 BREAKROOM PARTITION a Install thin 3-1/2" wide partition with 2-1/2" studs and 1/2" gyp. bd. Finish, etc. 13 BREAKROOM PARTITION a Install thin 3-1/2" wide partition with 2-1/2" studs and 1/2" gyp. bd. Finish, etc. 5 SF \$45.00 \$3,150 2 EA \$1,800.00 \$3,600 ST \$25.00 \$3,600 ST \$25.00 \$3,600 ST \$45.00 \$3,150 ST \$45.00 \$53,150 ST \$45.00 \$50,150 ST \$45.00 \$50,150 ST \$45.00 \$50		- American			
a Roof leak repair at valley EXHAUST FAN REPLACEMENT a Install an exhaust fan per restroom 2 EA \$1,800.00 \$3,600 13 BREAKROOM PARTITION a Install thin 3-1/2" wide partition with 2-1/2" studs and 1/2" gyp. bd. Finish, etc. 70 SF \$45.00 \$3,150 eneral Notes & Disclaimers: Estimate does not include asbestos abatement for floor/eciling removal. This Probable Construction Cost Estimate is based on the specific existing conditions for the project. Costs are based to March 2025 pricing, and should be adjusted to account for market conditions and inflation as the project moves reward. Due to factors such as tariffs on imported items and general labor shortages construction costs may vary considerably.	a Removal of hollow, delaminated stucco.	800	SF	\$18.00	\$14,400.
a Roof leak repair at valley EXHAUST FAN REPLACEMENT a Install an exhaust fan per restroom 2 EA \$1,800.00 \$3,600 13 BREAKROOM PARTITION a Install thin 3-1/2" wide partition with 2-1/2" studs and 1/2" gyp. bd. Finish, etc. 70 SF \$45.00 \$3,150 eneral Notes & Disclaimers: Estimate does not include asbestos abatement for floor/eciling removal. This Probable Construction Cost Estimate is based on the specific existing conditions for the project. Costs are based to March 2025 pricing, and should be adjusted to account for market conditions and inflation as the project moves reward. Due to factors such as tariffs on imported items and general labor shortages construction costs may vary considerably.	11 POOF I FAK REPAIR				
12 EXHAUST FAN REPLACEMENT a Install an exhaust fan per restroom 2 EA \$1,800.00 \$3,600 13 BREAKROOM PARTITION a Install thin 3-1/2" wide partition with 2-1/2" studs and 1/2" gyp. bd. Finish, etc. 70 SF \$45.00 \$3,150 eneral Notes & Disclaimers: Estimate does not include asbestos abatement for floor/eciling removal. This Probable Construction Cost Estimate is based on the specific existing conditions for the project. Costs are based to March 2025 pricing, and should be adjusted to account for market conditions and inflation as the project moves revard. Due to factors such as tariffs on imported items and general labor shortages construction costs may vary considerably.		60	SF	\$25.00	\$1,000.0
a Install an exhaust fan per restroom 2 EA \$1,800.00 \$3,600 13 BREAKROOM PARTITION a Install thin 3-1/2" wide partition with 2-1/2" studs and 1/2" gyp. bd. Finish, etc. This Probable Construction Cost Estimate is based on the specific existing conditions for the project. Costs are based to March 2025 pricing, and should be adjusted to account for market conditions and inflation as the project moves revard. Due to factors such as tariffs on imported items and general labor shortages construction costs may vary considerably.					
13 BREAKROOM PARTITION a Install thin 3-1/2" wide partition with 2-1/2" studs and 1/2" gyp. bd. Finish, etc. 70 SF \$45.00 \$3,150 seneral Notes & Disclaimers: Estimate does not include asbestos abatement for floor/eciling removal. Estimate does not include asbestos abatement for floor/eciling removal. March 2025 pricing, and should be adjusted to account for market conditions and inflation as the project moves roward. Due to factors such as tariffs on imported items and general labor shortages construction costs may vary considerably.	12 EXHAUST FAN REPLACEMENT				
a Install thin 3-1/2" wide partition with 2-1/2" studs and 1/2" gyp. bd. Finish, etc. 70 SF \$45.00 \$3,150 students and 1/2" students and 1/2" gyp. bd. Finish, etc. 8172,123 students and 1/2" students and 1/2" gyp. bd. Finish, etc. 823,150 students and 1/2" wide partition with 2-1/2" students and 1/2" gyp. bd. Finish, etc. 823,150 students and 1/2" gyp. bd. Finish, etc. 83,150 students and 1/2" gyp. bd. Finish, etc. 83,150 students and 1/2" gyp. bd. Finish, etc. 845.00 \$3,150 students and 1/2" gyp. bd. Finish, etc. 845.00 \$3,150 students and 1/2" gyp. bd. Finish, etc. 845.00 \$3,150 students and 1/2" gyp. bd. Finish, etc. 845.00 \$3,150 students and 1/2" gyp. bd. Finish, etc. 845.00 \$1,100 students and 1/2" gyp. bd. Finish and 1/2" g	a Install an exhaust fan per restroom	2	EA	\$1,800.00	\$3,600.
a Install thin 3-1/2" wide partition with 2-1/2" studs and 1/2" gyp. bd. Finish, etc. 70 SF \$45.00 \$3,150 students and 1/2" students and 1/2" gyp. bd. Finish, etc. 8172,123 students and 1/2" students and 1/2" gyp. bd. Finish, etc. 823,150 students and 1/2" wide partition with 2-1/2" students and 1/2" gyp. bd. Finish, etc. 823,150 students and 1/2" gyp. bd. Finish, etc. 83,150 students and 1/2" gyp. bd. Finish, etc. 83,150 students and 1/2" gyp. bd. Finish, etc. 845.00 \$3,150 students and 1/2" gyp. bd. Finish, etc. 845.00 \$3,150 students and 1/2" gyp. bd. Finish, etc. 845.00 \$3,150 students and 1/2" gyp. bd. Finish, etc. 845.00 \$3,150 students and 1/2" gyp. bd. Finish, etc. 845.00 \$1,100 students and 1/2" gyp. bd. Finish and 1/2" g	12 PREAKROOM BARTITION				
eneral Notes & Disclaimers: Estimate does not include asbestos abatement for floor/ceiling removal. This Probable Construction Cost Estimate is based on the specific existing conditions for the project. Costs are based it March 2025 pricing, and should be adjusted to account for market conditions and inflation as the project moves revard. Due to factors such as tariffs on imported items and general labor shortages construction costs may vary considerably.	Transition 2 1/20 and demonstrate and 2 1/20 and a red 1/20 and by Timich and	70	S.E.	945.00	\$3 150 (
Estimate does not include asbestos abatement for floor/eciling removal. This Probable Construction Cost Estimate is based on the specific existing conditions for the project. Costs are based and Arch 2025 pricing, and should be adjusted to account for market conditions and inflation as the project moves reward. Due to factors such as tariffs on imported items and general labor shortages construction costs may vary considerably.	a mount time is the partition with a real state and its gyp, out i mising ever	70	SF	\$43.00	\$3,130.
Estimate does not include assessors abatement for floor/ceiling removal. This Probable Construction Cost Estimate is based on the specific existing conditions for the project. Costs are based at March 2025 pricing, and should be adjusted to account for market conditions and inflation as the project moves reward. Due to factors such as tariffs on imported items and general labor shortages construction costs may vary considerably.	eneral Notes & Disclaimers:			Subtotal	\$172,123.
n March 2025 pricing, and should be adjusted to account for market conditions and inflation as the project moves revard. Due to factors such as tariffs on imported items and general labor shortages construction costs may vary considerably.					
Due to factors such as tariffs on imported items and general labor shortages construction costs may vary considerably.	n March 2025 pricing, and should be adjusted to account for market conditions and inflation as the project moves	Overhe	ad and	1 Profit (15%)	\$25,818.
	reverd. Due to factors such as tariffs on imported items and general labor shortages construction costs may vary considerably.				
	Design Fees and FFE costs are not included in the above costs.				